



Letter of Claims Request for direct settlement.

We are submitting a claim on behalf of our customer Hon See Lim Rosaline
NRIC S81704456 insured of vehicle SUZ GAT52 against
your insured vehicle number SFU 4082X ()
On the accident dated on 20/12/19 (ddmmyyyy) along P1E after
Steven Road exit

Dated this _____ (day) of _____ (month) 2019 .

Charmaine Kong
Volkswagen Group Singapore
Accident Claims Dept.
charmaine.kong@vw.com.sg
DID : 63057176/ 63057299
HP: 92361399

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Ms.
ROSALINE HON
SZE LIN
23 JALAN RAJA UDANG
#27-12
Singapore 329216

Document no.
Document date 29-07-2019
Customer no. 5211013960
Customer GST-ID
Dealer 39999
Job order number 2019001489/ 1
Job order date 29-07-2019
Service Advisor PEARLYN CHEONG

License plate	Model code	First registration	VIN	Model	Mileage
SLZ6875Z	BQ12AZ	15-05-2018	WVWZZZAUZJW225250	Golf Trendline 1.0 I TSI 81kW DSG	10

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
5G6807417BQGRU	Cover For Bumper Primed	1	pcs.	1,080.14	#1	1,080.14	1,155.75
5G6807568Q 9B9	Rear Diffusor Satin Black	1	pcs.	254.86	#1	254.86	272.70
5G0807305D	Bumper	1	pcs.	572.31	#1	572.31	612.37
	(bumper reinforcement)						
5G6807863C	Attachment Strip	1	pcs.	59.89	#1	59.89	64.08
5G6807393	Guide Piece	1	pcs.	34.51	#1	34.51	36.93
	(bumper bracket LHS)						
5G6807394	Guide Piece	1	pcs.	34.51	#1	34.51	36.93
	(bumper bracket RHS)						
5G6807393A	Guide Piece	1	pcs.	34.51	#1	34.51	36.93
	(Bumper retainer LHS)						
5G6807394A	Guide Piece	1	pcs.	34.51	#1	34.51	36.93
	(bumper retainer RHS)						
5G6827025Q	Rear Trunk Lid	1	pcs.	1,853.05	#1	1,853.05	1,982.76
5G0853687 2ZZ	Inscription Bright Chrome (Golf)	1	pcs.	66.63	#1	66.63	71.29
5G0853675AR2ZZ	Inscription Bright Chrome (TSI)	1	pcs.	58.66	#1	58.66	62.77
D 004660M2	2k-Glass Glue Application	1	pcs.	123.02	#1	123.02	131.63
D 00920002	Primer	1	pcs.	25.92	#1	25.92	27.73
D 181802M1	Activator For Precoated W	1	pcs.	23.63	#1	23.63	25.28
D 002000A2	Adhesive Remover	1	pcs.	115.74	#1	115.74	123.84
D 00950025	Applicator	2	pcs.	9.48	#1	18.96	20.29
5G0945095Q	Led Tail Light	1	pcs.	569.67	#1	569.67	609.55
5G0945096Q	Led Tail Light	1	pcs.	569.67	#1	569.67	609.55
5G0945093AH	Led Tail Light	1	pcs.	545.12	#1	545.12	583.28
	(INNER LEFT)						
5G0945094AH	Led Tail Light With Rear (RHS INNER)	1	pcs.	545.12	#1	545.12	583.28
1K8943021	License Plate Light	2	pcs.	37.19	#1	74.38	79.59
	LABOUR	5	pcs.	840.00	#1	4,200.00	4,494.00
	RE+REINSTALLED REAR WSCREEN	1	pcs.	840.00	#1	840.00	898.80
	Spray Painting	5	pcs.	800.00	#1	4,000.00	4,280.00
	NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	Tomo Holding Limited	1	pcs.	400.00	#1	400.00	428.00

Quotation valid till 05-08-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	16,214.81	7%	1,188.24	16,974.81	18,163.05
Total	760.00	16,214.81		1,188.24	16,974.81	18,163.05

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page	2/2
Document no.	
Document date	29-07-2019
Customer no.	5211013960
Customer GST-ID	
Dealer	39999
Job order number	2019001489/ 1
Job order date	29-07-2019
Service Advisor	PEARLYN CHEONG

License plate	Model code	First registration	VIN	Model	Mileage
SLZ6875Z	BQ12AZ	15-05-2018	WWWZZZAUZJW225250	Golf Trendline 1.0 I TSI 81kW DSG	10

Customer

Service Advisor

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----