

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020061-X



## Final Report

|                                          |          |    |   |          |
|------------------------------------------|----------|----|---|----------|
| # EXPANDING RIVET                        | 2.50     | 6  | 0 | 15.00    |
| BLIND RIVET NUT M6                       | 2.55     | 5  | 0 | 12.75    |
| SILENCER CLAMPING BUSH                   | 54.30    | 1  | 0 | 54.30    |
| REAR SILENCER                            | 1,465.05 | 1  | 0 | 1,465.05 |
| TAILPIPE TRIM BLACK CHROME               | 110.55   | 1  | 0 | 110.55   |
| BOOTLID                                  | 1,230.50 | 1  | 0 | 1,230.50 |
| INTERIOR TAIL TRIM                       | 315.65   | 1  | 0 | 315.65   |
| TAIL PANEL                               | 401.75   | 1  | 0 | 401.75   |
| RR BUMPER CARRIER                        | 493.85   | 1  | 0 | 493.85   |
| RR BUMPER LH CORNER MOUNTING             | 141.90   | 1  | 0 | 141.90   |
| RR BUMPER RH CORNER MOUNTING             | 141.90   | 1  | 0 | 141.90   |
| MOUNTING SMART OPENER (M)                | 45.30    | 1  | 0 | 45.30    |
| REAR BUMPER PANEL PRIMED (M/PDC)         | 1,185.70 | 1  | 0 | 1,185.70 |
| REAR BUMPER TRIM PANEL BOTTOM (M/PD)     | 297.80   | 1  | 0 | 297.80 ? |
| EMBLEM GROMMET                           | 0.80     | 2  | 0 | 1.60     |
| BMW PLAQUE WITH ADHESIVE FILM            | 71.25    | 1  | 0 | 71.25    |
| LETTERING S DRIVE 18I                    | 96.15    | 1  | 0 | 96.15    |
| LETTERING X1                             | 64.10    | 1  | 0 | 64.10    |
| BUMP STOP                                | 3.50     | 6  | 0 | 21.00    |
| # THERMAL PROTECTION LUGGAGE COMP. FL    | 48.90    | 1  | 0 | 48.90    |
| # LOADING SILL COVER                     | 143.95   | 1  | 0 | 143.95   |
| # STORAGE TROUG. LUGGAGE TRUNK FLOOR     | 224.20   | 1  | 0 | 224.20   |
| # REAR BUMPER HEAT INSULATION            | 69.55    | 1  | 0 | 69.55    |
| # (DG/SL) SOUND DEADENER 1160X700MM      | 105.55   | 1  | 0 | 105.55   |
| BOOTLID SEALING                          | 165.55   | 1  | 0 | 165.55   |
| # BLIND RIVET AVIBVLB                    | 0.55     | 10 | 0 | 5.50     |
| # BLIND RIVET AVIBVLB                    | 0.55     | 30 | 0 | 16.50    |
| # SCREW (SF PLUS M5X15)                  | 0.55     | 5  | 0 | 2.75     |
| # PUNCH RIVET N4                         | 0.55     | 20 | 0 | 11.00    |
| # (DG) CLEANER R1 (100ML)                | 26.15    | 1  | 0 | 26.15    |
| # (DG) CLEANER R1 (100ML)                | 26.15    | 1  | 0 | 26.15    |
| # (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) | 131.55   | 2  | 0 | 263.10   |
| # (DG/SL) GLASS PRIMER 30ML (VP206)      | 27.85    | 1  | 0 | 27.85    |
| # (S/L) SEAM SEAL 300ML                  | 33.80    | 1  | 0 | 33.80    |
| #                                        |          |    |   |          |
| #                                        |          |    |   |          |

### # SUPPLEMENTARY ITEMS

|                   |        |         |
|-------------------|--------|---------|
| OD                | DATE   | TIME    |
| FAX TO            | laufly | 30/8/19 |
| FAX NO            | 445    | 8       |
| FAX TO            |        |         |
| FAX NO            |        |         |
| FAX TO            |        |         |
| FAX NO            |        |         |
| CONFIRMED         |        |         |
| DATE              |        |         |
| PLEASE CONFIRM BY |        |         |

|                                 |           |
|---------------------------------|-----------|
| Total Labour :                  | 9,744.00  |
| Total Parts :                   | 7,373.60  |
| Total Repair Costs less Excess: | 17,117.60 |
| GST @7%:                        | 1,198.23  |
| Grand Total :                   | 18,315.83 |

LOSS OF USE = \$100 X 10 DAYS

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 52151**  
Date Estimated : **29/07/2019**  
Prepared By : **Joseph Yaguel**

### - ESTIMATE REPAIR FOR -

**Wenny Tan**  
**Blk 564 Hougang Street 51**  
**#13-430**

**Singapore 530564**

### - ACCOUNT - 121

**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

| REGN. NO.       | CHASSIS NO.    | REGN. DATE        | MODEL               | MILEAGE  |
|-----------------|----------------|-------------------|---------------------|----------|
| <b>SKE1819S</b> | <b>EG22916</b> | <b>31/08/2018</b> | <b>X1 sDrive18i</b> | <b>0</b> |

  

| DESCRIPTION                                                                                                                                                                                                                                                                      | ACCOUNT:<br>ORIGINAL PRICE | DISC. % | NETT     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|---------|----------|
| To replace rear bumper and attachments, rear boot lid and attachments, tail end panel and interior tail trim etc including to pull and straghten trunk floor and knock out dentd area caused by the accident. To remove and install boy part in order to carry out painting job. | 3,400.00                   | 0       | 3,400.00 |
| To respray rear bumper, rear boot li , tail end panel and trunk floor panel etc.                                                                                                                                                                                                 | 3,079.00                   | 0       | 3,079.00 |
| To tow accident vehicle to PML workshop.                                                                                                                                                                                                                                         | 195.00                     | 0       | 195.00   |
| To remove and install rear windscreen glass to facilitate the repair job.                                                                                                                                                                                                        | 487.00                     | 0       | 487.00   |
| To conduct water leak tests.                                                                                                                                                                                                                                                     | 75.00                      | 0       | 75.00    |
| To replace rear silencer and clamping bush including alignment system and conduct checks for leak.                                                                                                                                                                               | 451.00                     | 0       | 451.00   |
| To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.                                                                                                                                                                                | 742.00                     | 0       | 742.00   |
| To check electrical wiring systems and lightings at the rear section for proper function.                                                                                                                                                                                        | 150.00                     | 0       | 150.00   |
| To carry out body cavity preservation.<br>(For cut panel).                                                                                                                                                                                                                       | 451.00                     | 0       | 451.00   |
| Sundries                                                                                                                                                                                                                                                                         | 150.00                     | 0       | 150.00   |
| # To mount accident vehicle on speed bench to facilitate pulling and re-alignment of body/chassis according to BMW specification.                                                                                                                                                | 564.00                     | 0       | 564.00   |

| DESCRIPTION             | UNIT PRICE | QTY | DISC. % | NETT  |
|-------------------------|------------|-----|---------|-------|
| #                       |            |     |         |       |
| # EXPANDING RIVET WHITE | 1.85       | 19  | 0       | 35.15 |
| # EXPANDING RIVET WHITE | 1.85       | 1   | 0       | 1.85  |

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## Supplementary

Estimate No. : **b1 52151**  
Date Estimated : **29/07/2019**  
Prepared By : **Joseph Yaguel**

**- ESTIMATE REPAIR FOR -**  
**Wenny Tan**  
**Blk 564 Hougang Street 51**  
**#13-430**

**Singapore 530564**

**- ACCOUNT - 121**  
**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

|                 |                |                   |                     |          |
|-----------------|----------------|-------------------|---------------------|----------|
| REGN. NO.       | CHASSIS NO.    | REGN. DATE        | MODEL               | MILEAGE  |
| <b>SKE1819S</b> | <b>EG22916</b> | <b>31/08/2018</b> | <b>X1 sDrive18i</b> | <b>0</b> |

| DESCRIPTION                                                                                                                       | ACCOUNT:<br>ORIGINAL PRICE | DISC. % | NETT   |
|-----------------------------------------------------------------------------------------------------------------------------------|----------------------------|---------|--------|
| # To mount accident vehicle on speed bench to facilitate pulling and re-alignment of body/chassis according to BMW specification. | 564.00                     | 0       | 564.00 |

| DESCRIPTION                              | UNIT PRICE | QTY | DISC. % | NETT             |
|------------------------------------------|------------|-----|---------|------------------|
| #                                        |            |     |         |                  |
| # EXPANDING RIVET WHITE                  | 1.85       | 19  | 0       | 35.15 <i>ne</i>  |
| # EXPANDING RIVET WHITE                  | 1.85       | 1   | 0       | 1.85 <i>ne</i>   |
| # EXPANDING RIVET                        | 2.50       | 6   | 0       | 15.00 <i>ne</i>  |
| # THERMAL PROTECTION LUGGAGE COMP. FL    | 48.90      | 1   | 0       | 48.90 <i>di</i>  |
| # LOADING SILL COVER                     | 143.95     | 1   | 0       | 143.95 <i>di</i> |
| # STORAGE TROUG. LUGGAGE TRUNK FLOOR     | 224.20     | 1   | 0       | 224.20 <i>di</i> |
| # REAR BUMPER HEAT INSULATION            | 69.55      | 1   | 0       | 69.55 <i>bt</i>  |
| # (DG/SL) SOUND DEADENER 1160X700MM      | 105.55     | 1   | 0       | 105.55 <i>di</i> |
| # BLIND RIVET AVIBVLB                    | 0.55       | 10  | 0       | 5.50 <i>ne</i>   |
| # BLIND RIVET AVIBVLB                    | 0.55       | 30  | 0       | 16.50 <i>ne</i>  |
| # SCREW (SF PLUS M5X15)                  | 0.55       | 5   | 0       | 2.75 <i>ne</i>   |
| # PUNCH RIVET N4                         | 0.55       | 20  | 0       | 11.00 <i>ne</i>  |
| # (DG) CLEANER R1 (100ML)                | 26.15      | 1   | 0       | 26.15 <i>ne</i>  |
| # (DG) CLEANER R1 (100ML)                | 26.15      | 1   | 0       | 26.15 <i>ne</i>  |
| # (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) | 131.55     | 2   | 0       | 263.10 <i>ne</i> |
| # (DG/SL) GLASS PRIMER 30ML (VP206)      | 27.85      | 1   | 0       | 27.85 <i>ne</i>  |
| # (S/L) SEAM SEAL 300ML                  | 33.80      | 1   | 0       | 33.80 <i>ne</i>  |
| #                                        |            |     |         |                  |
| #                                        |            |     |         |                  |

### # SUPPLEMENTARY ITEMS

|                                 |          |
|---------------------------------|----------|
| Total Labour :                  | 564.00   |
| Total Parts :                   | 1,056.95 |
| Total Repair Costs less Excess: | 1,620.95 |

To: Taufikh (LKKAUTO)

Subject: DIRECT SETTLEMENT FINAL REPORT - SKW1819A

Dear Taufikh

For your perusal :

|        |            |
|--------|------------|
| Labour | \$ 9744.00 |
| Parts  | \$ 7373.60 |
| Total  | \$17117.60 |

Owner is claiming      LOSS OF USE = \$100 X 10 DAYS.

Please reply me directly.

Best Regards

Sharon Heng  
PML - Body and Paint  
DID : 63190123  
Fax : 64743229

-----Original Message-----

From: service.pml@simedarby.com.sg [mailto:service.pml@simedarby.com.sg]

Sent: Friday, 30 August, 2019 6:15 PM

To: Sharon Heng L K

Subject: Message from KM\_C458