

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0916/2019/TG
Date : 29-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

Your Insured Vehicle : SKN 1813 K

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Yee Kok Hai
Address : Blk 340 Bukit Batok Street 34
#12-32
Singapore 650340
Telephone : HP +65 90280140
Type of Claim : Third Party Claim
Policy No. :
Vehicle No : **SFQ 9212 K**
Model Code : A4 1.8 TFSI MU S- Line
Model / Year : Jan-13
Engine No : CJE 027629
Chassis No : WAUZZZ8K6DA1026343
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Jul-19
Place of Accident : PIE Towards Changi Before BKE Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0916/2019/TG
Date : 29-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

Your Insured Vehicle : SKN 1813 K

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Yee Kok Hai
Address : Blk 340 Bukit Batok Street 34
#12-32
Singapore 650340
Telephone : HP +65 90280140
Type of Claim : Third Party Claim
Policy No. :
Vehicle No : **SFQ 9212 K**
Model Code : A4 1.8 TFSI MU S- Line
Model / Year : Jan-13
Engine No : CJE 027629
Chassis No : WAUZZZ8K6DA1026343
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Jul-19
Place of Accident : PIE Towards Changi Before BKE Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFQ 9212 K - FRONT

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$360.00 ✓
2	To remove and renew aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system.	S/N \$ 1,200.00 ✓
3	To remove and renew front bumper, both front fenders, bonnet and both headlights. Remove and renew lock carrier and align to position. Reinstall all parts removed. ✓ ✓ ✓	\$ 6,300.00 1500 (without Lock carrier) 2750 (with Lock carrier)
4	To respray front bumper, both front fenders and bonnet. ✓	\$ 3,800.00 2200
FRONT-TOTAL LABOUR CHARGES		: <u><u>\$11,660.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFQ 9212 K - FRONT

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Distorted</i>	\$ 2,100.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 234.00	+
3	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>new</i>	\$ 207.00	+
4	FRONT BUMPER GRILLE-LOWER CENTRE <i>new</i>	\$ 123.00	+
5	FRONT BUMPER CLOSING ELEMENT-UPPER CENTRE <i>new</i>	\$ 177.00	+
6	FRONT BUMPER SUPPORT ELEMENT-UPPER <i>new</i>	\$ 54.00	+
7	RADIATOR GRILLE <i>crushed</i>	\$ 1,005.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE-LH <i>new</i>	\$ 123.00	+
9	FRONT BUMPER VENT GRILLE-RH <i>cut</i>	\$ 123.00	✓
10	FRONT WHEEL SPOILER-LH/RH <i>new</i>	2 \$ 90.00	+
11	FOAM FILLER PIECE <i>tear</i>	\$ 113.00	✓
12	FRONT REINFORCEMENT BEAM <i>Bent</i>	\$ 802.00	✓
13	FRONT BUMPER SUPPORT <i>2nd</i>	2 \$ 23.00	✓
14	FRONT BUMPER COVER <i>crushed</i>	\$ 116.00	✓
15	FRONT BUMPER GUIDE SECTION-LH/RH <i>new</i>	2 \$ 66.00	+
16	FRONT BUMPER BRACKET-LH/RH <i>new</i>	2 \$ 414.00	+
17	SIGN ' CAUTION ' <i>2 new</i>	\$ 13.00	✓
18	AIR CONDITIONER STICKER	\$ 22.00	✓
19	SHOCK ABOSORBER MOUNTING-LH/RH ?	2 \$ 156.00	?
20	SIGNAL HORN-LH/RH ?	2 \$ 368.00	?
SUB FRONT -TOTAL SPARE PARTS CHARGES		\$ 6,329.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFQ 9212 K - FRONT

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
21	SPRING SHACKLE FOR SIGNAL HORN-LH/RH <i>new</i>	2	\$ 46.00	+
22	FRONT FENDER-LH/RH <i>Repair</i>	2	\$ 1,808.00	+
23	FRONT FENDER ATTACHMENT PARTS <i>new</i>	2	\$ 103.00	+
24	FRONT FENDER BRACKET-LH/RH	2	\$ 96.00	+
25	BRACKET FOR DEFORMATION-LH/RH	2	\$ 90.00	+
26	FRONT FENDER BRACE-LH /RH LOWER	2	\$ 214.00	+
27	FRONT WHEEL HOUSING LINER-LH/RH <i>new</i>	2	\$ 446.00	+
28	FRONT WHEEL HOSUING LINER-LH/RH <i>new</i>	2	\$ 81.00	+
29	FRONT STONE CHIP GUARD <i>new</i>	2	\$ 134.00	✓
30	ADHESIVE TAPE		\$ 50.00	?
31	BONNET <i>Dented</i>		\$ 2,549.00	✓
32	BONNET PROTECTIVE FILM <i>new</i>		\$ 42.00	✓
33	BONNET ATTACHMENT PARTS		\$ 152.00	?
34	BONNET LID HINGE-LH/RH <i>new</i>	2	\$ 136.00	+
35	BONNET CATCH HOOK <i>new</i>		\$ 127.00	+
36	BONNET GAS FILLED STRUT <i>new</i>		\$ 109.00	+
37	BONNET EDGE PROTECTION <i>new</i>		\$ 25.00	✓
38	BONNET LID LOCK WITH MICRO SWITCH <i>new</i>		\$ 196.00	+
39	BONNET CABLE HOLDER <i>new</i>		\$ 7.00	+
40	BONNET LID LOCK CABLE <i>new</i>		\$ 44.00	+
SUB-FRONT -TOTAL SPARE PARTS CHARGES			\$ 6,455.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFQ 9212 K - FRONT

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	BONNET LOCK COVER <i>new</i>	\$ 21.00	+
42	HEADLIGHT MOUNTING -LH/RH ?	2 \$ 214.00	?
43	HEADLIGHT BRACKET -LH/RH ?	2 \$ 192.00	?
44	HEADLIGHT -LH/RH <i>cracked</i>	2 \$ 4,304.00	✓
45	GAS DISCHARGE LAMP FOR HEADLIGHT <i>new</i>	2 \$ 796.00	+
46	CONTROL UNIT FOR HEADLIGHT ?	2 \$ 2,102.00	+
47	POWER MODULE FOR HEADLIGHT <i>new</i>	2 \$ 1,039.00	+
48	HOSE FOR HEADLIGHT-LH/RH	2 \$ 64.00	+
49	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM ?	2 \$ 384.00	?
50	HOSE ON ROLLERS 5 M FOR LIFT CYLINDER <i>new</i>	\$ 170.00	+
51	T PIECE FOR LIFT CYLINDER <i>new</i>	\$ 14.00	+
52	CONNECTION PIECE FOR LIFT CYLINDER <i>new</i>	\$ 13.00	+
53	CABLE TIE WITH TERMINAL SOCKET <i>new</i>	\$ 3.00	+
54	WASH WATER RESERVOIR <i>new</i>	\$ 200.00	+
55	LOCK CARRIER WITH MOUNTING FOR RADIATOR ?	\$ 928.00	?
56	A/C CONDENSER <i>Dented</i>	\$ 677.00	✓
57	A/C CONDENSER VALVE <i>new</i>	\$ 48.00	+
58	A/C PRESSURE SENDER <i>new</i>	\$ 175.00	+
59	COOLANT RADIATOR WITH OIL COOLER <i>Dented</i>	\$ 1,246.00	✓
60	READY MIX- COOLANT <i>new</i>	4 \$ 84.00	✓
SUB-FRONT -TOTAL SPARE PARTS CHARGES		\$ 12,674.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFQ 9212 K - FRONT

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
61	RADIATOR <i>Dented</i>	\$ 513.00	✓
61	TWIN FAN RING FOR RADIATOR ?	\$ 237.00	?
62	RADIATOR FAN -RH ?	\$ 673.00	?
63	RADIATOR FAN -LH ?	\$ 779.00	?
64	CONTROL UNIT FOR RADIATOR <i>not use</i>	\$ 778.00	✗
65	AIR GUIDE RADIATOR-LH/RH ?	2 \$ 48.00	?
66	RADIATOR SEALING STRIP -LOWER ?	\$ 21.00	?
67	AIR INTAKE MANIFOLD-FRONT <i>not use</i>	\$ 88.00	✗
68	AIR INTAKE BELLOWS RESONATOR <i>use</i>	\$ 98.00	✓
69	AIR FILTER ?	\$ 279.00	+
70	AIR INTAKE ADAPTER <i>use</i>	\$ 11.00	+
71	AIT INTAKE MANIFOLD	\$ 117.00	+
72	HALOGEN FOG LAMP-LH/RH <i>not use</i>	2 \$ 484.00	✗
FRONT -TOTAL SPARE PARTS CHARGES		: \$ 29,584.00	
FRONT -TOTAL LABOUR CHARGES		: \$ 11,660.00	
FRONT GRAND TOTAL		: \$ 41,244.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFQ 9212 K - REAR

S/n	Nature of Jobs		Estimated Charges	
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N	\$280.00	✓
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$	280.00	✓
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$	480.00	?
4	To dismantle and renew rear bumper and rear lid. Cut out and reweld end panelling. Re-organise rear crash management components. Reinstall all parts removed.	\$	4,200.00	1000. ✓
5	To respray rear bumper, rear lid and end panelling. To carry out joint sealer works and stone chip treatment.	\$	3,000.00	1650. ✓
6	To remove and renew lhs rear exhaust silencer. To align to position.	S/N \$	480.00	X
7	To carry out diagnostic check.	S/N \$	384.00	✓
REAR - TOTAL LABOUR CHARGES		:	<u><u>\$9,104.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFQ 9212 K - REAR

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Rebanded</i>	\$ 2,100.00	✓
2	REAR BUMPER STICKY PAD ?	4 \$ 21.00	?
3	REAR BUMPER FIXING PARTS <i>new</i>	\$ 206.00	+
4	REAR BUMPER SPOILER <i>cut</i>	\$ 243.00	✓
5	REAR BUMPER CARRIER ?	\$ 587.00	?
6	REAR BUMPER SECURING STRIP <i>new</i>	\$ 12.00	+
7	REAR BUMPER HOLDER BRACKET-LH/RH <i>3</i>	2 \$ 406.00	+
8	REAR BUMPER GUIDE SECTION-LH/RH UPPER <i>2</i>	2 \$ 41.00	+
9	REAR BUMPER GUIDE SECTION-LH <i>new</i>	\$ 40.00	+
10	REAR BUMPER GUIDE SECTION-RH <i>new</i>	\$ 41.00	+
11	REAR SENSOR ?	4 \$ 838.00	?
12	REAR LID <i>Dented</i>	\$ 2,554.00	✓
13	REAR LID ATTACHMENT PART <i>new</i>	\$ 67.00	✓
14	REAR LID GASKET FLAP <i>new</i>	\$ 185.00	+
15	REAR LID LOCK-INNER ?	\$ 199.00	+
16	REAR LID LOCK COVER <i>new</i>	\$ 18.00	+
17	REAR LID LOCK STRIKER	\$ 45.00	+
18	REAR LID PUSH BUTTON FOR ELECTRIC <i>new</i>	\$ 167.00	+
19	PACKING ADHESIVE <i>new</i>	\$ 18.00	✓
20	GUARD PLATE-INNER <i>new</i>	\$ 56.00	+
SUB- REAR -TOTAL SPARE PARTS CHARGES		\$ 7,844.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFQ 9212 K - REAR

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	REAR LID INCRPTION ' A4 '	\$ 87.00	✓
22	REAR LID AUDI EMBLEM	\$ 113.00	✓
23	REAR LID INSCRIPTION ' 1.8 T '	\$ 87.00	✓
24	REAR CROSS PANEL -OUTER	\$ 286.00	✗ ?
25	REAR CROSS PANEL-LOWER	\$ 794.00	✗ ?
26	REAR BUMPER REINFORCEMENT BEAM -NNER	\$ 484.00	✗ ?
27	REAR CROSS PANEL TRIM	\$ 167.00	✗
28	REAR SILENCER	\$ 1,019.00	✗
29	REAR SILENCER DUAL CLIP	\$ 54.00	✗
30	REAR SILENCER CLAMP	\$ 70.00	✗
31	REAR SILENCER BRACKET-LH	\$ 52.00	✗
32	REAR SILENCER BRACKET-RH	\$ 29.00	✗
33	ACYLIC SEALANT	S/N \$ 180.00	✗ ?
34	CAVITY WAX	S/N \$ 140.00	✗ ?
35	STONE CHIP	S/N \$ 180.00	✗ ?
36	FRONT NO. PLATE	S/N \$ 60.00	✓
37	REAR NO. PLATE	S/N \$ 60.00	✗
38	SUNDRIES	\$ 800.00	?
REAR -TOTAL SPARE PARTS CHARGES		: \$ 12,506.00	
REAR -TOTAL LABOUR CHARGES		: \$ 9,104.00	
REAR - GRAND TOTAL		: \$ 21,610.00	
GRAND TOTAL (FRONT + REAR)		: \$ 62,854.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 30/07/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 11 Days (without lock carrier)
14 Days (with lock carrier)

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant