

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFQ 9212 K - FRONT

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Distorted</i>	\$ 2,100.00 ✓	1,680.00
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 234.00 +	
3	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>new</i>	\$ 207.00 +	
4	FRONT BUMPER GRILLE-LOWER CENTRE <i>new</i>	\$ 123.00 +	
5	FRONT BUMPER CLOSING ELEMENT-UPPER CENTRE <i>Distorted</i>	\$ 177.00 ✓	141.20
6	FRONT BUMPER SUPPORT ELEMENT-UPPER <i>new</i>	\$ 54.00 +	
7	RADIATOR GRILLE <i>Crushed</i>	\$ 1,005.00 ✓	804.00
8	FRONT BUMPER AIR GUIDE GRILLE-LH <i>new</i>	\$ 123.00 +	
9	FRONT BUMPER VENT GRILLE-RH <i>new</i>	\$ 123.00 ✓	98.00
10	FRONT WHEEL SPOILER-LH/RH <i>new</i>	2 \$ 90.00 +	
11	FOAM FILLER PIECE <i>torn</i>	\$ 113.00 ✓	90.40
12	FRONT REINFORCEMENT BEAM <i>Bent</i>	\$ 802.00 ✓	641.20
13	FRONT BUMPER SUPPORT <i>2nd</i>	2 \$ 23.00 ✓	17.92
14	FRONT BUMPER COVER <i>Crushed</i>	\$ 116.00 ✓	92.40
15	FRONT BUMPER GUIDE SECTION-LH/RH <i>new</i>	2 \$ 66.00 ✓	52.16
16	FRONT BUMPER BRACKET-LH/RH <i>new</i>	2 \$ 414.00 +	
17	SIGN ' CAUTION ' <i>2 new</i>	\$ 13.00 ✓	9.76
18	AIR CONDITIONER STICKER	\$ 22.00 ✓	16.96
19	SHOCK ABOSORBER MOUNTING-LH/RH <i>2nd new</i>	2 \$ 156.00 ✓	
20	SIGNAL HORN-LH/RH <i>2nd new</i>	2 \$ 368.00 ✓	
SUB FRONT -TOTAL SPARE PARTS CHARGES		\$ 6,329.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFQ 9212 K - FRONT

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
21	SPRING SHACKLE FOR SIGNAL HORN-LH/RH <i>new</i>	2	\$ 46.00 +	
22	FRONT FENDER-LH/RH <i>Repair</i>	2	\$ 1,808.00 +	
23	FRONT FENDER ATTACHMENT PARTS <i>new</i>	2	\$ 103.00 +	
24	FRONT FENDER BRACKET-LH/RH <i>2</i>	2	\$ 96.00 +	
25	BRACKET FOR DEFORMATION-LH/RH	2	\$ 90.00 +	
26	FRONT FENDER BRACE-LH /RH LOWER	2	\$ 214.00 +	
27	FRONT WHEEL HOUSING LINER-LH/RH <i>new</i>	2	\$ 446.00 +	
28	FRONT WHEEL HOSUING LINER-LH/RH <i>new</i>	2	\$ 81.00 +	
29	FRONT STONE CHIP GUARD <i>new</i>	2	\$ 134.00 ✓	105.92
30	ADHESIVE TAPE <i>new</i>		\$ 50.00 ✗	
31	BONNET <i>Dented</i>		\$ 2,549.00 ✓	2,039.20
32	BONNET PROTECTIVE FILM <i>new</i>		\$ 42.00 ✓	33.04
33	BONNET ATTACHMENT PARTS <i>new</i>		\$ 152.00 ✗	
34	BONNET LID HINGE-LH/RH <i>new</i>	2	\$ 136.00 +	
35	BONNET CATCH HOOK <i>new</i>		\$ 127.00 +	
36	BONNET GAS FILLED STRUT <i>new</i>		\$ 109.00 +	
37	BONNET EDGE PROTECTION <i>new</i>		\$ 25.00 ✓	19.92
38	BONNET LID LOCK WITH MICRO SWITCH <i>new</i>		\$ 196.00 +	
39	BONNET CABLE HOLDER <i>new</i>		\$ 7.00 +	
40	BONNET LID LOCK CABLE <i>new</i>		\$ 44.00 +	
SUB-FRONT -TOTAL SPARE PARTS CHARGES			\$ 6,455.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFQ 9212 K - FRONT

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	BONNET LOCK COVER <i>new</i>	\$ 21.00 +	
42	HEADLIGHT MOUNTING -LH/RH <i>new</i>	2 \$ 214.00 +	
43	HEADLIGHT BRACKET -LH/RH <i>new</i>	2 \$ 192.00 +	
44	HEADLIGHT -LH/RH <i>cracked</i>	2 \$ 4,304.00 ✓	1,721.60
45	GAS DISCHARGE LAMP FOR HEADLIGHT <i>new</i>	2 \$ 796.00 +	
46	CONTROL UNINT FOR HEADLIGHT	2 \$ 2,102.00 +	
47	POWER MODULE FOR HEADLIGHT <i>new</i>	2 \$ 1,039.00 +	
48	HOSE FOR HEADLIGHT-LH/RH	2 \$ 64.00 +	
49	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM <i>new</i>	2 \$ 384.00 +	
50	HOSE ON ROLLERS 5 M FOR LIFT CYLINDER <i>new</i>	\$ 170.00 +	
51	T PIECE FOR LIFT CYLINDER <i>new</i>	\$ 14.00 +	
52	CONNECTION PIECE FOR LIFT CYLINDER <i>new</i>	\$ 13.00 +	
53	CABLE TIE WITH TERMINAL SOCKET <i>new</i>	\$ 3.00 +	
54	WASH WATER RESERVOIR <i>new</i>	\$ 200.00 +	
55	LOCK CARRIER WITH MOUNTING FOR RADIATOR <i>cracked</i>	\$ 928.00 ✓	742.00
56	A/C CONDENSER <i>Dented</i>	\$ 677.00 ✓	541.60
57	A/C CONDENSER VALVE <i>new</i>	\$ 48.00 +	
58	A/C PRESSURE SENDER <i>new</i>	\$ 175.00 +	
59	COOLANT RADIATOR WITH OIL COOLER <i>Dented</i>	\$ 1,246.00 ✓	996.80
60	READY MIX- COOLANT <i>new</i>	4 \$ 84.00 ✓	67.20
SUB-FRONT -TOTAL SPARE PARTS CHARGES		\$ 12,674.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFQ 9212 K - FRONT

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
61	RADIATOR <i>Dented</i>	\$ 513.00	✓ 410.40
61	TWIN FAN RING FOR RADIATOR <i>Not Nec</i>	\$ 237.00	✗
62	RADIATOR FAN -RH <i>Not Nec</i>	\$ 673.00	✗
63	RADIATOR FAN -LH <i>Not Nec</i>	\$ 779.00	✗
64	CONTROL UNIT FOR RADIATOR <i>Not Nec</i>	\$ 778.00	✗
65	AIR GUIDE RADIATOR-LH/RH <i>Not Nec</i>	2 \$ 48.00	✗
66	RADIATOR SEALING STRIP -LOWER <i>Not Nec</i>	\$ 21.00	✗
67	AIR INTAKE MANIFOLD-FRONT <i>Not Nec</i>	\$ 88.00	✗
68	AIR INTAKE BELLOWS RESONATOR <i>Not Nec</i>	\$ 98.00	✗
69	AIR FILTER	\$ 279.00	✗
70	AIR INTAKE ADAPTER <i>Not Nec</i>	\$ 11.00	✗
71	AIR INTAKE MANIFOLD	\$ 117.00	✗
72	HALOGEN FOG LAMP-LH/RH <i>Not Nec</i>	2 \$ 484.00	✗
FRONT -TOTAL SPARE PARTS CHARGES		: \$ 29,584.00	
FRONT -TOTAL LABOUR CHARGES		: \$ 11,660.00	
FRONT GRAND TOTAL		: \$ 41,244.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFQ 9212 K - FRONT

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$360.00 ✓
2	To remove and renew aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system.	S/N \$ 1,200.00 ✓
3	To remove and renew front bumper, both front fenders, bonnet and both headlights. Remove and renew lock carrier and align to position. Reinstall all parts removed.	\$ 6,300.00 1500 (without lock carrier) 2750 (with lock carrier)
4	To respray front bumper, both front fenders and bonnet.	\$ 3,800.00 2200
FRONT-TOTAL LABOUR CHARGES		: <u><u>\$11,660.00</u></u>

+ SUPP

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFQ 9212 K - REAR

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Deformed</i>	\$ 2,100.00	✓ 1,680.00
2	REAR BUMPER STICKY PAD <i>new</i>	4 \$ 21.00	✗
3	REAR BUMPER FIXING PARTS <i>new</i>	\$ 206.00	✗
4	REAR BUMPER SPOILER <i>cut</i>	\$ 243.00	✓ 194.40
5	REAR BUMPER CARRIER <i>Bent</i>	\$ 587.00	✓ 469.60
6	REAR BUMPER SECURING STRIP <i>new</i>	\$ 12.00	✗
7	REAR BUMPER HOLDER BRACKET-LH/RH	2 \$ 406.00	✗
8	REAR BUMPER GUIDE SECTION-LH/RH UPPER	2 \$ 41.00	✗
9	REAR BUMPER GUIDE SECTION-LH	\$ 40.00	✗
10	REAR BUMPER GUIDE SECTION-RH	\$ 41.00	✗
11	REAR SENSOR <i>new</i>	4 \$ 838.00	?
12	REAR LID <i>Dented</i>	\$ 2,554.00	✓ 2,043.20
13	REAR LID ATTACHMENT PART <i>new</i>	\$ 67.00	✗
14	REAR LID GASKET FLAP <i>new</i>	\$ 185.00	✗
15	REAR LID LOCK-INNER	\$ 199.00	✗
16	REAR LID LOCK COVER	\$ 18.00	✗
17	REAR LID LOCK STRIKER	\$ 45.00	✗
18	REAR LID PUSH BUTTON FOR ELECTRIC <i>new</i>	\$ 167.00	✗
19	PACKING ADHESIVE <i>new</i>	\$ 18.00	✓ 13.92
20	GUARD PLATE-INNER <i>new</i>	\$ 56.00	✗
SUB- REAR -TOTAL SPARE PARTS CHARGES		\$ 7,844.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFQ 9212 K - REAR

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	REAR LID INSCRIPTION ' A4 '	\$ 87.00 ✓	69.28
22	REAR LID AUDI EMBLEM	\$ 113.00 ✓	90.00
23	REAR LID INSCRIPTION ' 1.8 T'	\$ 87.00 ✓	69.28
24	REAR CROSS PANEL -OUTER	\$ 286.00 ✗	
25	REAR CROSS PANEL-LOWER	\$ 794.00 ✗	
26	REAR BUMPER REINFORCEMENT BEAM -NNER	\$ 484.00 ✗	
27	REAR CROSS PANEL TRIM	\$ 167.00 ✗	
28	REAR SILENCER	\$ 1,019.00 ✗	
29	REAR SILENCER DUAL CLIP	\$ 54.00 ✗	
30	REAR SILENCER CLAMP	\$ 70.00 ✗	
31	REAR SILENCER BRACKET-LH	\$ 52.00 ✗	
32	REAR SILENCER BRACKET-RH	\$ 29.00 ✗	
33	ACYLIC SEALANT	S/N \$ 180.00 ✓ 2	
34	CAVITY WAX	S/N \$ 140.00 ✓ 2	
35	STONE CHIP	S/N \$ 180.00 ✓ 2	
36	FRONT NO. PLATE	S/N \$ 60.00 ✓	
37	REAR NO. PLATE	S/N \$ 60.00 ✗	
38	SUNDRIES	\$ 800.00 ?	53.28
REAR -TOTAL SPARE PARTS CHARGES		: \$ 12,506.00	
REAR -TOTAL LABOUR CHARGES		: \$ 9,104.00	
REAR - GRAND TOTAL		: \$ 21,610.00	
GRAND TOTAL (FRONT + REAR)		: \$ 62,854.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFQ 9212 K - REAR

S/n	Nature of Jobs		Estimated Charges	
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N	\$280.00	✓
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$	280.00	✓
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$	480.00	X
4	To dismantle and renew rear bumper and rear lid. Cut out and reweld end panelling. Re-organise rear crash management components. Reinstall all parts removed.	\$	4,200.00	1000. ✓
5	To respray rear bumper, rear lid and end panelling. To carry out joint sealer works and stone chip treatment.	\$	3,000.00	1650. ✓
6	To remove and renew lhs rear exhaust silencer. To align to position.	S/N \$	480.00	X
7	To carry out diagnostic check.	S/N \$	384.00	✓
REAR - TOTAL LABOUR CHARGES		:	<u><u>\$9,104.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name	:	Adrian Lim	
Surveyed Date	:	30/07/19	L/S (REPAIR LIMIT) = 15,700
Authorised Date	:		REPAIR DAYS = 16 DAYS
Excess Cost	:		
Liability	:		
Remarks	:	Not Authorized,	11 Days (without lock carrier) 14 Days (with lock carrier)

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant