

Mon 19/08 @ 10am

SKV6164A

S&R.

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

30 JUL 2019

## ESTIMATE

Estimate No. : b1 52173  
Date Estimated : 30/07/2019  
Prepared By : Han Kwan Yong

Page No. : 1 of 5

### - ESTIMATE REPAIR FOR -

Toh Ong Beng  
28 Canberra Drive  
#04-18

Singapore 768429

### - ACCOUNT - 40000

Cash Sales - Service  
Singapore

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL    | MILEAGE |
|-----------|-------------|------------|----------|---------|
| SKV6164A  | V458887     | 25/09/2015 | 218iA AT | 0       |

### DESCRIPTION

To replace rear bumper, boot lid including to knock out dented area caused by the accident

1700 2,550.00

To respray rear bumper and boot lid

1730 1,923.00

To carry out body cavity preservation.  
(Per panel).

100 118.00

To remove and install rear windscreen glass to transfer from old to new boot lid

451 574.00

To supply and install rear windscreen solar film.

451 531.00

To conduct water leak tests.

75 75.00

To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.

561 661.00

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

451 531.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

780 150.00

Total Labour 1: 7,290.00

### DESCRIPTION

TRUNK LID  
LETTERING 218 I  
GROMMET  
PLAQUE 74MM

| QTY | PRIC     |
|-----|----------|
| 1   | 1,204.35 |
| 1   | 64.10    |
| 2   | 0.75     |
| 1   | 71.25    |

### VALUE

bt 1,204.35  
ru 64.10  
ru 1.50  
ru 71.25

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 52173  
Date Estimated : 30/07/2019  
Prepared By : Han Kwan Yong

Page No. : 2 of 5

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL    | MILEAGE |
|-----------|-------------|------------|----------|---------|
| SKV6164A  | V458887     | 25/09/2015 | 218iA AT | 0       |

## DESCRIPTION

REAR WINDOW ESG  
SENSOR WIRE FOR SMART OPENER TOP  
SENSOR WIRE FOR SMART OPENER BOTTOM  
DECOUPLING RING PDC TORQUE CONVERTE  
PDC SENSOR MEDITERRANBLAU WC10  
(DG) CLEANER R1 (100ML)  
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)  
(DG/SL) GLASS PRIMER 30ML (VP206)

QTY PRIC

|   |        |
|---|--------|
| 1 | 654.35 |
| 1 | 43.15  |
| 1 | 41.50  |
| 2 | 5.05   |
| 1 | 380.65 |
| 1 | 26.15  |
| 2 | 131.55 |
| 1 | 27.85  |

VALUE

|        |
|--------|
| 654.35 |
| 43.15  |
| 41.50  |
| 10.10  |
| 761.30 |
| 26.15  |
| 263.10 |
| 27.85  |

Total Parts : 3,168.70

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date &amp; Time 19/8/19 10:30 Excess S\$

Surveyor's Name Tan Kah Sign

Surveyor's Tel 97495746 Authorised Yes / No

Authorised Date 'WP' Time

REGISTRY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tan.kah@pml.com.sg

No. of Working Days Recommend 6 days

|                |   |           |
|----------------|---|-----------|
| Labour 1       | : | 7,290.00  |
| Parts          | : | 3,168.70  |
| Labour 2       | : | 0.00      |
| Excess         | : | 0.00      |
| Total GST @ 7% | : | 732.11    |
| Grand Total    | : | 11,190.81 |

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*



# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 52173**  
Date Estimated : **30/07/2019**  
Prepared By : **Han Kwan Yong**

### - ESTIMATE REPAIR FOR -

**Toh Ong Beng**  
**28 Canberra Drive**  
**#04-18**

**Singapore 768429**

### - ACCOUNT - 121

**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

|                 |                        |                   |                 |          |
|-----------------|------------------------|-------------------|-----------------|----------|
| REGN. NO.       | CHASSIS NO.            | REGN. DATE        | MODEL           | MILEAGE  |
| <b>SKV6164A</b> | <b>WBA2A32060V4588</b> | <b>25/09/2015</b> | <b>218iA AT</b> | <b>0</b> |

| DESCRIPTION                                                                                                                              | ACCOUNT:<br>ORIGINAL PRICE | DISC. % | NETT     |
|------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|---------|----------|
| To replace rear boot lid, rear bumper and attachments etc including to remove and install body parts in order to carry out painting job. | 1,700.00                   | 0       | 1,700.00 |
| To respray rear bumper and rear boot lid                                                                                                 | 1,730.00                   | 0       | 1,730.00 |
| To carry out body cavity preservation.                                                                                                   | 100.00                     | 0       | 100.00   |
| To remove and install rear windscreen glass to transfer from old to new boot lid                                                         | 574.00                     | 0       | 574.00   |
| To conduct water leak tests.                                                                                                             | 75.00                      | 0       | 75.00    |
| To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.   | 451.00                     | 0       | 451.00   |
| To check electrical wiring systems and lightings at the rear section for proper function.                                                | 150.00                     | 0       | 150.00   |
| Sundries.                                                                                                                                | 80.00                      | 0       | 80.00    |

| DESCRIPTION                            | UNIT PRICE | QTY | DISC. % | NETT     |
|----------------------------------------|------------|-----|---------|----------|
| #                                      |            |     |         |          |
| # BLIND RIVET NUT M6                   | 2.55       | 2   | 0       | 5.10     |
| # BLIND RIVET NUT M6                   | 2.55       | 2   | 0       | 5.10     |
| TRUNK LID                              | 1,204.35   | 1   | 0       | 1,204.35 |
| # REAR BUMPER PANEL PRIMED (PDC)       | 1,045.45   | 1   | 0       | 1,045.45 |
| # EXPANDING NUT                        | 1.00       | 2   | 0       | 2.00     |
| LETTERING 218 I                        | 64.10      | 1   | 0       | 64.10    |
| GROMMET                                | 0.75       | 2   | 0       | 1.50     |
| PLAQUE 74MM                            | 71.25      | 1   | 0       | 71.25    |
| # BUMP STOP                            | 3.50       | 10  | 0       | 35.00    |
| DECOUPLING RING PDC TORQUE CONVERTE    | 5.05       | 2   | 0       | 10.10    |
| PDC SENSOR MEDITERRANBLAU WC10         | 380.65     | 1   | 0       | 380.65   |
| (DG) CLEANER R1 (100ML)                | 26.15      | 1   | 0       | 26.15    |
| (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) | 131.55     | 2   | 0       | 263.10   |
| (DG/SL) GLASS PRIMER 30ML (VP206)      | 27.85      | 1   | 0       | 27.85    |

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

### # SUPPLEMENTARY ITEMS

|                        |            |
|------------------------|------------|
| Total Labour :         | 4,860.00   |
| Total Parts :          | 3,141.70   |
| Total Labour & Parts : | 8,001.70 ✕ |
| GST @7%:               | 560.12     |
| Grand Total :          | 8,561.82   |

|                          | CD            | DATE     | WORKING DAYS |
|--------------------------|---------------|----------|--------------|
| FAX TO FAX NO            | Taufik<br>LHC | 27/10/19 | 6            |
| FAX TO FAX NO            |               |          |              |
| FAX TO FAX NO            |               |          |              |
| CONFIRMED DATE           |               |          |              |
| PLEASE FINALISE BY _____ |               |          |              |

LOSS OF USE = \$80 X 5 DAYS.  
MEDICAL FARE - \$122.00  
GIA SEARCH FEE - \$2.00



# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Supplementary

Estimate No. : **b1 52173**  
Date Estimated : **30/07/2019**  
Prepared By : **Han Kwan Yong**

### - ESTIMATE REPAIR FOR -

**Toh Ong Beng**  
**28 Canberra Drive**  
**#04-18**

**Singapore 768429**

### - ACCOUNT - 121

**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

|                 |                        |                   |                 |          |
|-----------------|------------------------|-------------------|-----------------|----------|
| REGN. NO.       | CHASSIS NO.            | REGN. DATE        | MODEL           | MILEAGE  |
| <b>SKV6164A</b> | <b>WBA2A32060V4588</b> | <b>25/09/2015</b> | <b>218iA AT</b> | <b>0</b> |

| DESCRIPTION | ACCOUNT:<br>ORIGINAL PRICE | DISC. % | NETT |
|-------------|----------------------------|---------|------|
|-------------|----------------------------|---------|------|

| DESCRIPTION                      | UNIT PRICE | QTY | DISC. % | NETT                |
|----------------------------------|------------|-----|---------|---------------------|
| #                                |            |     |         |                     |
| # BLIND RIVET NUT M6             | 2.55       | 2   | 0       | 5.10 <i>net</i>     |
| # BLIND RIVET NUT M6             | 2.55       | 2   | 0       | 5.10 <i>net</i>     |
| # REAR BUMPER PANEL PRIMED (PDC) | 1,045.45   | 1   | 0       | 1,045.45 <i>des</i> |
| # EXPANDING NUT                  | 1.00       | 2   | 0       | 2.00 <i>net</i>     |
| # BUMP STOP                      | 3.50       | 10  | 0       | 35.00 <i>net</i>    |

### # SUPPLEMENTARY ITEMS

|                        |          |
|------------------------|----------|
| Total Labour :         |          |
| Total Parts :          | 1,092.65 |
| Total Labour & Parts : | 1,092.65 |

