

Wed 14/08 @ 10am  
P&R

SKV7756K

BMW Dealer

### Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

30 JUL 2019

## E S T I M A T E

Estimate No. : b1 52157	Page No. : 1 of 5
Date Estimated : 30/07/2019	
Prepared By : Han Kwan Yong	

<b>- ESTIMATE REPAIR FOR -</b> <b>Aw Yong Jin Wei (Ouyang Jinwei)</b> <b>439 Fajar Road</b> <b>#09-418</b>  <b>Singapore 670439</b>	<b>- ACCOUNT - 40000</b> <b>Cash Sales - Service</b> <b>Singapore</b>
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV7756K	GK07743	30/09/2015	420IA GC	0

DESCRIPTION	VALUE
To replace front bumper, right headlight inner support including to knock out dented area caused by the accident	850 1,700.00
To respray rear bumper	937 1,038.00
To replace right headlight.	408 481.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
Sundries.	80.00

Total Labour 1: **3,476.00**

DESCRIPTION	QTY	PRIC	VALUE
# FRT BUMPER TOP CARRIER	1	415.50	415.50
FRT SHOCK ABSORBER	1	45.00	45.00
RH FOG LAMP SUPPORT	1	41.85	41.85
# INSERT AIR INLET MIDDLE	1	114.85	114.85
FRT BUMPER PANEL PRIMED (SRA)	1	1,078.65	1,078.65
RH COVER SPRAY NOZZLE PRIMED	1	43.25	43.25
SET MOUNTING PDC/PMA SENSOR FRT	1	75.30	75.30
GROMMET	2	0.75	1.50
EXPANDING RIVET D=8MM	10	1.05	10.50
RH SUPPORT	1	131.50	131.50
FRT BUMPER LOWER MOUNT	1	133.80	133.80
RH HEADLIGHT BRACKET	1	10.10	10.10
PLAQUE 82MM	1	71.25	71.25
# RH TELESCOPING NOZZLE	1	159.85	159.85
# RH BI XENON HEADLIGHT	1	2,119.70	2,119.70
RH FOG LIGHT	1	292.80	292.80
DECOUPLING RING PDC TORQUE CONVERTE	1	5.05	5.05
# ULTRASONIC SENSOR SPARLING B	1	368.80	737.60
(DG/SL) ADHESIVE SET K6	1	53.05	53.05

Total Parts : **5,541.10**

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 52157  
Date Estimated : 30/07/2019  
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV7756K	GK07743	30/09/2015	420IA GC	0

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>14/8/2019</u>	Excess S\$ _____
Surveyor's Name <u>Tan Jiah</u>	Sign <u>[Signature]</u>
Surveyor's Tel <u>97495749</u>	Authorised <u>Yes / No</u>
Authorised Date <u>WP</u>	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR <u>Yes / No</u>	PML <u>Yes / No</u>
Surveyor's E-mail <u>tanjiah@lkk.com</u>	
No. of Working Days Recommend <u>03 days</u>	

Labour 1	:	3,476.00
Parts	:	5,541.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	631.20
<b>Grand Total</b>	:	<b>9,648.30</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*