

Wed 14/08 @ 10am  
88R

SKV7756K

BMW Dealer

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

30 JUL 2019

**E S T I M A T E**

Estimate No. : b1 52157	Page No. : 1 of 5
Date Estimated : 30/07/2019	
Prepared By : Han Kwan Yong	

- ESTIMATE REPAIR FOR - Aw Yong Jin Wei (Ouyang Jinwei) 439 Fajar Road #09-418 Singapore 670439	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	--

REGN. NO. SKV7756K	CHASSIS NO. GK07743	REGN. DATE 30/09/2015	MODEL 420IA GC	MILEAGE 0
-----------------------	------------------------	--------------------------	-------------------	--------------

DESCRIPTION	VALUE
To replace front bumper, right headlight inner support including to knock out dented area caused by the accident	850 / 1,700.00
To respray rear bumper	934 / 1,038.00
To replace right headlight.	408 / 481.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 / 177.00
Sundries.	/ 80.00

Total Labour 1: 3,476.00

DESCRIPTION	QTY	PRIC	VALUE
# FRT BUMPER TOP CARRIER	1	415.50	unx 415.50
FRT SHOCK ABSORBER	1	45.00	unx 45.00
RH FOG LAMP SUPPORT	1	41.85	dis 41.85
# INSERT AIR INLET MIDDLE	1	114.85	unx 114.85
FRT BUMPER PANEL PRIMED (SRA)	1	1,078.65	de 1,078.65
RH COVER SPRAY NOZZLE PRIMED	1	43.25	at 43.25
SET MOUNTING PDC/PMA SENSOR FRT	1	75.30	net 75.30
GROMMET	2	0.75	unx 1.50
EXPANDING RIVET D=8MM	108	1.05	8.40 unx 10.50
RH SUPPORT	1	131.50	unx 131.50
FRT BUMPER LOWER MOUNT	1	133.80	unx 133.80
RH HEADLIGHT BRACKET	1	10.10	unx 10.10
PLAQUE 82MM	1	71.25	net 71.25
# RH TELESCOPING NOZZLE	1	159.85	dis 159.85
# RH BI XENON HEADLIGHT	1	2,119.70	cut 2,119.70
RH FOG LIGHT	1	292.80	unx 292.80
DECOUPLING RING PDC TORQUE CONVERTE	1	5.05	unx 5.05
# ULTRASONIC SENSOR SPARLING B (DG/SL) ADHESIVE SET K6	1	368.80	unx 368.80
	1	53.05	unx 53.05

Total Parts : 5,541.10

# Performance Motors Limited



A Sime Darby Motors Company  
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
 Toll-Free Number (1800-2255269)

303, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941  
 Fax. 64747770

280, Kampong Arang Road  
 East Coast Centre  
 Singapore 438180  
 Fax. 63449773

315, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Fax. 64796601 (AfterSales)  
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 52157 Date Estimated : 30/07/2019 Prepared By : Han Kwan Yong	Page No. : 2 of 5
---	-------------------

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV7756K	GK07743	30/09/2015	420IA GC	0

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 14/8/1A C11a Claim No. \_\_\_\_\_  
 Date & Time \_\_\_\_\_ Excess S\$ \_\_\_\_\_  
 Surveyor's Name Tan Jiah Sign [Signature]  
 Surveyor's Tel 97495449 Authorised Yes / No  
 Authorised Date WP Time \_\_\_\_\_  
 RESURVEY PARTS PHOTO BY SURVEYOR  Yes / No  No PML Yes / No \_\_\_\_\_  
 Surveyor's E-mail Tan Jiah @ [Email]  
 No. of Working Days Recommend 3 days

Labour 1	:	3,476.00
Parts	:	5,541.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	631.20
<b>Grand Total</b>	<b>:</b>	<b>9,648.30</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*  
 \*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 52157**  
Date Estimated : **30/07/2019**  
Prepared By : **Han Kwan Yong**

**- ESTIMATE REPAIR FOR -**  
**Aw Yong Jin Wei (Ouyang Jinwei)**  
**439 Fajar Road**  
**#09-418**

**Singapore 670439**

**- ACCOUNT - 121**  
**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SKV7756K</b>	<b>WBA4A12080GK0774</b>	<b>30/09/2015</b>	<b>420IA GC</b>	<b>0</b>

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	121 DISC. %	NETT
To replace front bumper panel, right telescoping nozzle and cover including to remove and install body parts in order to carry out painting job.	850.00	0	850.00
To respray rear bumper .	934.00	0	934.00
To replace right BI XENON headlight.	408.00	0	408.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00	0	150.00
Sundries.	80.00	0	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RH FOG LAMP SUPPORT	41.85	1.00	0	41.85
FRT BUMPER PANEL PRIMED (SRA)	1,088.90	1.00	0	1,088.90
RH COVER SPRAY NOZZLE PRIMED	43.25	1.00	0	43.25
SET MOUNTING PDC/PMA SENSOR FRT	75.30	1.00	0	75.30
EXPANDING RIVET D=8MM	1.05	8.00	0	8.40
PLAQUE 82MM	71.25	1.00	0	71.25
RH TELESCOPING NOZZLE	159.85	1.00	0	159.85
RH BI XENON HEADLIGHT	2,119.70	1.00	0	2,119.70
(DG/SL) ADHESIVE SET K6	53.05	1.00	0	53.05

CD	DATE	DAYS
Taufiqh Ltk	24/10/19	3
FAX TO FAX NO		
FAX TO FAX NO		
CONFIRM DATE		
PLEASE RETURN BY		

Total Labour :	2,422.00
Total Parts :	3,661.55
Total Labour & Parts :	6,083.55 *
GST @7%:	425.85
<b>Grand Total :</b>	<b>6,509.40</b>

LOSS OF USE = \$120X3 DAYS.  
LTA SEARCH FEE = \$7.45.