

Vehicle: GX9820G

Make & Model: *4d* Toyota Hiace

Chassis No: _____

n/s *3/7/29*

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Bootlid Tailgate <i>1487-10</i>			\$ 1,865.00	<i>Red 5.00</i>
2	Rear Bootlid Moulding <i>brush</i>			\$ 289.00	<i>good</i>
3	Rear Bootlid Number Plate Lamp	2	\$ 45.00	\$ 90.00	<i>nix</i>
4	Rear Number Plate			\$ 30.00 SN	<i>Buy 14</i>
5	70KM & 8 PAX Sticker			\$ 30.00 SN	<i>new 20</i>
6	Rear Bootlid Inner Lock			\$ 187.00	<i>new 1.00</i>
7	Rear Bootlid Wiper Motor			\$ 345.00	<i>new 1.00</i>
8	Rear Bootlid Lock Mechanism			\$ 322.00	<i>nix</i>
9	Rear Windscreen Rubber			\$ 198.00	<i>new 500</i>
10	Rear Taillamp (Left & right)	2	\$ 185.00	\$ 370.00	<i>one</i>
11	Weather Strip			\$ 190.00	<i>new</i>
12	Rear Bumper			\$ 395.00	<i>Dis</i>
13	Rear Bumper Inner Beam			\$289.00	<i>Buy</i>
14	Rear End panel			\$425.00	<i>Buy</i>
15	Reverse Sencer			\$ 200.00 SN	<i>Sub</i>
16					

S.W
S.W
99 S.W
S.W

Labour					
1	Transfer Bootlid			\$ 150.00	<i>60</i>
2	Transfer Glass			\$ 120.00	<i>60</i>
3	Remove & Refix Rear Bootlid inner Aluminium			\$ 100.00	<i>Rep/Box</i>
4	Anti Rust Proof			\$ 80.00	<i>60</i>
5	Check Wiring			\$ 80.00	<i>20</i>
6	Panel Beating			\$ 700.00	<i>600</i>

7	Paint Work			\$ 900.00	600
8					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3977-1
 252
 2982.82
 4715.82
 202
 3772