

Vehicle:

GX9820G

Alu Not Added

Make & Model:
Chassis No:

n/s #3700
4p

Toyota Hiace

3/7/19

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Bootlid Tailgate 1487-10			\$ 1,865.00	Bad 5.00 -
2	Rear Bootlid Moulding ^{BRUSH}			\$ 289.00	Good -
3	Rear Bootlid Number Plate Lamp	2	\$ 45.00	\$ 90.00	1 X
4	Rear Number Plate			\$ 30.00 SN	Best 14 S.W
5	70KM & 8 PAX Sticker			\$ 30.00 SN	new 20 S.W
6	Rear Bootlid Inner Lock			\$ 187.00	new 1/1m -
7	Rear Bootlid Wiper Motor			\$ 345.00	Ref 1/1m -
8	Rear Bootlid Lock Mechanism			\$ 322.00	1 X
9	Rear Windscreen Rubber			\$ 198.00	new 50g 99 S.W
10	Rear Taillamp (Left & right)	2	\$ 185.00	\$ 370.00	one -
11	Weather Strip			\$ 190.00	7m. -
12	Rear Bumper			\$ 395.00	Dis -
13	Rear Bumper Inner Beam			\$ 289.00	3rd -
14	Rear End panel			\$ 425.00	3rd -
15	Reverse Sencer			\$ 200.00 SN	5th - S.W
16					

Labour					
1	Transfer Bootlid			\$ 150.00	60
2	Transfer Glass			\$ 120.00	60
3	Remove & Refix Rear Bootlid inner Aluminium			\$ 100.00	Rep 1/1m
4	Anti Rust Proof			\$ 80.00	60
5	Check Wiring			\$ 80.00	20
6	Panel Beating			\$ 700.00	600

7	Paint Work			\$ 900.00	600
8					

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3977-1
 252
 2982.82
 4715.82
 207
 3772