

12507200

ASS. REC. BY:

REF: CS/CTI19013420/Ky/d3m2 Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI Date/Time: 30/7/19 @ 5:30am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLZ1062K Insured: CB 6604Y

at Workshop m/s Estem Performance Tel: 8799 0066

of 385 Sin Ming Drive

Policy No: MMB15N 143969 18044 Claim No: SNM19D 203530 cor

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 26/7/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS lap H.O.D. Endorsement: _____

Date/Time: 10:23am 31/7/19 Person Contacted: _____ Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	SLZ1062K - NBA / CTI19013258 / Y	JOA: 26/7/2019
	CB 6604Y - NBA / CTI19013258 / Y	JOA: 26/7/2019
	Kenneth confirmed final fig \$2977.45, 4 days. (Red \$3076.88, 50%)	

REF: OTI

ASS. REQ. BY:

ASSIGNMENT

From: _____ Date: 5/8/19

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLZ 1062K

at Workshop m/s Esteem Performance

of 385 Sin Ming Drive

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: After 11am

Veh No: SLZ 1062K Yr Regn: 04, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius C.C. 1797

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 121557 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZUV40 0027949

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: Falken 205/60R16

R Nexen

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front		Rear	
R/Bal.	<u>2</u> mm	R/Bal.	<u>3</u> mm
L/Bal.	<u>2</u> mm	L/Bal.	<u>3</u> mm
D.O.A.	<u>1 / 119</u>	D.O.I.	<u>5/8/19</u>

Survey held at

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1.3.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Cup

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
RECEIVED 22 AUG 2019	

Date/Time, File Pass to? : Prel. Report

1) 21/8 Junia : Final Report

Date/Time, File Return to?

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:	
Transportation:	
S + RS. SI	
Photos	
Others	<u>220</u>
TOTAL	

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Report Format: MER-TP

Lump Sum / E.R.T. (\$): 2977.45

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 30 July 2019 5:13 PM
To: jenny chong
Cc: assignments
Subject: RE: OUR REF : SNM19D203530-CB6604Y-THP - FW: REQUEST FOR PRI SURVEY SLZ1062K

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: jenny chong [mailto:jenny@esteemperf.com.sg]

Sent: Tuesday, 30 July, 2019 5:10 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: OUR REF : SNM19D203530-CB6604Y-THP - FW: REQUEST FOR PRI SURVEY SLZ1062K

Dear Sir / Madam

We are prefer KENNETH KONG to survey the car.

Thank you

Freundliche Grüße / Best Regards

Jenny Chong

Senior Operation Executive | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221

F: 6484 7829

E: jenny@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com



On Tue, Jul 30, 2019 at 5:06 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: jenny chong [<mailto:jenny@esteemperf.com.sg>]

Sent: Tuesday, July 30, 2019 2:35 PM

To: Claims Dept of CTI

Cc: carmen lim; serence ctc; keith tan; Kaeley Ng

Subject: REQUEST FOR PRI SURVEY SLZ1062K

Dear Sir / Madam,

Accident involving SLZ1062K & CB6604Y(CHINA TAIPING) on 26.07.2019

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PRE-ACTION PROTOCOAL FOR NON INJURY MOTOR ACCIDENT CASES
(NIMA)**

We act for Goldbell car Rental Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no.SLZ 1062 K

Please be informed that the said vehicle can be inspected at :

Name of workshop : Esteem Performance Pte Ltd

Address : BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 (S) 569536

Tel : 6566 2112

Fax : 6259 3326

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

We will email the GIA report to you once received

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.



Freundliche Grüße / Best Regards

Jenny Chong

Senior Operation Executive | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221


F: 6484 7829

E: jenny@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259
(Head Office)

385 Sin Ming Drive Vicom Inspection Centre
(Showroom)

www.esteemperformance.com



For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/07/2019 09:46
Date Of Accident	26/07/2019 16:10
Exact Location Of Accident	ALONG BUKIT PANJANG TOWARDS WOODLANDS CRESCENT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ1062K
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL CAR RENTAL PTE LTD
Co Reg No	200710651D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66039399
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS ALPHA
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999994314
Cover Note Number	
Driver	
Name of Driver	YAP CHOON KIONG
NRIC No	S7307384G
Date Of Birth	26/02/1973
Occupation	OUTDOOR
Date Of Driving Pass	08/06/1998
Driving Experience	21 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91001110
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 785B WOODLANDS RISE #09-82
Postcode	732785
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND 1 PASSENGER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO - ESTEEM PERFORMANCE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	CB6604Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	YAO DELONG
NRIC/Passport Number	G2350221L
Contact Number	82099569
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

1. Please report accurately the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 GOLD BELL CAR RENTAL PTE LTD

Policyholder's Signature

Date & Time:

29 JUL 2019

9:46 AM



Driver's Signature

(If driver is not the policyholder)

Date & Time: 26-07-2019

6:11:32 AM




Reporting Centre Personnel's Signature

Name: Poon Kwee Choo

NRIC/FIN No.: S8840583A

Sketch Plan Pg. 2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26/7/2019 @ 16:10, I was Driving along Bukit Panjang towards Woodlands crescent and was about to turn right in to ISSB Woodlands Rise HDB. I saw a Vehicle B at the entrance, so I stop at my lane, the vehicle B cut to my lane and hit on to my left hand front portion.

DECLARATION

I/we declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time: 29 JUL 2019

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time: 26-07-2019 @ 11:30 AM

[Signature]

Reporting Centre Personnel's Signature
Name: [Name]
NRIC/FIN No: [No.]

CERTIFICATE OF INSURANCE Pg. 1

HOTLINE TEL: (65) 6419-2000



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1999 (MALAYSIA)

M.Z.420

Comprehensive Commercial Motor		(The below excess is subject to GST)	
CERTIFICATE NO.	999994314	POLICY EXCESS	
1) VEHICLE REGISTRATION NO.		WINDSCREEN EXCESS	S\$100.00
2) NAME OF POLICYHOLDER		SUM INSURED	Market Value
3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT		INSURING WITH COE/PARF	Yes
4) DATE OF EXPIRY OF INSURANCE		SLZ1062K	
5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*		Goldbell Car Rental Pte Ltd	
		01 January 2019	
		31 March 2020	
<p>Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.</p>			
6) LIMITATION AS TO USE*			
<p>1) Use for social, domestic, pleasure purposes and business purposes of Insured 2) Use for social, domestic, pleasure purposes and business purposes of any person whom the vehicle is hired. 3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.</p>			
<p>The Policy does not cover: 1) Use for livery, driving test, racing, pace-making, reliability trial or speed-testing. 2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle. 3) Use for any purpose in connection with the Motor Trade.</p>			
LOSS OF USE	Not Included		
HIRE PURCHASE COMPANY	DBS Bank Ltd		
<p>*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.</p>			

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore: 17 Jan 2019

AIG Asia Pacific Insurance Pte. Ltd.

030123-000
 Acorn International Network Pte Ltd
 48 Changi South St 1 Level 3
 SINGAPORE 486130

M. Anis

AUTHORISED REPRESENTATIVE

SSPKWJ

ORIGINAL



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLZ 1062 K

*Not Authorized
 Return Byrain*

Parts	(a) Cost / List Price Items	\$	<u>4,979.10</u>
	Plus/Less 25%	\$	<u>1,244.78</u>
	Total of Cost / List	\$	<u><u>3,734.33</u></u>
	(b) Nett Price Items		_____
	Less		_____
	Total of Nett Item		_____
	(c) Special Nett Items	\$	<u>350.00</u>
Total Parts Cost		\$	<u><u>4,084.33</u></u>
Labour		\$	<u><u>1,920.00</u></u>
Total		\$	<u><u>6,004.33</u></u>

UKK Auto Company's terms notify the Repairer of the following:

- To resurvey once after work starting
- To complete approved work within 14 days
- To be held liable for any contamination
- This work is done on a "Without Prejudice" basis
- No direct or indirect work is allowed
- Supplementary repairs must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : UKK

Survey conducted on : 5/8/11 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : [Signature] Date: 5/8/11



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Spare Parts

Vehicle No. : SLZ 1062 K
 Make & Model : TOYOTA PRIUS ALPHA
 Chassis No : ZVW400027949

Submit By : JENNY
 Year Manufacture : 2017
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp LH <i>W</i>	1	\$959.10		—
2	Headlamp clip <i>M</i>	10	\$32.10		—
3	Front bumper <i>Bu</i>	1	\$489.20		—
4	Front bumper clip <i>M</i>	10	\$38.90		—
5	Front bumper side retainer LH <i>Dii</i>	1	\$78.90		✓
6	Front bumper side retainer RH <i>Sn</i>	1	\$78.90		X
7	Front bumper bracket LH <i>K</i>	1	\$202.30		X
8	Front bumper bracket RH <i>n</i>	1	\$202.30		X
9	Fog lamp LH	1	\$236.90		<i>SVC</i> ? X
10	Fog lamp garnish LH <i>M</i>	1	\$236.90		✓
11	LH front fender <i>M</i>	1	\$787.60		✓
12	LH front fender undershield	1	\$168.73		? <i>UPA</i> ✓
13	LH front fender undershield clip	10	\$22.10		? <i>XAN</i>
14	LHF fender wording "HYBRID" <i>M</i>	1	\$45.17		✓
15	LH front rim <i>Sn</i>	1	\$1,400.00		X
16	LH front tyre <i>Sn</i>	1	\$350.00	S.N	X
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ESTEEM PERFORMANCE

Blok 5033 Ang Mo Kio, Ind Park2 #01-251/259, 5695362
 Tel: +65-6484 1921 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

K9

Repair Estimates

SLZ 1062 K

Not Authorized
 Anthony B. G. G. G.
 82977.45

Parts	(a) Cost / List Price Items	\$ <u>73660</u>	4,979.10
	Plus/Less 25%	\$ <u>7095</u>	1,244.78
	Total of Cost / List	\$ <u>712745</u>	3,734.33
	(b) Nett Price Items	_____	_____
	Less: _____	_____	_____
	Total of Nett Item	_____	_____
	(c) Special Nett Items	\$ _____	350.00
Total Parts Cost:		\$ _____	4,084.33
Labour		\$ <u>850.00</u>	1,920.00
Total		\$ <u>707745</u> ✓ OK	6,004.33

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	_____	_____
Company	:	_____	_____
Survey conducted on	:	_____	_____
Remarks By Surveyor			
(a)	The repair of this vehicle is <u>authorized</u> / is not authorized until further notice.		
(b)	Recommended Days of Repair	:	_____ <u>09</u> _____ day(s)
(c)	Resurvey	:	Required / <u>Not Required</u>
(d)	Excess	:	\$ _____
(e)	Signature of surveyor	:	_____ <u>Je</u> _____ Date: <u>5/8/19</u>

ESTEEM PERFORMANCE

Blk 5033 Ang Mo Kio, Inc-Park 2 #01-251/252, 569536,
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :	<u>SLZ 1062 K</u>	Submit By :	<u>JENNY</u>
Make & Model :	<u>TOYOTA PRIUS ALPHA</u>	Year Manufacture :	<u>2017</u>
Chassis No. :	<u>ZVW400027949</u>	Engine No. :	<u> </u>
		Cost / List	

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp LH	1	\$959.10		✓
2	Headlamp clip	10	\$32.10		✓
3	Front bumper	1	\$489.20		✓
4	Front bumper clip	10	\$38.90		✓
5	Front bumper side retainer LH	1	\$78.90		✓
6	Front bumper side retainer RH	1	\$78.90		X
7	Front bumper bracket LH	1	\$202.30		X
8	Front bumper bracket RH	1	\$202.30		X
9	Fog lamp LH	1	\$236.90		X
10	Fog lamp garnish LH	1	\$236.90		X
11	LH front fender	1	\$787.60		✓
12	LH front fender undershield	1	\$168.73		ⓧ
13	LH front fender undershield clip	10	\$22.10		X
14	LHF fender wording "HYBRID"	1	\$45.17		✓
15	LH front rim	1	\$1,400.00		X
16	LH front tyre	1	\$350.00	S.N	X
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

2826 60

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119013420/KQD3N2

Date: 26/08/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN14396918044		
Claimant Vehicle No :	SLZ1062K	Insured Vehicle No :	CB6604Y		
Date of Loss:	26/07/2019	Nature of Claim:	TP	Claim No:	SNM19D203530C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ1062K	Engine No:	2ZR0A75711
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	ZVW400027949
Reg. Date:	23/04/2018 (Man. Year: 2017)	Odometer:	121557 km
Colour:	Red		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Falken 2 mm	Rear Left Side:	Nexen 3 mm
Front Right Side:	Falken 2 mm	Rear Right Side:	Nexen 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,084.32	2,127.45	1,956.87	47.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	850.00	1,070.00	55.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,004.32	2,977.45	3,026.87	50.41
+ GST 7.00/7.00% (S\$)	420.30	208.42	211.88	50.41
Nett Amount (S\$)	6,424.62	3,185.87	3,238.75	50.41

INSPECTION

Date of Assignment:	21/08/2019		
Date Inspected:	05/08/2019	Inspected At:	385 Sin Ming Drive Repairer: Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259 Singapore 569536

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Aug 2019)
Parts: 144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ1062K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Cut	959.10 FL	*959.10 FL
2	10		*HEADLAMP CLIP	Necessary	32.10 FL	*32.10 FL
3	1		*FRONT BUMPER	Buckled	489.20 FL	*489.20 FL
4	10		*FRONT BUMPER CLIP	Necessary	38.90 FL	*38.90 FL
5	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	78.90 FL	*78.90 FL
6	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	78.90 FL	*- FL
7	1		*FRONT BUMPER BRACKET LH	Repair	202.30 FL	*- FL
8	1		*FRONT BUMPER BRACKET RH	Repair	202.30 FL	*- FL
9	1		*FOG LAMP LH	Serviceable	236.90 FL	*- FL
10	1		*FOG LAMP GARNISH LH	Dented	236.90 FL	*236.90 FL
11	1		*LH FRONT FENDER	Bent	787.60 FL	*787.60 FL
12	1		*LH FRONT FENDER UNDERSHIELD	Cracked	168.73 FL	*168.73 FL
13	10		*LH FRONT FENDER UNDERSHIELD CLIP	Not Necessary	22.10 FL	*- FL
14	1		*LHF FENDER WORDING HYBRID	Necessary	45.17 FL	*45.17 FL
15	1		*LH FRONT RIM	Serviceable	1,400.00 FL	*- FL
16	1		*LH FRONT TYRE	Serviceable	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,329.10	2,836.60
- List Item Discount on L Items 25.00/25.00% (S\$)	1,244.78	709.15
Total Parts (S\$)	4,084.32	2,127.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(FRONT BUMPER,LHF FENDER,BONNET,FRONT SUPPORT PANEL)	New	800.00	400.00
2	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(FRONT BUMPER,LHF FENDER,BONNET,FRONT SUPPORT PANEL)	New	800.00	400.00
3	TO CHECK WIRING	New	50.00	20.00
4	TI TUFF COAT	New	150.00	30.00
5	TO DO WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (S\$)			1,920.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >