

T K MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL: 96273323 FAX: 68442641
CO. REG NO :53049097L

Adrian

Third party: MSIG Ins.

DATE: 10/8/2019

DR YEO CHYE LUAN
45 JALAN HAJI SALAM, TAMAM SALAM
SINGAPORE 468832

TPMSIG.

Lump Sum: 7 day.

Denise

By Hand 15/10/2019

DEAR SIR

MR053 DK 5100104814

ACCIDENT DATE: 26/07/2019

ESTIMATE COST OF REPAIRS BILL TO TOYOTA CAMRY CAR NO: SCH7800J

1	PC REAR BUMPER <i>deformed</i>	S\$ 697.10	697.10 ✓
1	PC REAR BUMPER REINFORCEMENT <i>4x6 Noc</i>	455.60	455.60 X
8	PC REAR BUMPER CLIP <i>Noc</i>	103.20	103.20 30
2	PC REAR BUMPER SIDE RETAINER <i>RH Noc</i>	125.80	125.80 62.80
2	PC REAR BUMPER SIDE CLIP <i>Noc</i>	56.20	56.20 30
2	PC REAR BUMPER REVERSE SENSOR & COVER <i>1 piece dng</i>	1,072.80	1,072.80 X 268.20
1	PC REAR BUMPER LOWER GARNISH <i>cnld</i>	285.90	285.90 ✓
8	PC REAR BUMPER LOWER GARNISH CLIP <i>cnld</i>	44.00	44.00 20
2	PC REAR BUMPER REFLECTOR <i>cnld</i>	150.40	150.40 ✓
1	PC REAR BUMPER LED LIGHTING <i>Noc</i>	60.00	60.00 S/NETT X
1	PC REAR R/H TAILLAMP <i>Noc</i>	404.10	404.10 X
1	PC REAR R/H FENDER INNER SHIELD <i>toru</i>	172.60	172.60 ✓
1	PC REAR R/H FENDER INNER SHIELD BRACKET <i>3mm</i>	45.70	45.70 X
10	PC REAR R/H FENDER INNER SHIELD BRACKET CLIP	38.00	38.00 X
1	PC REAR R/H 19 INCH SPORT RIM <i>at</i>	850.00	850.00 S/NETT 650(SW)
1	PC REAR R/H 245/40/R19 TYRE <i>1st</i>	650.00	650.00 S/NETT 350(SW)
2	PC REAR R/H LOWER ARM <i>Best</i>	635.10	635.10 245
1	PC REAR R/H KNUCKLE ARM <i>2nd</i>	565.10	565.10 ✓
1	PC REAR R/H KNUCKLE HUP & ABS BEARING <i>Damaged</i>	780.10	780.10 445
1	PC REAR R/H LINKAGE <i>Noc</i>	129.10	129.10 X
1	PC REAR R/H TRAILING ARM <i>Best</i>	329.10	329.10 295
1	PC REAR R/H SHOCK ASBORBER <i>2x2mm</i>	408.20	408.20 X
1	PC REAR STABILIZER BAR <i>1x2mm</i>	316.10	316.10 X
1	PC REAR CONTROL ARM SENSOR <i>1x2mm</i>	169.10	169.10 X
		3267.10	
		2450.32	
		S.N: 1000	

TO CHECK WRING.

50.00 50.00 30

TO SPRAY PAINTING.

1,000.00 1,000.00 550

TO REMOVE & REFIX REAR INTERIOR UPHOSLY.

120.00 120.00 X

TO REMOVE & REFIX EXHAUST PIPE.

80.00 80.00 X

TO COMPUTER WHEEL ALIGHTMENT.

120.00 120.00 S/NETT 80

TO REMOVE & REFIX REAR UNDER CARRIAGE & CROSS MEMBER.

550.00 550.00 220

LABOUR CHARGE TO RESET FAULT CODE & CARRY OUT
DIAGNOSTIC CHECKS.

80.00 80.00 X

TO LABOUR CHARGE FOR PANEL BEATING, WELDING, REMOVING
ALL DAMAGED PARTS & REPLACING OF THR NEW PARTS ETC.

750.00 750.00 400

TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED
PANEL FOR RUST PROTECTION.

80.00 80.00 X 1330

TO MEASURE DRILL THE REPLACED BUMPER, POSITION & RESTALL
REAR BUMPER CONTROL UNIT CHECK & TEST FOR FUNCTIONING
& CAMERA.

80.00 80.00 50

TOTAL S\$

11,453.10

Acknowledged by Repairer

Signature:

Date:

total: 4780.32
4/5: 38k
06 Days



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	CASH	DATE	Aug 6, 2019 5:07:19 PM
LICENSE NO.	SCH 7800 J		
MILEAGE	76021		
REFERENCE	CUSTOM	MODEL	TOYOTA CAMRY (V51)

Front Wheel	SPECS				DIAGNOSIS				ADJUSTMEN			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-2.50	0.00	2.50			0.60				0.00		
PARTIAL TOE	-1.20	0.00	1.20		1.50		-0.90		0.00		0.00	
SET BACK	---	---	---			0°04"				0°04"		
CAMBER	-1°18"	-0°32"	0°12"		-1°08"		-1°12" 0°02"		-1°08"		-1°10" 0°00"	
CASTER	1°54"	2°54"	3°54"		2°38"		2°48" 0°10"		2°38"		2°48" 0°10"	
KING-PIN	---	---	---		12°52"		12°26" 0°24"		12°52"		12°26" 0°24"	
INCLANGLE	---	---	---		11°42"		11°14"		11°42"		11°16"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel	SPECS				DIAGNOSIS				ADJUSTMEN			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	0.00	2.50	5.00			1.60				2.40		
PARTIAL TOE	0.00	1.20	2.50		-0.30		1.90		1.20		1.20	
SET BACK	---	---	---			-0°20"				-0°20"		
CAMBER	-1°30"	-0°44"	0°00"		-1°44"		-1°48" 0°02"		-1°46"		-1°46" 0°00"	
THRUST ANGLE	-0°08"	0.00	0°08"			-0°10"				0°00"		