

ASS. REC. BY:

REF: es/FCI19013432/ks d3m2 Special Instructions:Survey: KomethASSIGNMENT (Office)From (Person): Henry Kao of FCI Date/Time: 818am @ 31/7/19

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLF 8115B Insured: SHB3357Xat Workshop in/s Esteem Performance Tel: 8799 0066of 385 Sin Ming Ave. #Policy No: _____ Claim No: D19004880MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 24/7/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS cup H.O.D. Endorsement: _____Date/Time: 9:49am @ 31/7/19 Person Contacted: Carmen Vehicle IN OUTDate/Time Action/Instruction Johny ✓SLF 8115B-XSHB 3357X- CS / 7MI17007646 / H/L/bn2 D.O.A. 7/4/20176/8 @ 2:45pm- Revised via email preli advise19/8 83770.23 Cashmere(\$ 1,571.68 Red. 34%)

ASS. REC. BY:

REF:

1001

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1. B. 1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLF 8115B Yr Regn: 09, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Privia c.c. 1750

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 216060 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB31E4 703 532682

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 6 mm

L/Bal. 9 mm L/Bal. 6 mm

D.O.A. 24/7/19 D.O.I. 3/8/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

RECEIVED 19 AUG 2019

Date/Time, File Pass to?

1) 19/08/19 Typing

Date/Time, File Return to?

2)

☐ : Prell. Report☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

140

50

50

15

255

Report Format :

Lump Sum / I.B.T (\$)

3,770.23 P/A



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004880MFSH

Date: 06/08/2019

Our Ref: CS/FCI19013432/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLF 8115B

Please be informed that we had conducted the inspection of the abovementioned vehicle 5/8/2019 at the premises of M/s Esteem Performance have the following to report: -

Workshop Estimate Amount	: S\$	<u>5,741.91</u>
Revised Estimate Amount	: S\$	<u>3,770.23</u>
"Check" Items Amount	: S\$	<u>0.00</u>
Market Value	: S\$	<u> </u>
LTA Reimbursement Value	: S\$	<u> </u>
Nett Value	: S\$	<u> </u>

Description of Damage:

The vehicle sustained damages at the o/s front portion



Comments/ Present Status:

Damages Consistent.

Yours faithfully
Kenneth
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	26-07-2019	Our Ref No. D19004880MFSH
Accident Date	24-07-2019	Claim Type. Third Party
Insured Vehicle	SHB3357X	Third Party Vehicle. SLF8115B
Survey Location	385 SIN MING DRIVE (S) 575718 (INSIDE VICOM)	
Contact Person.	SERENCE CHEE	
Contact No.	87990066/ 87990066	Fax No. 62593326
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 6 August 2019 2:45 PM
To: 'CWS Motor Claims'
Cc: 'Henry Kao'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004880MFSH/1
Attachments: PRELI ADVISED OF SLF 8115B.pdf

Dear Sir/Madam,

Enclosed preliminary revised of **SLF 8115B**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 31 July 2019 8:17 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004880MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

(e) Signature of surveyor:  Date: 5/8/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLF 8115 B
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU703532682

Submit By : SERENCE
Year Manufacture : 2016
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp RH	1	\$2,531.60		✓
2	Front bumper	1	\$450.80		✓
3	Front bumper clip	10	\$40.00		✓
4	Front bumper reinforcement - upper	1	\$711.50		X
5	Front bumper reinforcement - lower	1	\$245.30		X
6	Front bumper side retainer RH	1	\$107.20		✓
7	Front bumper side retainer LH	1	\$107.20		X
8	Front bumper sponge - upper	1	\$89.81		X
9	Front bumper sponge - lower	1	\$135.70		X
10	Fog lamp RH	1	\$910.70		✓
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Labour

Vehicle No. :	<u>SLF 8115 B</u>	Submit By :	<u>SERENCE</u>
Make & Model :	<u>TOYOTA PRIUS</u>	Year of Manufacture :	<u>2017</u>

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19013432/Ksd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-08-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3357X	Veh. Inspected	SLF 8115B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004880MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	31/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDKB3FU703532682	Colour	METALLIC PEARL WHITE	
Odometer	216060	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	9 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	9 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/07/2019	Inspection Date	05/08/2019	
Survey held at	385 SIN MING DRIVE			
Repairer	ESTEEM PERFORMANCE PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 8115B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HEADLAMP RH	CUT	2,531.60	2,531.60
1	FRONT BUMPER	BUCKLED	450.80	450.80
10	FRONT BUMPER CLIP	NECESSARY	40.00	40.00
1	FRONT BUMPER REINFORCEMENT-UPPER	TO REPAIR SEE LABOUR	711.50	-
1	FRONT BUMPER REINFORCEMENT-LOWER	TO REPAIR SEE LABOUR	245.30	-
1	FRONT BUMPER SIDE RETAINER RH	DISTORTED	107.20	107.20
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	107.20	-
1	FRONT BUMPER SPONGE-UPPER	SERVICEABLE	89.81	-
1	FRONT BUMPER SPONGE-LOWER	SERVICEABLE	135.70	-
1	FOG LAMP RH	CUT	910.70	910.70
	LESS 25% DISCOUNT		-1,332.45	-1,010.07
			3,997.36	3,030.23
	LABOUR			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(FRONT BUMPER,SUPPORT PANEL).INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT-UPPER AND FRONT BUMPER REINFORCEMENT-LOWER.		800.00	280.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(FRONT BUMPER,SUPPORT PANEL,RHF FENDER).		800.00	440.00
	TO TUFF COAT.	NOT NECESSARY	50.00	-
	TO CHECK WIRING.		50.00	20.00
			1,700.00	740.00
	GRAND TOTAL		5,697.36	3,770.23
	RECOMMENDED COST OF REPAIRS			3,770.23

Report Ref No. CS/FC119013432/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.