


REPAIR ESTIMATE*

INDIA

Page 1 of 2

SHC 1225B

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,400.00 1000/-
	Spray Painting Charge			\$ 1,250.00 900/-
	Wiring Charge			\$ 100.00 100/-
	Tuff Kote			\$ 150.00 40/-
	Towing Charge			\$ 90.00 120/-
	Transfer of Door	\$	120.00	\$ 240.00 120/-
	Remove/Refix Undercarriage (FRT)			\$ 400.00 120/-
	Front Wheel Alignment			\$ 120.00 120/-
	Re-set Frt ABS System			\$ 200.00 120/-
	Re-set Frt & Rear Power Window System	\$	200.00	\$ 400.00
	R/Refix Air Bag/Steering Wheel/Dashboard/Seat			\$ 550.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 } 350/-
	TOTAL LABOUR			\$ 5,380.00
	ESTIMATE TOTAL			\$ 27,074.28
	31/07/2019 @ 1400m N/A Actual 2/Sum  gar 2kk Actual  9 days.			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 1225B (Supplementary)

DATE : 31.07.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Y, Sh mer

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Seat Side Garnish,RH <i>broken</i>			\$ 198.00 ✓
	Rear Trimboard Top Garnish,RH <i>broken</i>			\$ 159.00 ✓
	SUB TOTAL			\$ 357.00
	LESS 20%			\$ 71.40
	DISCOUNTED TOTAL			\$ 285.60
<i>02/08/2019</i> <i>[Signature]</i> <i>2KK Auto</i> <i>[Signature]</i>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

FAX : 6542 6039

Page 1 of 1