

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Aug 2019 Edit Reg		30 Jul 2019 00:00 Edit Adj Rpt	S\$867.47 Edit Estimates	S\$867.47 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]
Insured:	BS Car Rental Pte Ltd, Co. Reg. No.: NA	
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K	
Vehicle Reg. No.:	SHB7608X	Date of Loss: 29/07/2019 11:00 - :59 [2 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3145032669SG	Policy/Cover Note No.: 0999994153
Vehicle Reg. No. (Insured):	SJG5372M	Policy No. (Claimant): VFX/P2203857
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:	
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]	
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/08/2019]	
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (05/08/2019): Re: No OI GIA Report AIG_SG (01/08/2019): No OI GIA Report 		
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete
Due Date	Priority	Type
Task Group	Subject	Handler
Assigned By	Completed On	Created On
Done?		
No results.		

Claim Documents

***SHB7608X (3145032669SG)**
[SJK5372M]
TP
TRANS-CAB SERVICES PTE LTD
Jul 29 2019 11:00AM
[BS Car Rental Pte Ltd]
Trans-cab Auto Services Pte Ltd

View

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/08/19 11:48	Video - Accident TP VIDEO	Load WMV	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/08/20 13:43	General View	Load JPG	<input checked="" type="checkbox"/>
2	27/08/20 13:43	General View	Load JPG	<input checked="" type="checkbox"/>
3	27/08/20 13:43	General View	Load JPG	<input checked="" type="checkbox"/>
4	27/08/20 13:43	General View	Load JPG	<input checked="" type="checkbox"/>
5	27/08/20 13:43	General View	Load JPG	<input checked="" type="checkbox"/>
6	27/08/20 13:43	General View	Load JPG	<input checked="" type="checkbox"/>
7	27/08/20 13:43	General View	Load JPG	<input checked="" type="checkbox"/>
8	27/08/20 13:43	General View	Load JPG	<input checked="" type="checkbox"/>
9	27/08/20 13:43	General View	Load JPG	<input checked="" type="checkbox"/>
10	27/08/20 13:43	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
11	27/08/20 13:43	General View	Load JPG	<input checked="" type="checkbox"/>
12	27/08/20 13:43	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
13	27/08/20 13:43	General View	Load JPG	<input checked="" type="checkbox"/>
14	27/08/20 13:43	General View	Load JPG	<input checked="" type="checkbox"/>
15	10/09/20 15:43	Reinspection Photo	Load PDF	

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/07/19 17:11	TP GIA REPORT	Load PDF	
2	01/08/19 11:56	TP ESTIMATE-MARKED	Load PDF	
3	16/08/19 15:42	NR LETTER_1st Registered Letter	Load PDF	
4	21/08/19 11:47	ACCIDENT SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>
5	21/08/19 12:15	ACCIDENT SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>
6	21/08/19 12:15	ACCIDENT SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>
7	19/09/19 12:10	Form to Traffic Police (Non-Reporting)	Load PDF	
8	19/09/19 12:10	NR LETTER_2nd Registered Letter	Load PDF	
9	03/01/20 17:32	PIR	Load PDF	
10	27/08/20 13:34	Non_reporting_letter	Load PDF	
11	27/08/20 13:41	Receipt on 19082019	Load PDF	
12	27/08/20 13:41	Receipt on 20092019	Load PDF	
13	10/09/20 15:37	EMAIL	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG19013438/KDA3S2**Date:** 14/09/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994153
Claimant Vehicle No :	SHB7608X	Insured Vehicle No :	SJG5372M
Date of Loss:	29/07/2019	Nature of Claim:	TP
		Claim No:	3145032669SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB7608X	Engine No:	2ZR2C10347
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU503080098
Reg. Date:	17/05/2019 (Man. Year: 2018)	Odometer:	32008 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,975.15	447.47	13,527.68	96.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,100.00	420.00	11,680.00	96.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,075.15	867.47	25,207.68	96.67
+ GST 7.00/7.00% (S\$)	1,825.26	60.72	1,764.54	96.67
Nett Amount (S\$)	27,900.41	928.19	26,972.22	96.67

INSPECTION

Date of Assignment:	30/07/2019		
Date Inspected:	30/07/2019	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

DIFFERENT BY 1 CENT. FINALIZE CONFIRMED AMOUNT \$867.48

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Serviceable	458.60 FL	*- FL
2	1		*REAR BUMPER RE-INFORCEMENT	Serviceable	318.80 FL	*- FL
3	1		*REAR BUMPER TOWING COVER	Dented	14.70 FL	*14.70 FL
4	1		*REAR BUMPER UNDER COVER (BLACK)	Dented / Cut	552.60 FL	*552.60 FL
5	1		*ANTENNA, ELECTRICAL KEY	Serviceable	61.40 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	112.70 FL	*- FL
7	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	112.70 FL	*- FL
8	1		*REAR TAILGATE	Repair	1,547.27 FL	*- FL
9	1		*REAR TAILGATE OUTER GARNISH	Serviceable	910.40 FL	*- FL
10	1		*COVER, REAR COMBINATION LAMP, RH	Serviceable	54.70 FL	*- FL
11	1		*COVER, REAR COMBINATION LAMP, LH	Serviceable	54.70 FL	*- FL
12	1		*GARNISH, BACK DOOR SIDE, LH	Serviceable	93.60 FL	*- FL
13	1		*GARNISH, BACK DOOR SIDE, RH	Serviceable	93.60 FL	*- FL
14	1		*MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	Serviceable	55.40 FL	*- FL
15	1		*MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	Serviceable	55.40 FL	*- FL
16	1		*BOARD ASSY, BACK DOOR TRIM	Serviceable	254.40 FL	*- FL
17	1		*PANEL ASSY, BACK DOOR TRIM, UPPER	Serviceable	51.20 FL	*- FL
18	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	365.20 FL	*- FL
19	1		*PANEL SUB-ASSY, BODY LOWER BACK (REAR END PANEL)	Serviceable	641.50 FL	*- FL
20	1		*TAILLAMP LOWER RH	Serviceable	548.40 FL	*- FL
21	1		*TAILLAMP UPPER RH	Serviceable	557.90 FL	*- FL
22	1		*REAR BUMPER SIDE RH	Serviceable	232.00 FL	*- FL
23	1		*REAR BUMPER SIDE LH	Serviceable	232.00 FL	*- FL
24	1		*TAILLAMP LOWER LH	Serviceable	548.40 FL	*- FL
25	1		*TAILLAMP UPPER LH	Serviceable	557.90 FL	*- FL
26	1		*REAR RH FENDER PANEL	Repair	836.70 FL	*- FL
27	1		*REAR LH FENDER PANEL	Repair	836.70 FL	*- FL
28	1		*LINER, REAR WHEEL HOUSE, LH	Repair	138.10 FL	*- FL
29	1		*LINER, REAR WHEEL HOUSE, RH	Repair	138.10 FL	*- FL
30	1		*BOARD, BACK DOOR TRIM	Serviceable	220.70 FL	*- FL
31	1		*PANEL ASSY, DECK TRIM SIDE, RH	Serviceable	351.10 FL	*- FL
32	1		*PANEL ASSY, DECK TRIM SIDE, LH	Serviceable	351.10 FL	*- FL
33	1		*COVER, FLOOR UNDER, NO.1	Serviceable	172.60 FL	*- FL
34	1		*COVER, FLOOR UNDER, NO.2	Serviceable	238.70 FL	*- FL
35	1		*COVER, REAR FLOOR	Serviceable	226.80 FL	*- FL
36	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
37	1		*SET REAR BUMPER CLIP	Necessary	22.00 FS	*22.00 FS
38	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
39	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
40	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
41	1		*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.00 FS	*- FS
42	1		*REAR TAILGATE WORDING PRIUS	Not Necessary	52.90 FS	*- FS
43	1		*REAR TAILGATE WORDING HYBRID	Not Necessary	53.50 FS	*- FS
44	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
45	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
46	1		*REAR BUMPER PROTECTOR	Serviceable	100.00 FS	*- FS
47	1		*REAR WHEEL RIM	Serviceable	1,570.55 FS	*- FS
48	1		*REAR WHEEL RIM COVER	Serviceable	175.80 FS	*- FS
49	1		*SPARE WHEEL RIM	Serviceable	1,570.55 FS	*- FS
50	1		*SPARE WHEEL RIM COVER	Serviceable	175.80 FS	*- FS
51	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
52	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 16,974.17 589.30
- List Item Discount on L Items 25.00/25.00% (\$\$) 2,999.02 141.83

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (\$)	13,975.15	447.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	4,500.00	200.00
2	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
3	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	4,500.00	220.00
5	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	New	170.00	0.00
6	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	0.00
7	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
10	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	0.00
12	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
13	TO APPLY PAINT PROTECTION SYSTEM (PPPS) MAINTAIN AND ENHANCEMENT.	New	380.00	0.00
14	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
15	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
Gross Labour Cost (\$)			12,100.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >