

Trans-cab Auto Services Pte Ltd

AAD1907-253

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7608X

Not Notified

Recovery B4 paint

Vehicle No.:	SHB 7608X
Chassis No.:	JTDKB3FU503080098
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS
Date of Accident :	29.7.19
Third Party Insurer :	AIG
Date of Registration:	17/5/2019

PART		LIST	
1	1 REAR BUMPER	\$	SVC 458.60 TX
2	1 REAR BUMPER RE-INFORCEMENT	\$	SVC 318.80 TX
3	1 REAR BUMPER TOWING COVER	\$	<i>Re</i> 14.70 ✓
4	1 REAR BUMPER UNDER COVER (BLACK)	\$	<i>Re/ln</i> 552.60 ✓
5	1 ANTENNA, ELECTRICAL KEY	\$	<i>ln</i> 61.40
6	1 REAR BUMPER SIDE RETAINER LH	\$	<i>ln</i> 112.70
7	1 REAR BUMPER SIDE RETAINER RH	\$	<i>ln</i> 112.70
8	1 REAR TAILGATE	\$	<i>ln</i> 1,547.27
9	1 REAR TAILGATE OUTER GARNISH	\$	<i>ln</i> 910.40
10	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>ln</i> 54.70
11	1 COVER, REAR COMBINATION LAMP, LH	\$	<i>ln</i> 54.70
12	1 GARNISH, BACK DOOR SIDE, LH	\$	<i>ln</i> 93.60
13	1 GARNISH, BACK DOOR SIDE, RH	\$	<i>ln</i> 93.60
14	1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	<i>ln</i> 55.40
15	1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	<i>ln</i> 55.40
16	1 BOARD ASSY, BACK DOOR TRIM	\$	<i>ln</i> 254.40
17	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>ln</i> 51.20
18	1 REAR TAILGATE WEATHERSTRIP	\$	<i>ln</i> 365.20
19	1 PANEL SUB-ASSY, BODY LOWER BACK (REAR END PANEL)	\$	<i>ln</i> 641.50
20	1 TAILLAMP LOWER RH	\$	<i>ln</i> 548.40
21	1 TAILLAMP UPPER RH	\$	<i>ln</i> 557.90
22	1 REAR BUMPER SIDE RH	\$	SVC 232.00 TX
23	1 REAR BUMPER SIDE LH	\$	<i>ln</i> 232.00 X
24	1 TAILLAMP LOWER LH	\$	<i>ln</i> 548.40
25	1 TAILLAMP UPPER LH	\$	<i>ln</i> 557.90
26	1 REAR RH FENDER PANEL	\$	<i>ln</i> 836.70
27	1 REAR LH FENDER PANEL	\$	<i>ln</i> 836.70
28	1 LINER, REAR WHEEL HOUSE, LH	\$	<i>ln</i> 138.10
29	1 LINER, REAR WHEEL HOUSE, RH	\$	<i>ln</i> 138.10

Trans-cab Auto Services Pte Ltd

AAD1907-253

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7608X

30	1	BOARD, BACK DOOR TRIM	\$	Sm	220.70	}	X
31	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	Sm	351.10		
32	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	Sm	351.10		
33	1	COVER, FLOOR UNDER, NO.1	\$	Sm	172.60		
34	1	COVER, FLOOR UNDER, NO.2	\$	Sm	238.70		
35	1	COVER, REAR FLOOR	\$	Sm	226.80		
TOTAL			\$		11,996.07		
25%			\$		2,999.02		
			\$		8,997.05		

Special Nett

1	1SET	PARKING AID	\$	Sm	700.00	X	
2	1SET	REAR BUMPER CLIP	\$	nn	22.00	✓	
3	2	REAR WINDSCREEN SEALANT	\$	nn	80.00	}	X
4	1	WINDSCREEN MOULDING	\$	nn	100.00		
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00		
6	1	REAR TAILGATE TOYOTA LOGO	\$	nn	47.00		
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	nn	52.90		
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	nn	53.50		
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	nn	80.00		
10	1	REAR TAILGATE STICKER '6555-3333'	\$	nn	80.00		
11	1	REAR BUMPER PROTECTOR	\$	SVC	100.00	X	
12	1	REAR WHEEL RIM	\$	Sm	1,570.55	}	X
13	1	REAR WHEEL RIM COVER	\$	Sm	175.80		
14	1	SPARE WHEEL RIM	\$	Sm	1,570.55		
15	1	SPARE WHEEL RIM COVER	\$	Sm	175.80		
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00		
17	1SET	FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00		
TOTAL			\$		4,978.10		

TOTAL PARTS \$ 13,975.15

LABOUR

Panel Beating, Knocking And Straightening The Necessary
 Portion, Remove And Renewal Of Parts, Adjust And Realign
 The Same

\$ 4,500.00 *2001*

Trans-cab Auto Services Pte Ltd

AAD1907-253

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7608X

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn	170.00	X
Putty And Spray Painting Of The Affected Portion.	\$		4,500.00	22d
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	nn	170.00	X
To Rust-Proofing Of The Affected Areas.	\$	nn	170.00	X
To reinstall rear bumper parking sensor.	\$	nn	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$	nn	170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn	380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	nn	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00	X

Trans-cab Auto Services Pte Ltd

AAD1907-253

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7608X

TOTAL	\$	12,100.00
Over All Total	\$	26,075.15

(PART-BY-PART) Repair Days

~~15 Days~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: