

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9870R****AAD1907-257***Not Authorised*  
*11 Sep 2019*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model: 30 JUL 2019  
Date of Accident :  
Third Party Insurer :  
Date of Registration :

**SHB 9870R**

VF1ABL15AUC273310

RENAULT

LATITUDE

29.7.19

**AIG**

30/8/2013

|    |   | PART                             |    |    | LIST       |
|----|---|----------------------------------|----|----|------------|
| 1  | 1 | BUMPER COVER REAR                | \$ | Bu | 1,108.46 ✓ |
| 2  | 1 | BUMPER LOWER REAR                | \$ | nd | 768.84 ✓   |
| 3  | 1 | BUMPER BRACKET CTR REAR          | \$ | SL | 113.47 X   |
| 4  | 1 | BUMPER BRACKET SIDE RH REAR      | \$ | SL | 135.97 X   |
| 5  | 1 | BUMPER RETAINER RH REAR          | \$ | SL | 44.99 <    |
| 6  | 1 | BUMPER REFLECTOR RH              | \$ | SL | 43.61 X    |
| 7  | 1 | BUMPER BRACKET SIDE LH REAR      | \$ | SL | 135.97 X   |
| 8  | 1 | BUMPER RETAINER LH REAR          | \$ | SL | 44.99 X    |
| 9  | 1 | BUMPER REFLECTOR LH              | \$ | CM | 43.61 ✓    |
| 10 | 1 | BUMPER BEAM REAR                 | \$ | n  | 777.52     |
| 11 | 1 | BUMPER BEAM BRACKET LH REAR      | \$ | n  | 225.95     |
| 12 | 1 | BUMPER BEAM BRACKET RH REAR      | \$ | n  | 225.95     |
| 13 | 1 | OUTER PANEL REAR (End Panel)     | \$ | n  | 1,471.77   |
| 14 | 1 | OUTER PANEL REAR (End Panel)TRIM | \$ | SL | 404.56     |
| 15 | 1 | TAILLAMP RH                      | \$ | SL | 552.55     |
| 16 | 1 | TAILLAMP PANEL RH                | \$ | n  | 986.70     |
| 17 | 1 | TAILLAMP LH                      | \$ | SL | 552.55     |
| 18 | 1 | TAILLAMP PANEL LH                | \$ | n  | 986.70     |
| 19 | 1 | BOOT REAR                        | \$ | n  | 2,872.68   |
| 20 | 1 | BOOT FINISHER                    | \$ | SL | 470.06     |
| 21 | 1 | BOOT WHEATERSTRIP                | \$ | SL | 323.05     |
| 22 | 1 | BOOT REFLECTOR LAMP LH           | \$ | SL | 493.35     |
| 23 | 1 | BOOT REFLECTOR LAMP RH           | \$ | SL | 493.35     |
| 24 | 1 | BOOT BADGE 'RENAULT'             | \$ | na | 225.36     |
| 25 | 1 | BOOT BADGE                       | \$ | na | 225.36     |
| 26 | 1 | BOOT STRUT LH                    | \$ | SL | 276.08     |
| 27 | 1 | BOOT STRUT RH                    | \$ | SL | 276.08     |
| 28 | 1 | BOOT HINGE LH                    | \$ | n  | 367.84     |
| 29 | 1 | BOOT HINGE RH                    | \$ | n  | 367.84     |

**Trans-cab Auto Services Pte Ltd**

AAD1907-257

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9870R

|              |   |                  |    |    |                  |     |
|--------------|---|------------------|----|----|------------------|-----|
| 30           | 1 | BOOT INNER TRIM  | \$ | Sm | 586.45           | } X |
| 31           | 1 | BOOT SWITCH      | \$ | Sm | 168.13           |     |
| 32           | 1 | BOOT LOCK        | \$ | na | 202.67           |     |
| 33           | 1 | BOOT LOCK CATCH  | \$ | na | 74.40            |     |
| 34           | 1 | EXHAUST REAR     | \$ | na | 7,489.05         |     |
| 35           | 1 | EXHAUST CAP REAR | \$ | na | 230.49           |     |
| <b>TOTAL</b> |   |                  | \$ |    | <b>23,766.42</b> |     |
| <b>10%</b>   |   |                  | \$ |    | <b>2,376.64</b>  |     |
|              |   |                  | \$ |    | <b>21,389.78</b> |     |

**Special Nett**

|       |      |                                   |    |       |          |        |   |
|-------|------|-----------------------------------|----|-------|----------|--------|---|
| 1     | 1SET | PARKING AID                       | \$ | Short | 700.00   | 400.00 |   |
| 2     | 1SET | REAR BUMPER CLIP                  | \$ | na    | 66.00    | —      |   |
| 3     | 1SET | BUMPER BRACKET CTR CLIP           | \$ | na    | 33.00    | —      |   |
| 4     | 1SET | BUMPER BRACKET SIDE CLIP RH RR    | \$ | na    | 10.00    | X      |   |
| 5     | 1SET | BUMPER RETAINER RH CLIP RR        | \$ | na    | 20.00    | X      |   |
| 6     | 1SET | BUMPER BRACKET SIDE CLIP LH RR    | \$ | na    | 10.00    | X      |   |
| 7     | 1SET | BUMPER RETAINER CLIP LH RR        | \$ | na    | 20.00    | X      |   |
| 8     | 1SET | BUMPER LOWER REAR RIVET           | \$ | na    | 22.00    | X      |   |
| 9     | 1SET | BUMPER LOWER REAR CLIP            | \$ | na    | 66.00    | —      |   |
| 10    | 1    | BOOT STICKER "Trans-cab"          | \$ | na    | 30.00    | }      | X |
| 11    | 1    | BOOT STICKER "6555-3333"          | \$ | na    | 30.00    |        |   |
| 12    | 1    | EXHAUST MOUNTING REAR             | \$ | Sm    | 17.82    |        |   |
| 13    | 2    | REAR WINDSCREEN SEALANT           | \$ | na    | 80.00    |        |   |
| 14    | 1    | WINDSCREEN MOULDING               | \$ | na    | 100.00   |        |   |
| 15    | 1    | REAR WINDSCREEN INNER SPONGE SEAL | \$ | na    | 100.00   |        |   |
| 16    | 1    | BOOT INNER TRIM CLIP              | \$ | na    | 45.00    |        |   |
| 17    | 1SET | BOOT FINISHER CLIP                | \$ | na    | 24.20    |        |   |
| 18    | 1    | TAILLAMP CLIP LH                  | \$ | na    | 5.00     |        |   |
| 19    | 1    | TAILLAMP CLIP RH                  | \$ | na    | 5.00     |        |   |
| TOTAL |      |                                   | \$ |       | 1,384.02 |        |   |

**TOTAL PARTS \$ 22,773.80****LABOUR**

To remove and refit interior fittings, trimings, garnish,  
fittings and other, to enable repair.

\$ na 380.00 X

**Trans-cab Auto Services Pte Ltd****AAD1907-257**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9870R**

|                                                                                                                           |    |              |
|---------------------------------------------------------------------------------------------------------------------------|----|--------------|
| To transfer of bootlid fittings, attachments and perform water seepage test.                                              | \$ | nn 170.00 X  |
| To Check Electrical Lighting Concerned.                                                                                   | \$ | 170.00 151   |
| To Rust-Proofing Of The Affected Areas.                                                                                   | \$ | nn 170.00 X  |
| To transfer of tire, rim and on wheel balancing.                                                                          | \$ | nn 170.00 X  |
| To reinstall rear bumper parking sensor.                                                                                  | \$ | 170.00 61    |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 4,500.00 201 |
| Putty And Spray Painting Of The Affected Portion.                                                                         | \$ | 4,500.00 221 |
| To repair and realign rear exhaust pipe.                                                                                  | \$ | nn 170.00 X  |
| To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.                                      | \$ | 170.00 X     |
| To transfer of rear end panel fittings, attachment and perform water seepage test.                                        | \$ | 170.00 X     |
| To transfer of rear windscreen fittings and conduct water seepage test.                                                   | \$ | 170.00 X     |
| To check steering geometry and computer wheel alignment                                                                   | \$ | 170.00 X     |
| To transfer of rear bumper fittings, attachment and perform water seepage test.                                           | \$ | 380.00 X     |

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from LKK Auto Consultants

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

**TOTAL \$ 11,890.00****Over All Total \$ 34,663.80****LUMP SUM ( REPAIR DAY)****15 DAYS****2 days**

Acknowledged by Repairer

Signature:

Date: