

Case Summary Form (CSF).

Report No.J/20190716/2068

Case Sensitivity

No

Officer-in-Charge of Case

J / Bukit Panjang N.P.C /

KOH HONG CHIN, STANLEY

Contact No.

68929999

Classification of Case

-I) NO OFFENCE DISCLOSED

61V917

Il SERGERANT (>) NO WEE CHEW





1 of 4

Report No. J/20190712/2119

#### POLICE REPORT (NP299)

Police Station Of Origin Bukit Panjang N.P.C 1 Segar Road #01-05 SINGAPORE 677738 Tel No: 1800-8929999

Date/Time Report Made 12/07/2019 22:20	Vide Report No.		Station Diary No 143		
Name Of Informant	Address	Address			
ARUN S/O PRABHAKAR V CLEETUS	APT BLK 517 JELAPANG ROAD #06-183 SING 670517			-183 SINGAPORE	
ID Type / ID No. NRIC NO / \$9634820G	Contact No. Home/Office Mobile 86126903				
Nationality SINGAPORE CITIZEN	Email Address				
Occupation	Sex	Age	Date of Birth	Race	
FINANCIAL CONSULTANT	Male	22	03/10/1996	Indian	
Institution/School Name	Langua	ge		1800	
Date/Time Of Incident 12/07/2019 18:35	Location Of Incident 1 RAFFLES PLACE ONE RAFFLES PLACE SINGAPORE 048616 Outside One Raffles Place Mail, at the benches area				

#### Brief details.

On 12/07/2019 at about 1835hrs, I was outside One Raffles Place Mall and was sitting on the bench talking to my client. My client was sitting on my left and therefore I shifted my body to the left to talk to her. Before that, I placed my clutch bag on the bench on my right and it was in close proximity with me. However, the bag was not leaning on my lap or whatsoever. At about 1845hrs, I then turn to my right and saw that my bag was stolen. I then called my sister for help. We then checked the 'Find My IPhone' App

Signature Of Officer Recording The Report: / /	Signature Of Informant:
J / Sgt 2 NUR HAKIM BIN LOQMAN	A'
Signature Of Interpreter: Not applicable	Date/Time: 12/07/2019 22:20
Officer In-Charge Of Case: J / Bukit Panjang N.P.C / Staff Sgt KOH HONG CHIN, STANLEY Contact No.: 68929999	Classification Of Case:

Authentication Stamp





2 of 4

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20190712/2119

however it was not detecting as the phone had been switched off. At about 1920hrs, I then saw that the phone had been switched on and the estimated location was at Pasir Ris. I then quickly called my phone and a Chinese lady answered the phone. She then informed me that my bag had been left unattended inside the mrt and was placed on the seat opposite her. I then told her to hold on to my bag while I travel to meet her. At about 2110hrs, I met the lady and she further explained that she did not know the person that placed my bag on the seat. She also added that there was not a lot of people in the MRT at that point of time. Upon checking my bag, I then realized that my wallet had been stolen. However, the rest of the items inside the bag was intact.

I do not have any suspect in mind and there are CCTVs at the One Raffles Place Mall. This is the first time that this has happen to me.

Prop	erty Information				.0.		
S/N	Item	Туре	Brand/ Account/ Property/ Security- Type	Serial No./ IMEI/ Acct No.	Quantity	Value	Description
1	General property	Stolen			1		One Black Picard Wallet
2	Credit Card / Debit Card/ ATM Card	Stolen	DBS BANK LTD		1		One DBS Safra Card

Signature Of Officer Recording The Report:	Signature Of Informant:
J / Sgt 2 NUR HAKIM BIN LOQMAN	de
Signature Of Interpreter: Not applicable	Date/Time: 12/07/2019 22:20
Officer In-Charge Of Case: J / Bukit Panjang N.P.C / Staff Sgt KOH HONG CHIN, STANLEY Contact No.: 68929999	Classification Of Case:
Authentication Stamp	





POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20190712/2119

3	Credit Card / Debit Card/ ATM Card	Stolen	POSB		1		One POSB PassionCard
4	Identity Card	Stolen	SINGAP ORE NRIC	S963482 0G	1		One IC bearing number S9634820G
5	Licence	Stolen	Qualified Driving Licence		1		One Drivers License
6	Credit Card / Debit Card/ ATM Card	Stolen	OCBC LTD		1		One OCBC Frank card
7	Cash	Stolen			1	Singapor e Dollars 50.00	One \$50 SG50 note
8	Cash	Stolen			1	Singapor e Dollars 10.00	One \$10 SG50 note
9	Cash	Stolen			1	Australian Dollars 5.00	One Australia \$5 note
10	Cash	Stolen			1	Malaysia n Ringgit 250.00	Cash amouting to \$250 with unknown denominations

Signature Of Officer Recording The Report: / /	Signature Of Informant:
J / Sgt 2 NUR HAKIM BIN LOQMAN	do
Signature Of Interpreter: Not applicable	Date/Time: 12/07/2019 22:20
Officer In-Charge Of Case: J / Bukit Panjang N.P.C / Staff Sgt KOH HONG CHIN, STANLEY Contact No.: 68929999	Classification Of Case;

Authentication Stamp





POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20190712/2119

11	Identity Card	Stolen	SAF 11B	S963482	1	One 11B
				0G		bearing IC
						number
						S9634820G

Signature Of Officer Recording The Report:

J / Sgt 2 NUR HAKIM BIN LOQMAN

Signature Of Interpreter: Not applicable

Officer In-Charge Of Case: J / Bukit Panjang N.P.C / Staff Sgt KOH HONG CHIN, STANLEY Contact No.: 68929999

Signature Of Informant:

Date/Time: 12/07/2019 22:20

Classification Of Case:

Authentication Stamp

**Accident Photo** 





# *KAIZENMOTORS*

68 Kaki Bukit Avenue 6, #02-12 Ark@KB, Singapore 417896

UEN: 201502816H

GST Reg No. 201502816H Fax: (+65) 6384 1957

Tel: (+65) 6384 1956 Webpage: https://www.kaizenmotors.com.sg



kaizenmotorsingapore



kaizen\_motors



kaizenmotors

Date: 29/07/2019

Vehicle No : SJQ277K Model: Toyota Allion

Mileage:

Requesting for List Price

No	Job Description	Qty	Pri	ce / Unit	A	mount
1	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS, INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSMENT OF		\$	600.00	\$	600.00
8	REAR L/H DOOR ASSY & REAR L/H FENDER SPRAYPAINTING & PUTTY OF REAR L/H DOOR ASSY & REAR L/H FENDER		\$	600.00	\$	600.00

Not Abul Line 5/8/19 The she Athrey-2 Ly. 9/2 8480/.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Plants prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub-Total	\$ 1,200.00
GST 7%	\$ 84.00
Grand Total	\$ 1,284.00

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case I	Votified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Auth'ed				
	30 Jul 2019		01 Aug 2019 10:23 Edit Adj Rpt	S\$480.00 Edit Estimates	S\$480. View R	CONTRACTOR CO.		Pending for Survey Report Cancel Case			
М	ain	Re	ference	Cla	im Details		Documen	ts	Show All		
CLAIM SUB	FOLDER DI	ETAILS				[Created	by insurer]				
Insured:	-, Co. Re	g. No.: -									
Main Claimant:	KINETIC	HOLDING PTE L	r <b>D</b> , Co. Reg. N	o.: 201618392	N						
Vehicle Reg. No.:	SJQ277	K			Date of Loss:	25/07/20: [ <b>123</b> Mon	19 22:00 - :59 ths and <b>4</b> Days F	rom LTA Reg Date	(Man Yr)]		
Claim Type:	TP / SN	M19D203515C0	)2		Policy/Cover Note No.:	DMPCSN19225619000					
Vehicle Reg. No. (Insured):	SKB617E				Policy No. (Claimant):	999994105					
(Insured).					Excess:	S\$1,100.00					
Repairer:	Kaizen M	otors Pte Ltd (H	Q) 68 KAKI BUK	IT AVE 6, #02-	12 ARK @ KA	KI BUKIT, 4	17896 Kaki Bukit	- Tel:			
Handling Insurer:	China Ta	iping Insurance	(Singapore) Pt	e. Ltd. (HQ) -	Tel: 6389 611	11 [Hand	led by Tan Kah I	<b>Leong</b> - 63896193	1		
Claimant's Insurer:		Pacific Insuranc						<b>5</b> • 1 • 14/00	(2010]		
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	: 6256-3561	[Handled by	MARCUS C	HUA] [Final	<b>kpt</b> due 14/08	/2019]		
ASSOCIAT	ED MAIL RI	ECEIVED						View All Compo	se Case Mai		
There are no	mail for this	s case.									
ALL ASSO	CIATED TA	sks⊟				View All	Search Tasks	Create New Task	Complet		
Due Date	Priority	Type Task	Group Sub	ject Handl	er Assigi	ned By	Completed Or	Created O	n Done		

#### **Claim Documents**

\*SJQ277K (SNM19D203515C02) [SKB617E] TP KINETIC HOLDING PTE LTD Jul 25 2019 10:00PM [-] Kaizen Motors Pte Ltd

Up	oad Documents Uplo	ad Photos Compose New Letter	View	View in Brow	ser ▼
Pho	tos/Images		3 per pe	age 🔻	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/08/19 08:47	General View	0	Load JPG	•
2	16/08/19 08:47	General View	0	Load JPG	•
3	16/08/19 08:47	General View	0	Load JPG	•
4	16/08/19 08:47	General View	0	Load JPG	•
5	16/08/19 08:47	General View	0	Load JPG	•
6	16/08/19 08:47	General View	0	Load JPG	€
7	16/08/19 08:47	General View	0	Load JPG	•
8	16/08/19 08:47	General View	0	Load JPG	
9	16/08/19 08:47	General View	0	Load JPG	•
10	16/08/19 08:47	General View	0	Load JPG	•
11	16/08/19 08:47	General View	0	Load JPG	
12	16/08/19 08:47	General View	0	Load JPG	•
13	16/08/19 08:47	General View	0	Load JPG	
14	16/08/19 08:47	General View	0	Load JPG	
15	16/08/19 08:47	General View	0	Load JPG	
16	16/08/19 08:47	General View	0	Load JPG	
17	16/08/19 08:47	General View	0	Load JPG	
18	16/08/19 08:47	General View	0	Load JPG	•
19	16/08/19 08:47	General View	0	Load JPG	•
20	16/08/19 08:47	General View	0	Load JPG	
21	16/08/19 08:48	Reinspection Photo	0	Load JPG	
22	16/08/19 08:48	Reinspection Photo	0	Load JPG	•
23	16/08/19 08:48	Reinspection Photo	0	Load JPG	~

# **Linked Accident Report Documents**

		View View in Br	
essment Reports		1 per page	v 🕜
Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumi	onail Prin
26/07/19 17:05	Accident Statement	1 Load	HTM
Photos/Images		3 per page	<b>T</b>
tos/Images		3 per page	¥ Ø
Finalized On	SME Motor Pte Ltd (Kaki Bukit)		onail Prin
26/07/19 17:05	Accident Photo	1 Load	JPG 🗹
26/07/19 17:05	Accident Photo	① Load	JPG 🗹
26/07/19 17:05	Accident Photo	1 Load	JPG 🗹
	Finalized On 26/07/19 17:05 tos/Images Finalized On 26/07/19 17:05 26/07/19 17:05	26/07/19 17:05 Accident Statement  tos/Images  Finalized On SME Motor Pte Ltd (Kaki Bukit)  26/07/19 17:05 Accident Photo  26/07/19 17:05 Accident Photo	Finalized On   SME Motor Pte Ltd (Kaki Bukit)   Thumb

Assessment Reports			1 per page	
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbna	il Print
4	26/07/19 17:05	Accident Photo	1 Load JPG	•
5	26/07/19 17:05	Accident Photo	<b>⑥</b> Load JPG	
6	26/07/19 17:05	Accident Photo	1 Load JPG	
7	26/07/19 17:05	Accident Photo	<b>1</b> Load JPG	
Doc	cumentation		1 per page	
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbna	il Print
1	26/07/19 17:03	Sketch Plan	1 Load TIF	
2	26/07/19 17:03	Sketch Plan #2	<b>₫</b> Load TIF	
3	26/07/19 17:03	Sketch Plan #3	Load TIF	
4	26/07/19 17:03	Sketch Plan #4	1 Load TIF	
5	26/07/19 17:03	Sketch Plan #5	■ Load TIF	
6	26/07/19 17:03	Sketch Plan #6	● Load TIF	
7	26/07/19 17:03	Accident Sketch Plan	① Load TIF	
8	26/07/19 17:03	Accident Sketch Plan	1 Load TIF	
9	26/07/19 17:03	Accident Sketch Plan	1 Load TI	
10	26/07/19 17:03	Accident Sketch Plan	€ Load TI	
11	26/07/19 17:03	Accident Sketch Plan	● Load TI	
12	26/07/19 17:03	Accident Sketch Plan	● Load TII	
13	26/07/19 17:03	Accident Sketch Plan	1 Load TII	

# **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.	

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

Our File No:

DMPCSN19225619000

CS/CTI19013444/UYD3S2

Date:

SKB617E

TP

20/08/2019

REFERENCE

Date of Loss:

Handling Insurer: Claimant Vehicle

China Taiping Insurance (Singapore) Pte.

Ltd.

SJQ277K

25/07/2019

Policy No:

Insured Vehicle

No:

Nature of Claim:

Claim No:

SNM19D203515C02

1NZD313945

340303 km

NZT2603039239

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

No:

SJQ277K

Make & Model: Reg. Date:

TOYOTA ALLION, 1.5 (A) 21/04/2009 (Man. Year: 2008)

Black

Colour: Engine Capacity:

1496 cc N/A

Market Value/New Car Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Footbrake (Serviceable): Pre-accident Condition:

Engine No:

Odometer:

Chassis No:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Yes

Engine Modification:

195/65R15

Front Tyre Size: Front Left Side:

West Lake 6 mm

195/65R15

Rear Tyre Size:

West Lake 6 mm

Front Right Side:

West Lake 6 mm

Rear Left Side: Rear Right Side:

West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	480.00	720.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,200.00	480.00	720.00	60.00
+ GST 7.00/7.00% (S\$)	84.00	33.60	50.40	60.00
Nett Amount (S\$)	1,284.00	513.60	770,40	60.00

INSPECTION

Date of Assignment:

01/08/2019

Date Inspected:

05/08/2019 Inspected At:

Kaizen Motors Pte Ltd (HQ)

68 KAKI BUKIT AVE 6, #02-12 ARK @ KAKI BUKIT

Singapore 417896

Estimated Period of Repair:

2.0 days

MARCUS CHUA Adjuster:

Manager:

YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\_printrpt&caseid=851038&extid=312095&CFID=57784084&C... 1/4

# REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 20 Aug 2019) Part Source: MRM-SG

TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0) 143 Parts:

(Price-denominated Standard List) Repairer's Labour:

Print Code: (Unsubmitted, no print-code for SJQ277K)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the Validity:

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended	ahour
Recommended	I AURUII

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS. INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSTMENT OF REAR L/H DOOR ASS' & REAR L/H FENDER. }	New	600.00	480.00
2	SPRAY PAINTING & PUTTY OF REAR L/H DOOR ASSY & REAR L/H FENDER. }	New	600.00	0.00
	Gross Labo	ur Cost (S\$)	1,200.00	480.00
_	Report was unsubmitted during this p	print-out		

< END OF ESTIMATES >