

ASS. REC. BY:

REF:

CS/C1119013453/Ttd302

Special Instruction:

Surveyor: tanjit hASSIGNMENT (Office)From (Person): Chong Boon Sen

of

C11Date/Time: 31/7/19 @ 3.46pm

Estimated Cost:

Bill to:

OD - ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDB 980M

Insured:

CBH 370SP

at Workshop m/s

Trans Eurokars

Tel:

6331 0684

of

27A Tanjong Penjuru

Policy No:

Claim No:

SNM19D203558

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/7/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

5.04pm @ 31/7/19

Person Contacted:

VionVehicle IN (OUT)

Date/Time	Action/Instruction
	<u>SDB 980M - x</u>
	<u>CBH 370SP - 03/C1119012669/Klea3</u>
	<u>Don: 16/7/19</u>

ASS. REC. BY:

Tanjil

REF: CFI

ASSIGNMENT

From:

Date:

5/8/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SDB 980 M

at Workshop m/s

TransEurokars

of

27A Tanjung Penjur

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

After 2pm (vion)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

995K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{cap}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SDB 980 M

Yr Regn:

2018 / Dec.

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 6

C.C

1998

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

7742

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM 664072 K03 08634

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R17

R:

22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6

mm

L/Bal.

6 mm

L/Bal.

6

mm

D.O.A.

D.O.I.

Survey held at

TransEurokars

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/8

14/16/11 11 days email to Catherine.
 (Red: 10320.29; 43%)

Date/Time, File Pass to?



: Preli. Report

1) 30/8 Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 11

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format:

TP

Lump Sum / 10% / 10%

14/16/11

200

200

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 31 July 2019 3:46 PM
To: vion.lim@eurokars.com.sg
Cc: assignments
Subject: RE: OUR REF: SNM19D203558-GBH3705P-CBS - FW: Accident on 29/7/19 involving SDB980M & GBH3705P

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: vion.lim@eurokars.com.sg [mailto:vion.lim@eurokars.com.sg]
Sent: Wednesday, 31 July, 2019 3:39 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D203558-GBH3705P-CBS - FW: Accident on 29/7/19 involving SDB980M & GBH3705P

Dear Boon Seng,

We would like to request for Marcus Chua to conduct the pre-repair inspection survey. Please assist to arrange.
Thank you.

Best Regards.

 **EUROKARS GROUP**

Vion Lim

Insurance Claims Officer

EUROKARS SERVICES PTE LTD

27A Tanjong Penjuru, Singapore 609042
D: (65) 6331 0684 H: (65) 9111 7463
E: vion.lim@eurokars.com.sg

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: 31 July 2019 1:50 PM

To: Vion Lim <vion.lim@eurokars.com.sg>

Subject: RE: OUR REF: SNM19D203558-GBH3705P-CBS - FW: Accident on 29/7/19 involving SDB980M & GBH3705P

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: vion.lim@eurokars.com.sg [<mailto:vion.lim@eurokars.com.sg>]

Sent: Wednesday, 31 July, 2019 1:46 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: FW: OUR REF: SNM19D203558-GBH3705P-CBS - FW: Accident on 29/7/19 involving SDB980M & GBH3705P

Importance: High

Dear Boon Sen,

Please assist to revert the liability and the surveyor to conduct the survey.

We are trying to arrange the whole process at one go instead of booking appointment timing for the survey. Appreciate your assistance on the matter. Thank you.

Best Regards.



Vion Lim

Insurance Claims Officer

EUROKARS SERVICES PTE LTD

27A Tanjong Penjuru, Singapore 609042

D: (65) 6331 0684 H: (65) 9111 7463

E: vion.lim@eurokars.com.sg

Website: www.eurokars.com.sg

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Sent: 31 July 2019 1:22 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Vion Lim <vion.lim@eurokars.com.sg>

Subject: OUR REF: SNM19D203558-GBH3705P-CBS - FW: Accident on 29/7/19 involving SDB980M & GBH3705P

Importance: High

Dear Boon Sen,

Please conduct PRS for SDB980M.

Note: officer in charge – Boon Sen 63896171.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T : (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: vion.lim@eurokars.com.sg [<mailto:vion.lim@eurokars.com.sg>]

Sent: Tuesday, 30 July, 2019 8:23 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: samuel.ng@eurokars.com.sg; ronald.yap@eurokars.com.sg; tommywoon@eurokars.com.sg

Subject: Accident on 29/7/19 involving SDB980M & GBH3705P

Importance: High

Dear Sir / Mdm,

Your Ref: GBH3705P

Please assist to arrange survey & revert the liability for the above case urgently.
Thank you.

Best Regards,



Vion Lim

Insurance Claims Officer

EUROKARS SERVICES PTE LTD

27A Tanjong Penjuru, Singapore 609042

D: (65) 6331 0684 H: (65) 9111 7463

E: vion.lim@eurokars.com.sg

Website: www.eurokars.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Denise Tay (LKKAUTO)

From: Taufikh (LKKAUTO)
Sent: Thursday, 29 August 2019 12:44 PM
To: catherinechua@eurokars.com.sg
Cc: CS A Team; Admin A; vion.lim@eurokars.com.sg; Denise Tay (LKKAUTO)
Subject: RE: SDB980M - FINALIZATION OF COR

Hi Catherine,

COR \$14,161.11 , 11 days.

Regards
Taufikh
Lkk Auto

From: catherinechua@eurokars.com.sg [mailto:catherinechua@eurokars.com.sg]
Sent: Tuesday, 27 August 2019 10:15 AM
To: taufikh@lkkauto.com
Cc: cs-a@lkkauto.com; admin-a@lkkauto.com; vion.lim@eurokars.com.sg
Subject: SDB980M - FINALIZATION OF COR

Dear Taufikh

Our COR computation with B4 paint photos is attached for your agreement.
COR: \$14161.11 before GST
11 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Kindly confirm the above as soon as possible.

Thanks n Regards

 **EUROKARS GROUP**
Driving luxury experiences since 1985
Catherine Chua
Insurance Claims Executive
23 Leng Kee Road Singapore 159095
T: (65) 6603 6128 D: (65) 6603 6121 F: (65) 6476 7417
E: catherinechua@mazda.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanone@mazda.com.sg <mazdacanone@mazda.com.sg>
Sent: 27 August 2019 9:09 AM
To: Catherine Chua <catherinechua@eurokars.com.sg>
Subject: Attached Image

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	008B
Vehicle Details	
Vehicle No.:	SDB980M
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Aug 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 SEDAN 2.0 AT STANDARD 2WD
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	PE21229855
Chassis No.:	JM6GL1072K0308634
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$18,573.00
Original Registration Date:	28 Dec 2018
First Registration Date:	28 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$18,573.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2028
PARF Rebate Amount:	\$13,929.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$32,552.00
COE Rebate Amount:	\$29,390.00
Total Rebate Amount:	\$43,319.00

The information contained herein is correct as at 06 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/07/2019 09:53
Date Of Accident	29/07/2019 19:30
Exact Location Of Accident	TAMPINES AVE 5 NEAR PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDB980M
Insured/Policyholder	
Name Of Registered Owner	CHAN MUN FAI FREDERICK
NRIC No	S1728008B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91882298
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MAZDA
Model	6-2.0 4-DOOR SEDAN (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900005531
Cover Note Number	

Driver

Name of Driver	CHAN MUN FAI FREDERICK
NRIC No	S1728008B
Date Of Birth	17/10/1965
Occupation	INDOOR
Date Of Driving Pass	23/08/1994
Driving Experience	24 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91882298
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	NOEMAIL

Address	107 LORONG H TELOK KURAU
Postcode	426132
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH3705P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLK2449B
-----------------------------	----------



Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE NO: SDB980M

ACCIDENT DATE: 29 Jan 2019

CONTACT NUMBER: 91882298

ACCIDENT TIME: ~ 7.30 pm

EMAIL:

LOCATION: Tampine Ave 5 near entrance to PIE (toward CGH)

Driving along Tampine Ave 5 (towards CGH direction) intending to enter PIE. However there was a taxi SHD 201X parked at side of the road near to the PIE entrance. Unable to filter out in time, I stopped my car behind the taxi. As I stopped, I was hit from behind by minivan GBH 3705P. The minivan was hit by BMW car SLK2449B.

Police was informed and 3 officers came onsite.

After the police collected all the details, we were told to ~~go~~ go off and report the accident within 24hr.

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIMS UNDER YOUR OWN POLICY.

PLEASE CHECK YOUR POLICY FOR MORE INFORMATION

PLEASE STATE: ☐ CLAIM OWN POLICY ☐ CLAIM THIRD PARTY ☐ REPORTING ONLY

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Wans Eurokars Pte Ltd
5 Wans Close
Singapore 498605
Tel: 6479 4003 / 6749 4333
Fax: 6479 4003
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Chan Mun Fai Frederick ADDRESS: 107 Lorong H Telok Kurau Singapore 426132 TEL: 91882298		WIP: 59118 EXCESS: DATE: 30-Jul-19	
VEH NO:	SDB980M	DATE IN:		CONTACT PERSON:	Vion 63957877
CHASSIS NO:	JM6GL1072K0308634	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA6	DATE REG.:	28-Dec-18	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	REAR BUMPER	1	MGSK1-50-221ABB	✓	\$ 1,099.00
2	BRACKET CENTER	1	MKD53-50-251	✓	\$ 5.40
3	COVER UNDER, REAR BUMPER	1	MGSH7-50-C51	✓	\$ 128.50
4	TOWING COVER LHS	1	MGSH7-50-EL1 BB	✓	\$ 46.60
5	TOWING COVER RHS	1	MGSH7-50-EK1 BB	✓	\$ 46.60
6	REAR REINFORCEMENT	1	MGHK1-50-260	✓	\$ 538.30
7	GROMMET, REAR BUMPER	2	M9991-00-501	✓	\$ 6.00
8	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	✓	\$ 10.80
9	RIVET, REAR BUMPER	2	MTK21-50-355	✓	\$ 18.40
10	RIVET, REAR BUMPER	6	MEA01-50-037	✓	\$ 48.00
11	FASTENER, REAR BUMPER	6	MB45A-56-146A	✓	\$ 18.00
12	RUBBER SEAL, REAR BUMPER	2	MGSH7-50-2G1	✓	\$ 27.40
13	CLIP, REAR BUMPER	4	MC274-50-133	✓	\$ 14.80
14	RETAINER CENTER, SENSOR	1	MKD45-67-UC5AE4	✓	\$ 31.00
15	SENSOR CENTER, ULTRASONIC	1	MGMK6-67-UC1 E4	✓	\$ 361.80
16	TAPE PROTECTOR, SENSOR	4	MBCKA-50-EM1	✓	\$ 18.80
17	CORD SHORT, SENSOR	1	MGBF5-67-290	✓	\$ 192.90
18	REAR END PANEL - photo	1	MGHY1-70-75Z	✓	\$ 700.10
19	TRIM, END PANEL	1	MGRF5-68-89X	✓	\$ 157.00
20	BEZEL, LOCK	1	MGHK1-68-894	✓	\$ 11.40
21	FASTENER, TRIM	10	MGJ21-68-885B02	✓	\$ 30.00
22	SPONGE LHS, FLOOR PANEL	1	MGHK3-68-8F0A	✓	\$ 260.40
23	SPONGE RHS, FLOOR PANEL	1	MGHK3-68-8E0A	✓	\$ 156.90
24	SPARE WHEEL BOARD	1	MGMD9-68-81XA	✓	\$ 540.70
25	BOOTLID	1	MGBY2-52-61X	✓	\$ 953.30
26	HINGE LHS, BOOTLID	1	MGBFN-52-720	✓	\$ 230.50
27	HINGE RHS, BOOTLID	1	MGBFN-52-710	✓	\$ 230.50
28	WEATHERSTRIP, BOOTLID	1	MGBFN-56-951	✓	\$ 120.60
29	LOCK, BOOTLID	1	MGHK1-56-820A	✓	\$ 160.70
30	STRIKER, BOOTLID	1	MGG2A-56-840	✓	\$ 35.10

31	SWITCH, OPENER	1	MGHK1-56-8D0	X	MM	\$ 124.80
32	CHROME FINISHER, BOOTLID	1	MGBEF-50-85ZA	✓	CRG	\$ 360.20
33	COVER LOWER, FINISHER	1	MGBEF-50-858	✓	? mig	\$ 47.10
34	PIN LOCATOR, CHROME FINISHER	1	MBHN9-50-1K5	✓	NEI	\$ 2.90
35	GROMMET, FINISHER	1	MBHN9-50-ES1	✓	NE	\$ 2.90
36	FASTENER, FINISHER	2	MBHN9-50-EA1	✓	NE	\$ 5.80
37	ORNAMENT, MAZDA	1	MGBEF-51-711	✓	NEI	\$ 25.60
38	ORNAMENT, 6	1	MGBEF-51-721	✓	NE	\$ 15.50
39	MASCOT, REAR	1	MGBEF-51-730A	✓	NEI	\$ 41.60
40	ORNAMENT, SKYACTIVE	1	MGBFN-51-771	✓	NE	\$ 66.70
41	GROMMET, BOOTLID	2	MGA7B-51-146	✓	NE	\$ 6.60
42	FASTENER, BOOTLID	2	MEG21-51-146	✓	NEI	\$ 12.40
43	LAMP LHS, BOOTLID	1	MGRF5-51-3G0B	✓	CRG	\$ 768.90
44	LAMP RHS, BOOTLID	1	MGRF5-51-3F0B	✓	X	\$ 768.90
45	TAILLAMP LHS	1	MGSJ4-51-160B	✓	X	\$ 1,672.70
46	TAILLAMP RHS	1	MGSJ4-51-150B	✓	X	\$ 1,672.70
47	FASTENER, TAILLAMP	2	MKD53-51-146B	✓	X	\$ 8.20
48	FASTENER, TAILLAMP	2	MGJ6A-51-14Y	✓	X	\$ 31.40
49	FASTENER, TAILLAMP	2	MGHP9-51-146	✓	X	\$ 7.00
50	GASKET LHS, BOOTLID	1	MGRF5-51-3J8	✓	NEI	\$ 68.20
51	GASKET RHS, BOOTLID	1	MGRF5-51-3H8	✓	NE	\$ 68.20
52	GASKET LHS, TAILLAMP	1	MGRF5-51-163	✓	NEI	\$ 43.80
53	GASKET RHS, TAILLAMP	1	MGRF5-51-153	✓	NE	\$ 43.80
54	GUARD STONE LHS	1	MGHP9-50-4R2A	✓	NEI	\$ 17.40
55	GUARD STONE RHS	1	MGHP9-50-4P2A	✓	NEI	\$ 17.40
56	INSULATOR, HEAT	1	MGBEF-56-451	✓	?	\$ 62.50
57	RIVET, INSULATOR	5	MB25D-56-398	✓	?	\$ 10.50
58	<u>CAMERA, BACK</u>	<u>1</u>	<u>MGBEF-67-RCOA</u>	✓	?	<u>\$ 1,015.30</u>
TOTAL PARTS						\$ 13,188.50
LESS 10%						\$ 1,318.85
TOTAL PARTS COST						\$ 11,869.65

Labour Description					
1	MZ-BR-REAR05	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOTLID. TO REPAIR REAR FLOOR PANEL, REAR FENDER LH, REAR FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.	660.	✓ 3630.	\$ 5,610.00
2	MZ-SP-SREAR7	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, REAR FLOOR PANEL, BOOT LID, REAR FENDER LH AND REAR FENDER RH.	630.	✓ 3150.	\$ 4,095.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.		NETT ✓	\$ 330.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.		NETT ✓	\$ 330.00

5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	nm X	NETT	\$ 70.00
6	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	✓	660	\$ 990.00
7	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	✓	180.	\$ 350.00
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	✓	150.	\$ 250.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	✓	150.	\$ 250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	✓	180.	\$ 350.00
11		TO SUPPLY BRILA PREMIUM COATING. = 7 sales agreement	✓	NETT	\$ 450.00
12	MZ-BR-SUNDRI	SUNDRIES. Nu	30. ✓	NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 13,175.00
TOTAL PARTS	\$ -	\$ 11,869.65
TOTAL	\$ -	\$ 25,044.65
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

25051.40

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

[Signature]
14/8/19

Authorised Signature

Taufik 97445249
wp

5/8/19 330pm

Resurvey before paint.
save 10-11 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

CHINA TAIPING INSURANCE P/L		NAME : Mr Chan Mun Fai Frederick		WIP : 59118	
3 ANSON ROAD		ADDRESS : 107 Lorong H Telok Kurau		EXCESS :	
#16-00 SPRINGLEAF TOWER		Singapore 426132		DATE: 30-Jul-19	
SINGAPORE 079909		TEL : 91882298			
ATTN : MOTOR CLAIMS					
FAX :					
VEH NO :	SDB980M	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM6GL1072K0308634	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6	DATE REG.:	28-Dec-18	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MGSK1-50-221ABB	\$ 1,099.00	\$ 1,099.00
2	BRACKET CENTER	1	MKD53-50-251	\$ 5.40	\$ 5.40
3	COVER UNDER, REAR BUMPER	1	MGSH7-50-C51		\$ 128.50
4	TOWING COVER LHS	1	MGSH7-50-EL1 BB		\$ 46.60
5	TOWING COVER RHS	1	MGSH7-50-EK1 BB		\$ 46.60
6	REAR REINFORCEMENT	1	MGHK1-50-260	\$ 538.30	\$ 538.30
7	GROMMET, REAR BUMPER	2	M9991-00-501	\$ 6.00	\$ 6.00
8	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	\$ 10.80	\$ 10.80
9	RIVET, REAR BUMPER	2	MTK21-50-355	\$ 18.40	\$ 18.40
10	RIVET, REAR BUMPER	6	MEA01-50-037	\$ 48.00	\$ 48.00
11	FASTENER, REAR BUMPER	6	MB45A-56-146A	\$ 18.00	\$ 18.00
12	RUBBER SEAL, REAR BUMPER	2	MGSH7-50-2G1	\$ 27.40	\$ 27.40
13	CLIP, REAR BUMPER	4	MC274-50-133	\$ 14.80	\$ 14.80
14	RETAINER CENTER, SENSOR	1	MKD45-67-UC5AE4	\$ 15.50	\$ 31.00
15	SENSOR CENTER, ULTRASONIC	1	MGMK6-67-UC1 E4	\$ 180.90	\$ 361.80
16	TAPE PROTECTOR, SENSOR	4	MBCKA-50-EM1	\$ 18.80	\$ 18.80
17	CORD SHORT, SENSOR	1	MGBF5-67-290		\$ 192.90
18	REAR END PANEL	1	MGHY1-70-75Z	\$ 700.10	\$ 700.10
19	TRIM, END PANEL	1	MGRF5-68-89X		\$ 157.00
20	BEZEL, LOCK	1	MGHK1-68-894		\$ 11.40
21	FASTENER, TRIM	10	MGJ21-68-885B02	\$ 30.00	\$ 30.00
22	SPONGE LHS, FLOOR PANEL	1	MGHK3-68-8F0A		\$ 260.40
23	SPONGE RHS, FLOOR PANEL	1	MGHK3-68-8E0A		\$ 156.90
24	SPARE WHEEL BOARD	1	MGMD9-68-81XA		\$ 540.70
25	BOOTLID	1	MGBY2-52-61X	\$ 953.30	\$ 953.30
26	HINGE LHS, BOOTLID	1	MGBFN-52-720		\$ 230.50
27	HINGE RHS, BOOTLID	1	MGBFN-52-710		\$ 230.50
28	WEATHERSTRIP, BOOTLID	1	MGBFN-56-951		\$ 120.60
29	LOCK, BOOTLID	1	MGHK1-56-820A	\$ 160.70	\$ 160.70
30	STRIKER, BOOTLID	1	MGG2A-56-840		\$ 35.10
31	SWITCH, OPENER	1	MGHK1-56-8D0		\$ 124.80

32	CHROME FINISHER, BOOTLID	1	MGBEF-50-852A	\$ 360.20	\$ 360.20
33	COVER LOWER, FINISHER	1	MGBEF-50-858	\$ 47.10	\$ 47.10
34	PIN LOCATOR, CHROME FINISHER	1	MBHN9-50-1K5	\$ 2.90	\$ 2.90
35	GROMMET, FINISHER	1	MBHN9-50-ES1	\$ 2.90	\$ 2.90
36	FASTENER, FINISHER	2	MBHN9-50-EA1	\$ 5.80	\$ 5.80
37	ORNAMENT, MAZDA	1	MGBEF-51-711	\$ 25.60	\$ 25.60
38	ORNAMENT, G	1	MGBEF-51-721	\$ 15.50	\$ 15.50
39	MASCOT, REAR	1	MGBEF-51-730A	\$ 41.60	\$ 41.60
40	ORNAMENT, SKYACTIVE	1	MGBFN-51-771	\$ 66.70	\$ 66.70
41	GROMMET, BOOTLID	2	MGA7B-51-146	\$ 6.60	\$ 6.60
42	FASTENER, BOOTLID	2	MEG21-51-146	\$ 12.40	\$ 12.40
43	LAMP LHS, BOOTLID	1	MGRF5-51-3G0B	\$ 768.90	\$ 768.90
44	LAMP RHS, BOOTLID	1	MGRF5-51-3F0B		\$ 768.90
45	TAILLAMP LHS	1	MGSJ4-51-160B		\$ 1,672.70
46	TAILLAMP RHS	1	MGSJ4-51-150B		\$ 1,672.70
47	FASTENER, TAILLAMP	2	MKD53-51-146B		\$ 8.20
48	FASTENER, TAILLAMP	2	MGJ6A-51-14Y		\$ 31.40
49	FASTENER, TAILLAMP	2	MGHP9-51-146		\$ 7.00
50	GASKET LHS, BOOTLID	1	MGRF5-51-3J8	\$ 68.20	\$ 68.20
51	GASKET RHS, BOOTLID	1	MGRF5-51-3H8	\$ 68.20	\$ 68.20
52	GASKET LHS, TAILLAMP	1	MGRF5-51-163	\$ 43.80	\$ 43.80
53	GASKET RHS, TAILLAMP	1	MGRF5-51-153	\$ 43.80	\$ 43.80
54	GUARD STONE LHS	1	MGHP9-50-4R2A	\$ 17.40	\$ 17.40
55	GUARD STONE RHS	1	MGHP9-50-4P2A	\$ 17.40	\$ 17.40
56	INSULATOR, HEAT	1	MGBEF-56-451		\$ 62.50
57	RIVET, INSULATOR	5	MB25D-56-398		\$ 10.50
58	CAMERA, BACK	1	MGBEF-67-RC0A		\$ 1,015.30
	SUPPLEMENTARY ITEM				
1	COVER HOLE, BOOTLID	1	MD24H-62-866	\$ 7.50	\$ 7.50
			TOTAL PARTS	\$ 5,467.90	\$ 13,196.00
			LESS 10%	\$ 546.79	\$ 1,319.60
			TOTAL PARTS COST	\$ 4,921.11	\$ 11,876.40

Labour Description

1	MZ-BR-REAR05	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOTLID. TO REPAIR REAR FLOOR PANEL, REAR FENDER LH, REAR FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 3,630.00	\$ 5,610.00
2	MZ-SP-SREAR7	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, REAR FLOOR PANEL, BOOT LID, REAR FENDER LH AND REAR FENDER RH.	\$ 3,150.00	\$ 4,095.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	\$ 330.00	\$ 330.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	\$ 330.00	\$ 330.00
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.		\$ 70.00

6	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	\$ 660.00	\$ 990.00
7	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	\$ 180.00	\$ 350.00
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 150.00	\$ 250.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
11		TO SUPPLY BRILA PREMIUM COATING.	\$ 450.00	\$ 450.00
12	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00
TOTAL LABOUR			\$ 9,240.00	\$ 13,175.00
TOTAL PARTS			\$ 4,921.11	\$ 11,876.40
TOTAL			\$ 14,161.11	\$ 25,051.40
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 14,161.11	
GST 7%			\$ 991.28	\$ -
GRAND TOTAL			\$ 15,152.39	\$ -

REMARKS:

11 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

ID:t05

INTERNAL INVOICE

CODE: I9104 I04
CUSTOMER: MARKETING NEW - PDI
ADDRESS:

PAGE NO: 1
INVOICE NO: 31008043
DEPT/POS ID: N / 12
DATE IN: 17/12/2018
DATE PRINTED: 31/12/2018
JOB NO: 30024
CSO/OP CODE: PDI - Min Yue
TEL NO:
REGN NO: SDB980M
REGN DATE:
MILEAGE: 3
REQUISITION NO: 26640/BG

MODEL: MAZDA6 IPM 2L SDN STD BLACK LS
CHASSIS NO: JM6GL1072K0308634
ENGINE NO: PE21229855
DESCRIPTION: P.D.I.

MZ-PT M6	PETROL TOPPING			0.00
	Std PDI Pkg M6			
MZ-PDI M	PRE DELIVERY INSPECTION & INSTALL IU			.00
	Std PDI Pkg M6			
MZ-PV M6	POLISH A UNIT OF VEHICLE			0.00
	Std PDI Pkg M6			
MZ-RP M6	SUPPLY 1 SET OF REGN PLATE			0.00
	Std PDI Pkg M6			
MZ-IU M6	SUPPLY 1 UNIT OF IU			0.00
	Std PDI Pkg M6			
MZ-SF M6	SUPPLY & INSTALL SOLAR FILM			.00
	SUBLET 142185			
MZ-FVC M	INSTALL FRONT & REAR VIDEO CAMERA			.00
SUB	M6 BRILA PREMIUM BODY COATING			.00
	SUBLET 142186			
11-CARPETM6GJ	CARPET MAZDA6 12-	1.0	.00	.40
11-BPDVR9	DVR, BLAUPUNKT 9.0 2-	1.0	.50	.50
BJA9-66-EZ1M	MBJA9-66-EZ1L/SD CAR	1.0	.70	.44

COPY DOCUMENT

ID:t05

INTERNAL INVOICE

CODE: I9104 I04
CUSTOMER: MARKETING NEW - PDI
ADDRESS:

PAGE NO: 2
INVOICE NO: 31008043
DEPT/POS ID: N / 12
DATE: 17/12/2018
DATE PRINTED: 31/12/2018
JOB NO: 30024
CSO/OP CODE: PDI - Min Yue
TEL NO:
REGN NO: SDB980M
REGN DATE:
MILEAGE: 3

MODEL: SINGAPORE
CHASSIS NO: MAZDA6 IPM 2L SDN STD BLACK LS
ENGINE NO: JM6GL1072K0308634
PE21229855

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Aug 2019		08 Aug 2019 11:54 Edit Adj Rpt	S\$14,161.11 Edit Estimates	S\$14,161.11 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, ID: -									
Main Claimant: CHAN MUN FAI FREDERICK , ID: S1728008B									
Vehicle Reg. No.: SDB980M		Date of Loss: 29/07/2019 19:00 - :59 [7 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D203558C02		Policy/Cover Note No.: DMCVSN18319618000							
Vehicle Reg. No. (Insured): GBH3705P		Policy No. (Claimant): 1900005531							
		Excess: S\$0.00							
Repairer: Trans Eurokars Pte Ltd (Sungei Kadut) 12 Sungei Kadut Ave, 729648 Sungei Kadut - Tel: 63602845									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 21/08/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDB980M (SNM19D203558C02)
[GBH3705P]

TP




























CHAN MUN FAI FREDERICK

Jul 29 2019 7:00PM

[-]

Trans Eurokars Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)		Thumbnail	Print
1	30/07/19 11:13	Video - Accident [Linked Accident Report Documents]		Load MP4	
2	30/07/19 11:14	Video - Accident [Linked Accident Report Documents]		Load MP4	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)		Thumbnail	Print
1	30/07/19 11:41	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)		Thumbnail	Print
1	30/07/19 11:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	30/07/19 11:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	30/07/19 11:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	30/07/19 11:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	30/07/19 11:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	30/07/19 11:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	30/07/19 11:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
2	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
3	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
4	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
5	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
6	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
7	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
8	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
9	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
10	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
11	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
12	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
13	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
14	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
15	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
16	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
17	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
18	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
19	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
20	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
21	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
22	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
23	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>
24	30/08/19 11:02	General View		Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
25	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
26	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
27	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
28	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
29	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
30	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
31	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
32	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
33	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
34	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
35	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
36	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
37	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
38	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
39	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
40	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
41	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
42	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
43	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
44	30/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
45	30/08/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	30/08/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	30/08/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	30/08/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	30/08/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	30/08/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	30/07/19 11:41	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	30/07/19 11:13	Video - Accident	 Load MP4	
2	30/07/19 11:14	Video - Accident	 Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	30/07/19 11:41	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	30/07/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	30/07/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	30/07/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	30/07/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	30/07/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	30/07/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	30/07/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	30/07/19 11:41	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119013453/T1TD3E2

Date: 20/09/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN18319618000

Claimant
Vehicle No : SDB980MInsured
Vehicle No : GBH3705P

Date of Loss: 29/07/2019

Nature of Claim: TP

Claim
No: SNM19D203558C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDB980M

Make & Model: MAZDA 6, 2.0 4-DOOR SEDAN (A)

Engine No: PE21229855

Reg. Date: 28/12/2018 (Man. Year: 2018)

Chassis No: JM6GL1072K0308634

Colour: Silver

Odometer: 7742 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,046.40	4,951.11	7,095.29	58.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,005.00	9,210.00	3,795.00	29.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	25,051.40	14,161.11	10,890.29	43.47
+ GST 7.00/7.00% (\$\$)	1,753.60	991.28	762.32	43.47
Nett Amount (\$\$)	26,805.00	15,152.39	11,652.61	43.47

INSPECTION

Date of Assignment: 08/08/2019

Date Inspected: 05/08/2019 Inspected At:

27A TANJONG PENJURU
Repairer: Trans Eurokars Pte Ltd
(Sungei Kadut)

Estimated Period of Repair: 11.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Sep 2019)
Parts:	143	MAZDA 6 2.0 4-DOOR SEDAN (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDB980M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	1,099.00 FL	*1,099.00 FL
2	1		*BRACKET CENTER	Distorted	5.40 FL	*5.40 FL
3	1		*COVER UNDER, REAR BUMPER	Not Necessary	128.50 FL	*- FL
4	1		*TOWING COVER LHS	Not Necessary	46.60 FL	*- FL
5	1		*TOWING COVER RHS	Not Necessary	46.60 FL	*- FL
6	1		*REAR REINFORCEMENT	Bent	538.30 FL	*538.30 FL
7	2		*GROMMET, REAR BUMPER	Necessary	6.00 FL	*6.00 FL
8	4		*GROMMET, REAR BUMPER	Necessary	10.80 FL	*10.80 FL
9	2		*RIVET, REAR BUMPER	Necessary	18.40 FL	*18.40 FL
10	6		*RIVET, REAR BUMPER	Necessary	48.00 FL	*48.00 FL
11	6		*FASTENER, REAR BUMPER	Necessary	18.00 FL	*18.00 FL
12	2		*RUBBER SEAL, REAR BUMPER	Necessary	27.40 FL	*27.40 FL
13	4		*CLIP, REAR BUMPER	Necessary	14.80 FL	*14.80 FL
14	1		*RETAINER CENTER, SENSOR (2pcs)	Necessary-1pc only	31.00 FL	*15.50 FL
15	1		*SENSOR CENTER, ULTRASONIC (2pcs)	Not Working-1pc only	361.80 FL	*180.90 FL
16	4		*TAPE PROTECTOR, SENSOR	Necessary	18.80 FL	*18.80 FL
17	1		*CORD SHORT, SENSOR	Not Necessary	192.90 FL	*- FL
18	1		*REAR END PANEL	Bent	700.10 FL	*700.10 FL
19	1		*TRIM, END PANEL	Not Necessary	157.00 FL	*- FL
20	1		*BEZEL, LOCK	Not Necessary	11.40 FL	*- FL
21	10		*FASTENER, TRIM	Necessary	30.00 FL	*30.00 FL
22	1		*SPONGE LHS, FLOOR PANEL	Not Necessary	260.40 FL	*- FL
23	1		*SPONGE RHS, FLOOR PANEL	Not Necessary	156.90 FL	*- FL
24	1		*SPARE WHEEL BOARD	Not Necessary	540.70 FL	*- FL
25	1		*BOOTLID	Bent	953.30 FL	*953.30 FL
26	1		*HINGE LHS, BOOTLID	Not Necessary	230.50 FL	*- FL
27	1		*HINGE RHS, BOOTLID	Not Necessary	230.50 FL	*- FL
28	1		*WEATHERSTRIP, BOOTLID	Not Necessary	120.60 FL	*- FL
29	1		*LOCK, BOOTLID	Bent	160.70 FL	*160.70 FL
30	1		*STRIKER, BOOTLID	Not Necessary	35.10 FL	*- FL
31	1		*SWITCH, OPENER	Not Necessary	124.80 FL	*- FL
32	1		*CHROME FINISHER, BOOTLID	Cracked	360.20 FL	*360.20 FL
33	1		*COVER LOWER, FINISHER	Missing	47.10 FL	*47.10 FL
34	1		*PIN LOCATOR, CHROME FINISHER	Necessary	2.90 FL	*2.90 FL
35	1		*GROMMET, FINISHER	Necessary	2.90 FL	*2.90 FL
36	2		*FASTENER, FINISHER	Necessary	5.80 FL	*5.80 FL
37	1		*ORNAMENT, MAZDA	Necessary	25.60 FL	*25.60 FL
38	1		*ORNAMENT, 6	Necessary	15.50 FL	*15.50 FL
39	1		*MASCOT, REAR	Necessary	41.60 FL	*41.60 FL
40	1		*ORNAMENT, SKYACTIVE	Necessary	66.70 FL	*66.70 FL
41	2		*GROMMET, BOOTLID	Necessary	6.60 FL	*6.60 FL
42	2		*FASTENER, BOOTLID	Necessary	12.40 FL	*12.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*LAMP LHS, BOOTLID	Cracked	768.90 FL	*768.90 FL
44	1		*LAMP RHS, BOOTLID	Not Necessary	768.90 FL	*- FL
45	1		*TAILLAMP LHS	Not Necessary	1,672.70 FL	*- FL
46	1		*TAILLAMP RHS	Not Necessary	1,672.70 FL	*- FL
47	2		*FASTENER, TAILLAMP	Not Necessary	8.20 FL	*- FL
48	2		*FASTENER, TAILLAMP	Not Necessary	31.40 FL	*- FL
49	2		*FASTENER, TAILLAMP	Not Necessary	7.00 FL	*- FL
50	1		*GASKET LHS, BOOTLID	Necessary	68.20 FL	*68.20 FL
51	1		*GASKET RHS, BOOTLID	Necessary	68.20 FL	*68.20 FL
52	1		*GASKET LHS, TAILLAMP	Necessary	43.80 FL	*43.80 FL
53	1		*GASKET RHS, TAILLAMP	Necessary	43.80 FL	*43.80 FL
54	1		*GUARD STONE LHS	Necessary	17.40 FL	*17.40 FL
55	1		*GUARD STONE RHS	Necessary	17.40 FL	*17.40 FL
56	1		*INSULATOR, HEAT	Not Necessary	62.50 FL	*- FL
57	5		*RIVET, INSULATOR	Not Necessary	10.50 FL	*- FL
58	1		*CAMERA, BACK	Not Necessary	1,015.30 FL	*- FL
59	1		*NUMBER PLATE	Not Necessary	70.00 FS	*- FS
60	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
61	1		*COVER HOLE, BOOTLID	Necessary	7.50 FL	*7.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,366.00	5,497.90
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,319.60	546.79
Total Parts (\$\$)	12,046.40	4,951.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOTLID. TO REPAIR REAR FLOOR PANEL, REAR FENDER LH, REAR FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT	New	5,610.00	3,630.00
2	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, REAR FLOOR PANEL, BOOT LID, REAR FENDER LH AND REAR FENDER RH	New	4,095.00	3,150.00
3	TO TRANSFER REVERSE SENSORS	New	330.00	330.00
4	TO TRANSFER REVERSE CAMERA	New	330.00	330.00
5	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	New	350.00	180.00
6	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	150.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
9	TO SUPPLY BRILA PREMIUM COATING	New	450.00	450.00
10	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	990.00	660.00
Gross Labour Cost (S\$)			13,005.00	9,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >