

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 709M**AAD1907-244***Not Authorized
1/1/2019*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

30 JUL 2019

SHF 709M

VF1ABL15AUC281192

RENAULT

LATITUDE

25.7.19

AXA

31/12/2014

PART

1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	OUTER PANEL REAR (End Panel)
14	1	OUTER PANEL REAR (End Panel)TRIM
15	1	TAILLAMP RH
16	1	TAILLAMP PANEL RH
17	1	TAILLAMP LH
18	1	TAILLAMP PANEL LH
19	1	BOOT REAR
20	1	BOOT FINISHER
21	1	BOOT WHEATERSTRIP
22	1	BOOT REFLECTOR LAMP LH
23	1	BOOT REFLECTOR LAMP RH
24	1	BOOT BADGE 'RENAULT'
25	1	BOOT BADGE
26	1	BOOT STRUT LH
27	1	BOOT STRUT RH

LIST

\$	<i>Bu</i>	1,108.46	—
\$	<i>na/ln</i>	768.84	—
\$	<i>ln</i>	113.47	X
\$	<i>ln</i>	135.97	X
\$	<i>ln</i>	44.99	X
\$	<i>ln</i>	43.61	X
\$	<i>ln</i>	135.97	X
\$	<i>ln</i>	44.99	X
\$	<i>ln</i>	43.61	X
\$	<i>Bu</i>	777.52	—
\$	<i>ln</i>	225.95	} X
\$	<i>ln</i>	225.95	
\$	<i>ln</i>	1,471.77	
\$	<i>ln</i>	404.56	
\$	<i>ln</i>	552.55	
\$	<i>ln</i>	986.70	
\$	<i>ln</i>	552.55	
\$	<i>ln</i>	986.70	
\$	<i>ln</i>	2,872.68	
\$	<i>ln</i>	470.06	
\$	<i>ln</i>	323.05	
\$	<i>ln</i>	493.35	
\$	<i>ln</i>	493.35	
\$	<i>ln</i>	225.36	
\$	<i>ln</i>	225.36	
\$	<i>ln</i>	276.08	
\$	<i>ln</i>	276.08	

Trans-cab Auto Services Pte Ltd**AAD1907-244**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 709M

28	1	BOOT HINGE LH	\$	<i>R</i>	367.84	}	<i>X</i>	
29	1	BOOT HINGE RH	\$	<i>R</i>	367.84			
30	1	BOOT INNER TRIM	\$	<i>SL</i>	586.45			
31	1	BOOT SWITCH	\$	<i>SL</i>	168.13			
32	1	BOOT LOCK	\$	<i>R</i>	202.67			
33	1	BOOT LOCK CATCH	\$	<i>R</i>	74.40			
34	1	EXHAUST REAR	\$	<i>R</i>	7,489.05			
35	1	EXHAUST CAP REAR	\$	<i>R</i>	230.49			
TOTAL			\$		23,766.42			
10%			\$		2,376.64			
			\$		21,389.78			

Special Nett

1	1SET	PARKING AID	\$	Short	700.00	400.00
2	1SET	REAR BUMPER CLIP	\$	na	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	—
10	1	BOOT STICKER "Trans-cab"	\$	na	30.00	} X
11	1	BOOT STICKER "6555-3333"	\$	na	30.00	
12	1	EXHAUST MOUNTING REAR	\$	na	17.82	
13	2	REAR WINDSCREEN SEALANT	\$	na	80.00	
14	1	WINDSCREEN MOULDING	\$	na	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
16	1	BOOT INNER TRIM CLIP	\$	na	45.00	
17	1SET	BOOT FINISHER CLIP	\$	na	24.20	
18	1	TAILLAMP CLIP LH	\$	na	5.00	
19	1	TAILLAMP CLIP RH	\$	na	5.00	
TOTAL			\$		1,384.02	
TOTAL PARTS			\$		22,773.80	

Trans-cab Auto Services Pte Ltd**AAD1907-244**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 709M**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nr</i> 380.00 <i>X</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nr</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>100</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nr</i> 170.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nr</i> 170.00 <i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>600</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00 <i>2000</i>
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 <i>2200</i>
To repair and realign rear exhaust pipe.	\$	<i>nr</i> 170.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>L</i> 170.00 <i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>L</i> 170.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>L</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>L</i> 220.00 <i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1907-244**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 709M

To transfer of rear bumper fittings, attachment and
perform water seepage test.

\$ *m* 380.00 *X*

Labour charge to mount and dismount vehicle on jig
bench, to facilitate repair.

\$ *m* 380.00 *X***TOTAL \$ 11,890.00****Over All Total \$ 34,663.80****LUMP SUM (REPAIR DAY) *15 DAYS****2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: