

ASS. REC. BY:

REF: CS/CT19013474/ G9f3e1 Special Instruction:

**Special Instruction:**

Surveyor : GA

ASSIGNMENT (Office)

From (Person): Tan Kan Leong of CTI Date/Time: 1.8.19 9.18 a.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD (TP) WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGG 7286B Insured: Ym 9748 C

at Workshop m/s Kah mojo Tel: 82886302

of 6 A mandai Estate

Policy No: DMCVSN30735818000 Claim No: SNM190203570002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 27.7.19  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 18.12.19 10.34 a.m. Person Contacted: Amtken Vehicle: IN/OUT

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction ( ✓ ) Estimate.
	S6g J2B6B-X
	Ym 9748C-7

ASS. REQ. BY:

REF: CTI

## ASSIGNMENT

From:

Date:

20/1/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

S9G 7286B

at Workshop m/s

Kah Motor

of

6A Mendeni Estate

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

Carlin

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.:

Yes or No

Lum Sum:

1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

(up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S6G 7286B

Yr Regn:

04 Jan 2016

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda HR-V

C.C.

1497

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

83051

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRHRU1830FP000559

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

215/55 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

20-08-19

Survey held at

W/S

3:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

02/10

Finalised \$ 10692.04 with Anikka

Used \$ 4352.64, 29%.

RECEIVED 04 OCT 2019

Date/Time, File Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

Survey Fee:

220

Transportation:

Photos

Others

TOTAL

220

Report Format:

MER-TP

Lump Sum / L.B.E. @

10692.04

**Nivitha (LKK Auto)**

---

**From:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Sent:** Thursday, 1 August 2019 9:18 AM  
**To:** Anikka Lai; assignments  
**Subject:** RE: OUR REF: SNM19D203570-YM9748C- TKL- FW: SGG7286B - TP CLAIMS AGAINST YM9748C DOA: 27/07/2019

**WITHOUT PREJUDICE**

Dear Anikka,

We refer to your email of 31.07.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

**Tan Kah Leong**  
Assistant Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Anikka Lai [mailto:anikkalai@honda.com.sg]  
**Sent:** Wednesday, 31 July, 2019 5:52 PM  
**To:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Subject:** RE: OUR REF: SNM19D203570-YM9748C- TKL- FW: SGG7286B - TP CLAIMS AGAINST YM9748C DOA: 27/07/2019  
**Importance:** High

Dear Kah Leong,

Pls arrange Henry Ng to survey the vehicle. However, kindly advise the liability of direct settlement before survey.

Thank you.

Warmest regards  
Anikka Lai  
6A Mandai Estate  
Singapore 729903  
DID : 65145248 HP: 82886302

Email add: anikkalai@honda.com.sg

**From:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>

**Sent:** Wednesday, 31 July 2019 5:38 PM

**To:** Anikka Lai <anikkalai@honda.com.sg>

**Subject:** RE: OUR REF: SNM19D203570-YM9748C- TKL- FW: SGG7286B - TP CLAIMS AGAINST YM9748C DOA: 27/07/2019

**Without Prejudice**

Dear Anikka,

We refer to your email dated 31 July 2019.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
LOW SAR HUEI
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
HONG FOOK CHOY
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards

**Tan Kah Leong**  
Assistant Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI

**Sent:** Wednesday, 31 July, 2019 5:19 PM

**To:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; anikkalai@honda.com.sg

**Subject:** OUR REF: SNM19D203570-YM9748C- TKL- FW: SGG7286B - TP CLAIMS AGAINST YM9748C DOA: 27/07/2019

**Importance:** High

Dear kah Leong,

Please conduct PRS for SGG7286B.

Note : officer in charge – Kah Leong 63896193

Regards,

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Anikka Lai [<mailto:anikkalai@honda.com.sg>]

**Sent:** Wednesday, 31 July, 2019 3:23 PM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Subject:** SGG7286B - TP CLAIMS AGAINST YM9748C DOA: 27/07/2019

**Importance:** High

Dear Sir / Madam,

Attached pls find the claim documents for your necessary action. Kindly advise the liability of direct settlement.

Thank you.

Warmest regards

Anikka Lai

6A Mandai Estate

Singapore 729903

DID : 65145248 HP: 82886302

Email add: [anikkalai@honda.com.sg](mailto:anikkalai@honda.com.sg)


---

**From:** Printer Service <[printservice@honda.com.sg](mailto:printservice@honda.com.sg)>

**Sent:** Wednesday, 31 July 2019 3:17 PM

**To:** Anikka Lai <[anikkalai@honda.com.sg](mailto:anikkalai@honda.com.sg)>


**Subject:** Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

[Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	461Z
Vehicle No.:	SGG7286B
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 LX CVT ABS D/AIRBAG 2WD
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	L15Z71001095
Chassis No.:	MRHRU1830FP000559
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$23,082.00
Original Registration Date:	04 Jan 2016
First Registration Date:	04 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$24,315.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Jan 2026
PARF Rebate Amount:	\$18,236.00
COE Expiry Date:	03 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,399.00
COE Rebate Amount:	\$35,294.00
<b>Total Rebate Amount:</b>	<b>\$53,530.00</b>

The information contained herein is correct as at 20 Aug 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/07/2019 17:59
Date Of Accident	27/07/2019 18:20
Exact Location Of Accident	SLIP RD FM ECP TO STILL RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGG7286B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KAM KWEE ENG
NRIC No	S1291461Z
Email Address	KWEE@MAIL.COM
Mobile Phone No	(LOCAL) +65-94233612
Alternative Phone No	OFFICE-94233612

### Vehicle Particulars

Manufacturer	HONDA
Model	HR-V-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	TAN KAI ANN
NRIC No	S1654004H
Date Of Birth	23/08/1960
Occupation	INDOOR
Date Of Driving Pass	28/03/1992
Driving Experience	27 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	+65-93860382
Fax Number	
Contact Number	
EMail Address	TK_ANN@MAIL.COM



Address	-
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

AS ANNEX D&E

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	YM9748C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	OWALED MD KHALED BEEN
NRIC/Passport Number	G8402168L
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Vehicle Number: SGG 7286B


**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:

\_\_\_\_\_  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer** : CHINA TAIPING INSURANCE (S'PORE) PTE  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

**Registration No** : SGG7286B

**Chassis No** : MRHRU1830FP000559

**Model** : HRV LX-SIN CVT YM 2015

**Owner's Name** : KAM KWEE ENG

**Ins Policy No.** :

**Date of Accident** : 27/6/2019

**Document No.** : SQT19003344

**Date** : 30. Jul 2019

**Customer No.** : WZC008

**Svc Advisor** :

**Engine No** : L15Z71001095

**Date | Time** : 30. Jul 2019 11:41:55 AM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: KAM KWEE ENG OWNER INSURER: TOKIO MARINE ACC DATE: 27/07/2019 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: YM9748C	82886302 Anikka.					
68100-T8P-U10ZZ	TAILGATE COMP / Buc.	1	855.70	5	812.91	56.90	869.81
68210-T5A-023ZZ	HINGE COMP, TAILGATE X NN	2	28.70	5	54.53	3.82	58.35
74440-T7A-003	WEATHERSTRIPTAILGATE X NN	1	98.70	5	93.76	6.56	100.32
74800-T7A-J01	LOCK ASSYTAILGATE / BT.	1	78.90	5	74.95	5.25	80.20
74813-T5A-003	STRIKER ASSYTAILGATE X NN	1	24.70	5	23.46	1.64	25.10
74820-T7J-H01	STAY ASSYR.TAILGATE OPEN X NN	1	101.20	5	96.14	6.73	102.87
74870-T7J-H01	STAY ASSYL.TAILGATE OPEN X NN	1	101.20	5	96.14	6.73	102.87
74890-T7A-J12ZR	GARNISH ASSYRR.LICENSE / BR.	1	189.80	5	180.31	12.62	192.93
75701-T5A-000	EMBLEMH / S.MC.	1	10.70	5	10.16	0.71	10.87
90301-ST0-003	NUTPUSH 3MM / S.MC.	2	2.10	5	3.99	0.28	4.27
84431-T8N-T01ZA	LINING ASSYTAILGATE LOWER X NN	1	89.30	5	84.83	5.94	90.77
84441-S2K-000ZB	POCKETTAILGATE PULL X NN	1	15.20	5	14.44	1.01	15.45
84640-T8N-T01ZA	LINING ASSYRR.PANEL X NN	1	66.60	5	63.27	4.43	67.70
71501-T8N-T50	FACERR.BUMPER / RC	1	463.70	5	440.51	30.84	471.35
71593-T7A-000	SPACER,R.RR.BUMPER SIDE / S.MC.	1	17.20	5	16.34	1.14	17.48
71598-T7A-000	SPACER,L.RR.BUMPER SIDE / S.MC.	1	17.20	5	16.34	1.14	17.48
91505-TM8-003	CLIP,BUMPER /	8	2.30	5	17.48	1.22	18.70
71502-T7J-H50ZZ	FACER.RR.BUMPER CORNER X NN	1	83.50	5	79.32	5.55	84.87

Printed on 31/7/2019 3:15:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer** : CHINA TAIPING INSURANCE (S'PORE) PTE  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

**Registration No** : SGG7286B

**Chassis No** : MRHRU1830FP000559

**Model** : HRV LX-SIN CVT YM 2015

**Owner's Name** : KAM KWEE ENG

**Ins Policy No.** :

**Date of Accident** : 27/6/2019

**Document No.** : SQT19003344

**Date** : 30. Jul 2019

**Customer No.** : WZC008

**Svc Advisor** :

**Engine No** : L15Z71001095

**Date | Time** : 30. Jul 2019 11:41:55 AM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71507-T7J-H50ZZ	FACEL.RR.BUMPER CORNER X <i>NN</i>	1	83.50	5	79.32	5.55	84.87
66100-T8N-T00ZZ	PANEL COMPR. <i>Buc.</i>	1	411.90	5	391.30	27.39	418.69
33502-T7A-J01	LAMP UNITR. <i>scr</i>	1	441.50	5	419.42	29.36	448.78
33552-T7A-J01	LAMP UNITL. <i>scr</i>	1	441.50	5	419.42	29.36	448.78
34150-T7A-J01	LIGHT ASSY,R.LID <i>scr</i>	1	269.90	5	256.40	17.95	274.35
34155-T7A-J01	LIGHT ASSYL.LID <i>scr</i>	1	269.90	5	256.40	17.95	274.35
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>NN</i>	1	320.00		320.00	22.40	342.40
74940-TR0-003	BUZZER ASSYSMART <i>NN</i>	1	60.10	5	57.09	4.00	61.09
38387-TZ5-A01	ANTENNA ASSYL.F. <i>NN</i>	1	59.30	5	56.33	3.94	60.27
39530-T7M-H01	CAMERA ASSYRR.VIEW <i>NN</i>	1	1041.10	5	989.04	69.23	1058.27
39680-TV0-E01ZU	SENSOR ASSYPARKING <i>NN</i>	1	62.10	5	58.99	4.13	63.12
39680-TV0-E01C5	SENSOR ASSYPARKING <i>NN</i>	1	82.10	5	77.99	5.46	83.45
39680-TV0-E11ZN	SENSOR ASSYPARKING <i>NN</i>	2	62.10	5	117.99	8.26	126.25
39681-T7A-H01ZB	RETAINER PARKING SENSOR <i>NN</i>	2	62.10	5	117.99	8.26	126.25
75722-T7W-A01	EMBLEMRR. <i>NN</i>	1	13.30	5	12.63	0.88	13.51
75725-T8N-T00	EMBLEM,RR. I-VTEC <i>NN</i>	1	14.50	5	13.77	0.96	14.73
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>NN</i>	1	45.00		45.00	3.15	48.15
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER <i>NN</i>	1	19.30	5	18.33	1.28	19.61
73226-SZW-000	DAMPERSTD 5X5 <i>NN</i>	1	8.50	5	8.07	0.56	8.63
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER <i>NN</i>	1	19.30	5	18.33	1.28	19.61
76711-T6A-003	CAPPVOT <i>NN</i>	1	4.80	5	4.56	0.32	4.88
91501-S70-003	FASTENER BW/SHIELD <i>NN</i>	4	5.30	5	20.14	1.41	21.55
91502-S70-003	FASTENER B <i>NN</i>	2	5.30	5	10.07	0.70	10.77
91536-SS0-J01	FASTENER AW/SHIELD <i>NN</i>	2	3.80	5	7.22	0.51	7.73
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>NN</i>	2	60.00		120.00	8.40	128.40
Sum Item					6074.68	425.20	6,499.88
BOSUN	SUNDRIES <i>NN</i>	1	100.00		100.00	7.00	107.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM <i>NN</i>	1	480.00		480.00	33.60	513.60

Printed on 31/7/2019 3:15:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer** : CHINA TAIPING INSURANCE (S'PORE) PTE  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

**Registration No** : SGG7286B

**Chassis No** : MRHRU1830FP000559

**Model** : HRV LX-SIN CVT YM 2015

**Owner's Name** : KAM KWEE ENG

**Ins Policy No.** :

**Date of Accident** : 27/6/2019

**Document No.** : SQT19003344

**Date** : 30. Jul 2019

**Customer No.** : WZC008

**Svc Advisor** :

**Engine No** : L15Z71001095

**Date | Time** : 30. Jul 2019 11:41:55 AM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00	✓	560.00	39.20	599.20
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	480.00	280	480.00	33.60	513.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	150.00	✓	150.00	10.50	160.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	600.00	560	600.00	42.00	642.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	800.00	380	800.00	56.00	856.00
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00	80	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00	80	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT END PANEL	1	100.00	80	100.00	7.00	107.00
BKRP02M	CUT OFF & RENEW RR PANEL & DAMAGE PARTS.	1	3000.00	2240	3000.00	210.00	3210.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2500.00	2250	2500.00	175.00	2675.00
Sum Labor					8970.00	627.90	9,597.90

Survey By

Date &amp; Time

Excess

Status

Signature

Total Amount 15,044.68 1,053.10 16,097.78

Total (Inclusive of GST) 16,097.78

7 Days.  
ref one paint photos.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 31/7/2019 3:15:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

**SERVICE PRE-INVOICE**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0031272 / CHINA TAIPING  
 Chassis No: MRHRU1830FP000559  
 License No: SGG7286B  
 Mileage: 79236  
 Engine No: L15Z71001095

Document No: SVO19053372  
 Printed By: ANIKKALAI  
 Order Date: 20. August 2019  
 Order Time: 3:52:05 PM  
 Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: KAM KWEE ENG OWNER INSURER: TOKIO MARINE ACC DATE: 27/07/2019 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: YM9748C						
68100-T8P-U10ZZ	TAILGATE COMP	1	855.70	5	812.91	56.90	869.81
74800-T7A-J02	LOCK ASSYTAILGATE	1	78.90	5	74.95	5.25	80.20
74890-T7A-J12ZR	GARNISH ASSYRR.LICENSE	1	189.80	5	180.31	12.62	192.93
75701-T5A-000	EMBLEMH	1	10.70	5	10.16	0.71	10.87
90301-ST0-003	NUTPUSH 3MM	2	2.10	5	3.99	0.28	4.27
71501-T8N-T50	FACERR.BUMPER	1	463.70	5	440.51	30.84	471.35
71593-T7A-000	SPACER,R.RR.BUMPER SIDE	1	17.20	5	16.34	1.14	17.48
71598-T7A-000	SPACER,L.RR.BUMPER SIDE	1	17.20	5	16.34	1.14	17.48
91505-TM8-003	CLIP,BUMPER	8	2.30	5	17.48	1.22	18.70
66100-T8N-T00ZZ	PANEL COMPRR.	1	411.90	5	391.30	27.39	418.69
33502-T7A-J01	LAMP UNITR.	1	441.50	5	419.42	29.36	448.78
33552-T7A-J01	LAMP UNITL.	1	441.50	5	419.42	29.36	448.78
34150-T7A-J01	LIGHT ASSY,R.LID	1	269.90	5	256.40	17.95	274.35
34155-T7A-J01	LIGHT ASSYL.LID	1	269.90	5	256.40	17.95	274.35
39681-T7A-H01ZB	RETAINER PARKING SENSOR	2	62.10	5	117.99	8.26	126.25
75722-T7W-A01	EMBLEMRR.	1	13.30	5	12.63	0.88	13.51
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.50	5	13.77	0.96	14.73
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	5	18.33	1.28	19.61
73226-SZW-000	DAMPERSTD 5X5	1	8.50	5	8.07	0.56	8.63
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	5	18.33	1.28	19.61
76711-T6A-003	CAPPVOT	1	4.80	5	4.56	0.32	4.88
91501-S70-003	FASTENER BW/SHIELD	4	5.30	5	20.14	1.41	21.55
91502-S70-003	FASTENER B	2	5.30	5	10.07	0.70	10.77
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	5	7.22	0.51	7.73
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
	<b>SUM PARTS:</b>				<b>3,712.04</b>	<b>259.82</b>	<b>3,971.86</b>
BOSUN		1	40.00		40.00	2.80	42.80
	SUNDRIES						
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	280.00		280.00	19.60	299.60
BG02R	1438	1	560.00		560.00	39.20	599.20
	REPLACE RR. WINDSCREEN.(N)						
BC011R	1438	1	280.00		280.00	19.60	299.60
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA						
BA02R	1466	1	150.00		150.00	10.50	160.50
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						



## SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer:** CU0031272 / CHINA TAIPING  
**Chassis No:** MRHRU1830FP000559  
**License No:** SGG7286B  
**Mileage:** 79236  
**Engine No:** L15Z71001095

**Document No:** SVO19053372  
**Printed By:** ANIKKALAI  
**Order Date:** 20. August 2019  
**Order Time:** 3:52:05 PM  
**Service Advisor:** ANIKKA LAI SWEE KAM

BMI03D	1438 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	560.00	560.00	39.20	599.20
BKTG02R	1466 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	380.00	380.00	26.60	406.60
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00	80.00	5.60	85.60
BOJSE	1718 BODY JOINT SEALANT TAILGATE	1	80.00	80.00	5.60	85.60
BOJSE	1718 BODY JOINT SEALANT END PANEL	1	80.00	80.00	5.60	85.60
BKRP02M	1466 CUT OFF & RENEW RR PANEL & DAMAGE PARTS. FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	1	2,240.00	2,240.00	156.80	2,396.80
BP05R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	2,250.00	2,250.00	157.50	2,407.50

**SUM LABOUR:** 6,980.00 488.60 7,468.60

**TOTAL SGD** 10,692.04 748.42 11,440.46

**Total Payable (SGD)** 11,440.46

GST Amount is calculated from individual line(s)













































## ...CLAIM SUBFOLDER...(Pending for Survey Report)





CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jul 2019		04 Oct 2019 13:59 <a href="#">Edit Adj Rpt</a>	<b>S\$10,692.04</b> <a href="#">Edit Estimates</a>	<b>S\$10,692.04</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: -, Co. Reg. No.: -									
Main Claimant: <b>KAM KWEE ENG</b> , ID: S1291461Z									
Vehicle Reg. No.: <b>SGG7286B</b>		Date of Loss: 27/07/2019 18:00 - :59 [42 Months and 23 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / SNM19D203570C02</b>		Policy/Cover Note No.: DMCVSN30735818000							
Vehicle Reg. No. (Insured): <b>YM9748C</b>		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: <b>Kah Motor Co Sdn Bhd (Ubi)</b> 15 Ubi Road 4, 408610 Ubi - Tel: 68465671									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Tan Kah Leong</b> - 63896193]									
Claimant's Insurer: <b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 15/10/2019]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




## Claim Documents

\*SGG7286B (SNM19D203570C02)  
[YM9748C]  
TP  
KAM KWEE ENG  
Jul 27 2019 6:00PM  
[-]  
Kah Motor Co Sdn Bhd








Upload Documents		Upload Photos	Compose New Letter	View <span>View in Browser</span>	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
2	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
3	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
4	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
5	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
6	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
7	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
8	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
9	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
10	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
11	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
12	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
13	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
14	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
15	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
16	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
17	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
18	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
19	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
20	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
21	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
22	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
23	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
24	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
25	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
26	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
27	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
28	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
29	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
30	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
31	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
32	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
33	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
34	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
35	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
36	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
37	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
38	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
39	04/10/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
40	04/10/19 14:16	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
41	04/10/19 14:16	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
42	04/10/19 14:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
43	04/10/19 14:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	04/10/19 14:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	04/10/19 14:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	04/10/19 14:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	04/10/19 14:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>


## Linked Accident Report Documents

Assessment Reports			View	View in Browser	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print	
1	29/07/19 18:53	Accident Statement	 Load HTM		
2	29/07/19 18:54	Addendum Sheet	 Load TIF		
3	29/07/19 18:54	Accident Statement Addm. #1	 Load HTM		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	29/07/19 18:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	29/07/19 18:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	29/07/19 18:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	29/07/19 18:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	29/07/19 18:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	29/07/19 18:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	29/07/19 18:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	29/07/19 18:53	Sketch Plan	 Load TIF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin: 5px 0;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19013474/GQF3E2

Date: 15/10/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN30735818000

Claimant  
Vehicle No : SGG7286BInsured  
Vehicle No : YM9748C

Date of Loss: 27/07/2019

Nature of Claim: TP

Claim  
No: SNM19D203570C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SGG7286B

Make &amp; Model: HONDA HR-V, 1.5 (A)

Engine No: L15Z71001095

Reg. Date: 04/01/2016 (Man. Year: 2015)

Chassis No: MRHRU1830FP000559

Colour: Blue

Odometer: 83051 km

Engine Capacity: 1497 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,174.68	3,752.04	2,422.64	39.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,870.00	6,940.00	1,930.00	21.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>15,044.68</b>	<b>10,692.04</b>	<b>4,352.64</b>	<b>28.93</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,053.13</b>	<b>748.44</b>	<b>304.69</b>	<b>28.93</b>
<b>Nett Amount (S\$)</b>	<b>16,097.81</b>	<b>11,440.48</b>	<b>4,657.33</b>	<b>28.93</b>

## INSPECTION

Date of Assignment: 04/10/2019

Date Inspected: 20/08/2019 Inspected At:

Kah Motor Co Sdn Bhd (Ubi)  
6A MANDAI ESTATE  
SINGAPORE 729903

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Oct 2019)
<b>Parts:</b>	M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGG7286B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE COMP	Buckled	812.91 FS	*812.91 FS
2	2		*HINGE COMP, TAILGATE	Not Necessary	54.53 FS	*- FS
3	1		*WEATHERSTRIPTAILGATE	Not Necessary	93.76 FS	*- FS
4	1		*LOCK ASSYTAILGATE	Bent	74.95 FS	*74.95 FS
5	1		*STRIKER ASSYTAILGATE	Not Necessary	23.46 FS	*- FS
6	1		*STAY ASSYR.TAILGATE OPEN	Not Necessary	96.14 FS	*- FS
7	1		*STAY ASSYL.TAILGATE OPEN	Not Necessary	96.14 FS	*- FS
8	1		*GARNISH ASSYRR.LICENSE	Broken	180.31 FS	*180.31 FS
9	1		*EMBLEMH	Necessary	10.16 FS	*10.16 FS
10	1		*NUTPUSH 3MM (2PCS)	Necessary	3.99 FS	*3.99 FS
11	1		*LINING ASSYTAILGATE LOWER	Not Necessary	84.83 FS	*- FS
12	1		*POCKETTAILGATE PULL	Not Necessary	14.44 FS	*- FS
13	1		*LINING ASSYRR.PANEL	Not Necessary	63.27 FS	*- FS
14	1		*FACERR.BUMPER	Deformed	440.51 FS	*440.51 FS
15	1		*SPACER,R.RR.BUMPER SIDE	Necessary	16.34 FS	*16.34 FS
16	1		*SPACER,L.RR.BUMPER SIDE	Necessary	16.34 FS	*16.34 FS
17	1		*CLIP, BUMPER (8PCS)	Necessary	17.48 FS	*17.48 FS
18	1		*FACER.RR.BUMPER CORNER	Not Necessary	79.32 FS	*- FS
19	1		*FACEL.RR.BUMPER CORNER	Not Necessary	79.32 FS	*- FS
20	1		*PANEL COMPRR.	Buckled	391.30 FS	*391.30 FS
21	1		*LAMP UNITR.	Scratched	419.42 FS	*419.42 FS
22	1		*LAMP UNITL.	Scratched	419.42 FS	*419.42 FS
23	1		*LIGHT ASSY,R.LID	Scratched	256.40 FS	*256.40 FS
24	1		*LIGHT ASSYL.LID	Cracked	256.40 FS	*256.40 FS
25	4		*ACT RR.SENSOR	Not Necessary	320.00 FS	*- FS
26	1		*BUZZER ASSYSMART	Not Necessary	57.09 FS	*- FS
27	1		*ANTENNA ASSYL.F.	Not Necessary	56.33 FS	*- FS
28	1		*CAMERA ASSYRR.VIEW	Not Necessary	989.04 FS	*- FS
29	1		*SENSOR ASSYPARKING	Not Necessary	58.99 FS	*- FS
30	1		*SENSOR ASSYPARKING	Not Necessary	77.99 FS	*- FS
31	2		*SENSOR ASSYPARKING	Not Necessary	117.99 FS	*- FS
32	1		*RETAINER PARKING SENSOR (2PCS)	Necessary	117.99 FS	*117.99 FS
33	1		*EMBLEMRR.	Necessary	12.63 FS	*12.63 FS
34	1		*EMBLEM,RR.I-VTEC	Necessary	13.77 FS	*13.77 FS
35	1		*NUMBER PLATE WITH CASING - L	Scratched	45.00 FS	*45.00 FS
36	1		*RUBBER CR.WINDSHIELD DAMPER	Necessary	18.33 FS	*18.33 FS
37	1		*DAMPERSTD 5X5	Necessary	8.07 FS	*8.07 FS
38	1		*RUBBER CL.WINDSHIELD DAMPER	Necessary	18.33 FS	*18.33 FS
39	1		*CAPPIVOT	Necessary	4.56 FS	*4.56 FS
40	1		*FASTENER BW/SHIELD (4PCS)	Necessary	20.14 FS	*20.14 FS
41	1			Necessary	10.07 FS	*10.07 FS
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			<b>*FASTENER B</b> (2PCS)			
42	2		<b>*FASTENER AW/SHIELD</b>	Necessary	7.22 FS	*7.22 FS
43	2		<b>*WINDSCREEN SEALANT</b>	Necessary	120.00 FS	*120.00 FS
44	1		<b>*SUNDRIES</b>	Necessary	100.00 FS	*40.00 FS
F=Franchise part. S=SpcNett.						
				<b>Total Parts (S\$)</b>	<b>6,174.68</b>	<b>3,752.04</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RESET VEHICLE SMART ENTRY SYSTEM	New	480.00	280.00
2	REPLACE RR.WINDSCREEN	New	560.00	560.00
3	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	480.00	280.00
4	REMOVE & RENEW REVERSE SENSORS - 4 PCS	New	150.00	150.00
5	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	600.00	560.00
6	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	New	800.00	380.00
7	WINDSCREEN DAM KIT	New	100.00	80.00
8	BODY JOINT SEALANT TAILGATE	New	100.00	80.00
9	BODY JOINT SEALANT END PANEL	New	100.00	80.00
10	CUT OFF & RENEW RR PANEL & DAMAGE PARTS	New	3,000.00	2,240.00
11	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	New	2,500.00	2,250.00
Gross Labour Cost (S\$)			<b>8,870.00</b>	<b>6,940.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >