

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0512/2019/DY/TF
Date : 18-Apr-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle : **SMF 2364 B**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR AW MING ZHE ALVIN
Address : 100 SHREWSBURY ROAD
: Singapore 307850
Telephone : HP +65 97982558
Type of Claim : Third Party Claims
Policy No. : 1900009652
Vehicle No : **SCG 100 Y**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Dec-18
Engine No : CHZ C25985
Chassis No : WAUZZZ8V0K1012760
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Jul-19

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCG 100 Y

S/n	Nature of Jobs	Estimated Charges	SURVEYOR'S RECOMMENDATION
1	To remove and transfer rear parking aid. Check function and renew according to damage.	s/n \$ 280.00 ✓	
2	To dismantle and renew rear bumper. Re-organise rear crash managements components. Reinstall all parts removed.	\$ 1,050.00 500	
3	To respray rear bumper.	\$ 900.00 550	
4	To carry out diagnostic check.	s/n \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>2,422.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCG 100 Y

S/N	Parts Description	Damaged Parts & Prices		
		S/Nett	Remark	
1	REAR BUMPER <i>rehd</i>	\$1,793.00	✓	
2	REAR BUMPER STICKY PAD	\$21.00	+	
3	REAR BUMPER FIXING PARTS <i>ma</i>	\$175.00	+	
4	REAR BUMPER GUIDE SECTION - LH / RH <i>2</i>	2	\$30.00	+
5	REAR BUMPER GUIDE PIN	2	\$53.00	+
6	REAR BUMPER SPOILER - LH		\$216.00	+
7	REAR LIGHT REFLECTOR - LH / RH		\$76.00	+
8	REAR BUMPER REINFORCEMENT BAR		\$522.00	+
9	REAR BUMPER BRACKET - LH		\$25.00	+
10	REAR BUMPER BRACKET - RH <i>HL</i>		\$26.00	+
11	REAR PARKING AID SENSOR <i>2</i>	2	\$462.00	+
12	SEAL RING	4	\$12.00	+
13	SUNDRIES ?		\$200.00 ?	
TOTAL SPARE PARTS CHARGES		:	\$3,611.00	
TOTAL LABOUR CHARGES			\$ 2,422.00	
GRAND TOTAL			\$ 6,033.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 01/08/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant