

INS. CASE OWNER:

CHAN KIAN HONG

CC 3 /AIG1901

3494, R16639

LKK:

IDAC:

Surveyor:

KASUL

DOI:

ASSIGNMENT

27/08/19

Date / Time:

1/8/19

Registered in Meritum:

1/8/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBH1231C

Name of Insured:

GREYS PIL

Insured Tel No.:

HP:

Excess Sec II :\$:

D.O.A.:

27/7/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: SCHEFFER WILLIAM ROBERT

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

6FK131B



INSRS:

WSP:

Tel:

Liability:

RMKS:

performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

PE 119-A

LHM 1191C-7

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

After call 1st to OI:

06/08/19 - VIC

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

06/08/19

- PIR REVIEWED. OLD RATE-PAID TP.
SEND LETTER 4 BUAL TO OI TO
NOTIFY TP CLAIM 4 NCD ISSUES.
- BUAL LIABILITY CLAR
- MAINTAINED
- ORIGINAL TP LOD IN

21/08/19
20/08/19

- UPLOAD 14 IN MERITUM
- AIG APPROVED MAINTENANCE
- SEND ACCEPTANCE BUAL TO TP.
- ALL BOCS IN ORDER.
- TO CLOSE.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

\$:

2,574.55

(3 days)

Reduction:

70

%

Email:

Call:

FINAL SETTLEMENT

Date/Time:

20/08/19

Confirm with:

CAROLINE

Email:

Call:

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

(w/est)

\$:

2,754.77

COD RATE-PAID TP

Loss of Rental (LOR):

\$:

-

(days)

Loss of Use (LOU):

\$:

180.00

(5 60 x 3 days)

Loss of Income (LOI):

\$:

-

(5 a days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$:

2.00

Medical:

\$:

-

Disbursement:

\$:

-

(e.g. Tow/ Independent)

Legal Cost:

\$:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4320.00

Total:

\$:

2,936.77

Global Sum \$:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

\$:

2,936.77

Name 1:

PERFORMANCE MOTORS LIMITED

Payee 2: (Strike if N.A.)

\$:

-

Name 2:

-

Payee 3: (Strike if N.A.)

\$:

-

Name 3:

-

h

Veh No: SFK 1315 Yr Regn: 2018 / max
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: B. M. W X1 SDRIVE 18I cc 1499
Colour: BLACK A/C: Insured / Std / NI / NA
Sp. Reading: 25786 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WBA JG 12630 EE 74859
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 225/50R18
R: _____

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:			
IDAC Accident Rpt:		Consistent?	Yes or No
GIA / PR Seen:		Consistent?	Yes or No
Est. Repairs:	<u>3</u>	days	Res.: Yes or No
Lum Sum:		%	3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	29/07/19	D.O.I.	27/08/19

Survey held at PERFORMANCE

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

RGAE n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PIR 42.574.53 CRAB: 46.171.75 (70%)

☐ : Prel. Report
☐ : Final Report

29

Report Format :

Lump Sum / LBJ: 13

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

☐: Interview (\$

Tech. Invs t3

☐ West end 17

Survey Fee:

Transportation:

$$S + RS \rightarrow S_2$$

3. Photons

3	Control
---	---------

1999年

BMW Dealer

Performance Motors Limited

A Sino Darby Motors Company
 Co. Reg. No. 197401000 GST Reg. No. M2-0020081-X
 Toll-Free Number 1800-2288249

101, Alexandra Road
 Sino Darby Performance Centre
 Singapore 159941
 Fax: 64747770

260, Kangkong Arang Road
 East Coast Centre
 Singapore 478180
 Fax: 63449771

119, Alexandra Road
 Sino Darby Business Centre
 Singapore 159944
 Fax: 64796601 (AfterSales)
 64796604 (Motors&I)



GST REG. NO : M2 - 0020081 - X

01 AUG 2019

ESTIMATE

Estimate No. : b1 52197 Page No. : 1 of 5
 Date Estimated : 01/08/2019
 Prepared By : Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -
 Tai Keng Hooi
 723 Bedok Reservoir Road
 #08-5180

Singapore 470723

- ACCOUNT - 40000
 Cash Sales - Service
 Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFK131B	EE74854	26/03/2018	X1 sDrive18i	0

DESCRIPTION

To replace rear bumper and R/l rear bootlid & attachment
 include knocking cause by the accident.

painting rear bumper, bootlid

To check electrical wiring systems and lightings at the
 rear section for proper function.

Sundries.

VALUE

850 2,500.00

934 1,923.00

150 171.00

40 80.00

Total Labour 1: 4,730.00

DESCRIPTION

TAILPIPE TRIM BLACK CHROME
 REAR LH BUMPER MOUNT
 REAR RH BUMPER MOUNT
 RR BUMPER CARRIER
 MOUNTING SMART OPENER
 REAR TRIM UNDERRIDE PROTECTION (X Lade -
 RR BUMPER LH CORNER MOUNTING
 RR BUMPER RH CORNER MOUNTING
 REAR BUMPER PANEL PRIMED
 REAR BUMPER MIDDLE TRIM PANEL (PDC)
 REAR BUMPER TRIM BOTTOM (LINES)
 EMBLEM GROMMET
 BMW PLAQUE WITH ADHESIVE FILM
 LETTERING X1
 REAR LH REFLECTOR
 REAR RH REFLECTOR
 ULTRASONIC SENSOR BLACK
 DECOUPING RING PDC TORQUE CONVERTER

QTY	PRIC	VALUE
1	110.55	110.55
1	160.55	160.55
1	160.55	160.55
1	493.85	493.85
1	45.30	45.30
1	105.40	105.40
1	141.90	141.90
1	141.90	141.90
1	903.40	903.40
1	265.65	265.65
1	216.00	216.00
2	0.80	1.60
1	71.25	71.25
1	64.10	64.10
1	37.90	37.90
1	37.90	37.90
4	248.70	994.80
4	5.05	20.20

Total Parts : 3,972.80

+surp

Performance Motors Limited

A Siam Derby Motors Company
Co. Reg. No. 197401859W GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2259249)



292, Alexandra Road
Siam Derby Performance Centre
Singapore 159941
Fax: 64767770

290, Kembangan Road
East Coast Centre
Singapore 438180
Fax: 63449773

333, Alexandra Road
Siam Derby Business Centre
Singapore 159944
Fax: 64766801 (AfterSales)
64766824 (Motors&S)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 52197
Date Estimated : 01/08/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFK131B	EE74854	26/03/2018	X1 sDrive18i	0

Circle CO (Third Party) Insurance / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 27/08/19 @ 1715 Excess S\$ _____

Surveyor's Name Basu Sign _____

Survey No. 90010068 Insured Yes / No _____

Approved, Lm _____ Time _____

Insured Yes / No _____ Yes / No _____

Surveyor's Email _____

No. of Working Days 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Labour 1	:	4,730.00
Parts	:	3,972.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	609.20
Grand Total	:	9,312.00

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

8,716.30

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-x



Final Report

- ESTIMATE REPAIR FOR -
Tai Keng Hooi
723 Bedok Reservoir Road
#08-5180

- ACCOUNT - 509
Cash Sales - Service
Singapore

Singapore 470723

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFK131B	WBAJG12030EE74854	26/03/2018	X1 sDrive18i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To made good rear bumper and replace damaged parts. To remove and install body parts in order to carry out painting job.	850.00	0.00	850.00 ✓
To respray rear bumper.	934.00	0.00	934.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0.00	150.00 ✓
Sundries.	40.00	0.00	40.00 ✓
REAR TRIM UNDERRIDE PROTECTION (X L	105.40	1.00	105.40 ✓
REAR BUMPER MIDDLE TRIM PANEL (PDC)	265.65	1.00	265.65 ✓
REAR BUMPER TRIM BOTTOM (LINES)	216.00	1.00	216.00 ✓
# EXPANDING RIVET BLACK	1.35	10.00	13.50 (3) ✓

SUPPLEMENTARY ITEMS

Total Labour :	1,974.00
Total Parts :	600.55
Total Repair Costs less Excess:	2,574.55
GST @7%:	180.22
Grand Total :	2,754.77

TEXT TO	DATE	TIME	INITIALS
TEXT TO	DATE	TIME	INITIALS
TEXT TO	DATE	TIME	INITIALS
TEXT TO	DATE	TIME	INITIALS
TEXT TO	DATE	TIME	INITIALS
TEXT TO	DATE	TIME	INITIALS
TEXT TO	DATE	TIME	INITIALS
TEXT TO	DATE	TIME	INITIALS
TEXT TO	DATE	TIME	INITIALS
TEXT TO	DATE	TIME	INITIALS

REC-1011-1000-10

LOSS OF USE=\$60 X 3DAYS
GIA SEARCH FEE=\$2.00

Performance Motors Limited

A member of the Sims Darby Group
Co Reg No: 197401559W. GST Reg No M2-0020081-K



Supplementary

- ESTIMATE REPAIR FOR -
Tai Keng Hooi
723 Bedok Reservoir Road
#08-5180

- ACCOUNT - 509
Cash Sales - Service
Singapore

Singapore 470723

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFK131B	WBAJG12030EE74854	26/03/2018	X1 sDrive18i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
# EXPANDING RIVET BLACK <i>MS</i>	1.35	10.00	0.00	13.50

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	13.50
Total Labour & Parts :	13.50

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 187401359W GST Reg. No. M2-0020081-X
Toll-Free Number (1800-3255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63448773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorsrad)



GST REG. NO : M2 - 0020081 - X

01 AUG 2019

ESTIMATE

Estimate No. : b1 52197
Date Estimated : 01/08/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Tai Keng Hooi
723 Bedok Reservoir Road
#08-5180

Singapore 470723

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFK131B	EE74854	26/03/2018	X1 sDrive18i	0

DESCRIPTION

To replace rear bumper and R/l rear bootlid & attachment
include knocking cause by the accident.

VALUE
850 ~~2,580.00~~

painting rear bumper, bootlid

934 ~~1,923.00~~

To check electrical wiring systems and lightings at the
rear section for proper function.

150 ~~171.00~~

Sundries.

? 80.00

Total Labour 1: 4,730.00

DESCRIPTION

TAILPIPE TRIM BLACK CHROME ?
REAR LH BUMPER MOUNT ?
REAR RH BUMPER MOUNT X
RR BUMPER CARRIER ?
MOUNTING SMART OPENER ?
REAR TRIM UNDERRIDE PROTECTION (X) Lde -
RR BUMPER LH CORNER MOUNTING ?
RR BUMPER RH CORNER MOUNTING X
REAR BUMPER PANEL PRIMED repair ✓
REAR BUMPER MIDDLE TRIM PANEL (PDC) de -
REAR BUMPER TRIM BOTTOM (LINES) scu -
EMBLEM GROMMET X
BMW PLAQUE WITH ADHESIVE FILM X
LETTERING X1 X
REAR LH REFLECTOR ?
REAR RH REFLECTOR X
ULTRASONIC SENSOR BLACK ?
DECOUPING RING PDC TORQUE CONVERTER ?

QTY	PRIC	VALUE
1	110.55	110.55
1	160.55	160.55
1	160.55	160.55
1	493.85	493.85
1	45.30	45.30
1	105.40	105.40
1	141.90	141.90
1	141.90	141.90
1	903.40	903.40
1	265.65	265.65
1	216.00	216.00
2	0.80	1.60
1	71.25	71.25
1	64.10	64.10
1	37.90	37.90
1	37.90	37.90
4	248.70	994.80
4	5.05	20.20

Total Parts : 3,972.80

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255269)



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

289, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796501 (AfterSales)
64796524 (Motors&D)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 52197**
Date Estimated : **01/08/2019**
Prepared By : **Gary Poh Chai Hoon**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFK131B	EE74854	26/03/2018	X1 sDrive18i	0

Client (C) / Direct Settlement

Page No. / Client No.

Date & Time 27/08/19 @ 1715 / Excess \$S

Surveyor's Name Basel / Sign

Surveyor's No. 90060068 / Insured / Via

Approved By / Time

Remarks / To / P&L No.

Valid Until / **3 days**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Labour 1	:	4,730.00
Parts	:	3,972.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	609.20
Grand Total	:	9,312.00

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY****

**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****

Print Received Message

This mail is associated with :

***SFK131B (8292066056SG)
[GBH1231C]**

TP
TAI KENG HOOI
Jul 29 2019 6:00PM
[GREYYS PTE LTD]
Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 20/11/2019 09:38 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2936.77) - SFK131B - Claim Handler: Chan, Kian-Meng

Approved:2936.77.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Aug 2019 Edit Reg		27 Aug 2019 00:00 Edit Adj Rpt	S\$2,574.55 Edit Estimates	S\$2,574.55 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	GREYYS PTE LTD, Co. Reg. No.: A201333907E		
Main Claimant:	TAI KENG HOOI, ID: S1669486Z		
Vehicle Reg. No.:	SFK131B	Date of Loss:	29/07/2019 18:00 - :59 [16 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8292066056SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	GBH1231C	Policy No. (Claimant):	D19MTPV01005080
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 14/08/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (20/11/2019): Alert - Adj Mandate Approved (S\$2936.77) - SFK131B - Claim Handler: Chan, Kian-M...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFK131B (8292066056SG)
[GBH1231C]
TP
TAI KENG HOOI
Jul 29 2019 6:00PM
[GREYSS PTE LTD]
Performance Motors Limited

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/10/19 09:01	Adjuster Immediate Advice	1	Load HTML

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/10/19 10:43	Odometer Reading	1	Load JPG
2	10/10/19 10:43	Chassis Number	1	Load JPG
3	10/10/19 10:44	General View	1	Load JPG
4	10/10/19 10:44	General View	1	Load JPG
5	10/10/19 10:44	General View	1	Load JPG
6	10/10/19 10:44	General View	1	Load JPG
7	10/10/19 10:44	General View	1	Load JPG
8	10/10/19 10:44	General View	1	Load JPG
9	10/10/19 10:44	General View	1	Load JPG
10	10/10/19 10:44	General View	1	Load JPG
11	10/10/19 10:44	General View	1	Load JPG
12	10/10/19 10:44	General View	1	Load JPG
13	10/10/19 10:44	General View	1	Load JPG
14	10/10/19 10:44	General View	1	Load JPG
15	10/10/19 10:44	General View	1	Load JPG
16	10/10/19 10:44	General View	1	Load JPG
17	10/10/19 10:44	General View	1	Load JPG
18	10/10/19 10:44	General View	1	Load JPG
19	10/10/19 10:44	General View	1	Load JPG
20	10/10/19 10:44	General View	1	Load JPG
21	10/10/19 10:44	General View	1	Load JPG
22	10/10/19 10:44	General View	1	Load JPG
23	10/10/19 10:44	General View	1	Load JPG
24	10/10/19 10:44	General View	1	Load JPG
25	10/10/19 10:44	General View	1	Load JPG
26	10/10/19 10:44	General View	1	Load JPG

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/08/19 14:45	TP EST & GIA REPORT	1	Load PDF
2	06/08/19 13:11	EMAIL TO OI	1	Load PDF
3	06/08/19 13:11	LETTER TO OI	1	Load PDF
4	28/08/19 18:22	TP ESTIMATE- MARKED	1	Load PDF
5	10/10/19 10:31	TP ESTIMATE - FINALIZED	1	Load PDF
6	21/10/19 08:46	TP LOD	1	Load PDF
7	22/11/19 12:38	WORKSHOP INVOICE	1	Load PDF
8	22/11/19 12:38	AUTHORISATION TO ACT FORM	1	Load PDF
9	22/11/19 12:38	Release Voucher	1	Load PDF

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
10	22/11/19 12:38	GIA SEARCH		Load PDF	
11	22/11/19 12:38	LOD		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	02/08/19 11:52	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	GBH1231C (Insd veh)	Model:	BMW X1 1.5 SDRIVE 18i (A)
	SFK131B (TP veh)		
Date of Accident:	29/07/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	9,272.94
Final Repair Cost	:	\$	2,754.77
Loss of Use	:	\$	180.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	2,936.77

3.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____
 27
 BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 2,936.77
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

22 Nov
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19013494/R1HB3Q2

Date: 22/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SFK131B

Insured Vehicle No : GBH1231C

Date of Loss: 29/07/2019

Nature of Claim: TP

Claim No: 8292066056SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFK131B

Make & Model: BMW X1, 1.5 SDRIVE 18i (A)

Engine No: F924H689B38B15A

Reg. Date: 26/03/2018 (Man. Year: 2018)

Chassis No: WBAJG12030EE74854

Colour: Black

Odometer: 35786 km

Engine Capacity: 1499 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18

Rear Tyre Size: 225/50 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,066.30	640.55	3,425.75	84.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,600.00	1,934.00	2,666.00	57.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,666.30	2,574.55	6,091.75	70.29
+ GST 7.00/7.00% (S\$)	606.64	180.22	426.42	70.29
Nett Amount (S\$)	9,272.94	2,754.77	6,518.17	70.29
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,936.77		

INSPECTION

Date of Assignment: 27/08/2019

Date Inspected: 27/08/2019 Inspected At:

Performance Motors Limited
(Alexandra)

303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*40.00 FS
2	1		*TAILPIPE TRIM BLACK CHROME	Serviceable	110.55 FS	*- FS
3	1		*REAR LH BUMPER MOUNT	Serviceable	160.55 FS	*- FS
4	1		*REAR RH BUMPER MOUNT	Serviceable	160.55 FS	*- FS
5	1		*RR BUMPER CARRIER	Serviceable	493.85 FS	*- FS
6	1		*MOUNTING SMART OPENER	Serviceable	45.30 FS	*- FS
7	1		*REAR TRIM UNDERRIDE PROTECTION (X L)	Deformed	105.40 FS	*105.40 FS
8	1		*RR BUMPER LH CORNER MOUNTING	Serviceable	141.90 FS	*- FS
9	1		*RR BUMPER RH CORNER MOUNTING	Serviceable	141.90 FS	*- FS
10	1		*REAR BUMPER PANEL PRIMED	Repair	903.40 FS	*- FS
11	1		*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Deformed	265.65 FS	*265.65 FS
12	1		*REAR BUMPER TRIM BOTTOM (LINES)	Scratched	216.00 FS	*216.00 FS
13	2		*EMBLEM GROMMET	Serviceable	1.60 FS	*- FS
14	1		*BMW PLAQUE WITH ADHESIVE FILM	Serviceable	71.25 FS	*- FS
15	1		*LETTERING X1	Serviceable	64.10 FS	*- FS
16	1		*REAR LH REFLECTOR	Serviceable	37.90 FS	*- FS
17	1		*REAR RH REFLECTOR	Serviceable	37.90 FS	*- FS
18	4		*ULTRASONIC SENSOR BLACK	Serviceable	994.80 FS	*- FS
19	4		*DECOUPING RING PDC TORQUE CONVERTER	Serviceable	20.20 FS	*- FS
20	1		*EXPANDING RIVET BLACK	Necessary	13.50 FS	*13.50 FS

F=Franchise part. S=SpcNetf.

Total Parts (\$\$) **4,066.30** **640.55**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER AND R/I REAR BOOTLID & ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT	New	2,500.00	850.00
2	PAINTING REAR BUMPER ,BOOTLID	New	1,923.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			4,600.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >