

VLC

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

363, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

01 AUG 2019

E S T I M A T E

Estimate No. : b1 52197		Page No. : 1 of 5	
Date Estimated : 01/08/2019			
Prepared By : Gary Poh Chai Hoon			

- ESTIMATE REPAIR FOR - Tai Keng Hooi 723 Bedok Reservoir Road #08-5180 Singapore 470723	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFK131B	EE74854	26/03/2018	X1 sDrive18i	0

DESCRIPTION	VALUE
To replace rear bumper and R/l rear bootlid & attachment include knocking cause by the accident.	850 2,550.00
painting rear bumper, bootlid	934 1,923.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	40 80.00
Total Labour 1:	4,730.00

DESCRIPTION	QTY	PRIC	VALUE
TAILPIPE TRIM BLACK CHROME	1	110.55	110.55
REAR LH BUMPER MOUNT	1	160.55	160.55
REAR RH BUMPER MOUNT	1	160.55	160.55
RR BUMPER CARRIER	1	493.85	493.85
MOUNTING SMART OPENER	1	45.30	45.30
REAR TRIM UNDERRIDE PROTECTION (X Lode -	1	105.40	105.40
RR BUMPER LH CORNER MOUNTING	1	141.90	141.90
RR BUMPER RH CORNER MOUNTING	1	141.90	141.90
REAR BUMPER PANEL PRIMED repair	1	903.40	903.40
REAR BUMPER MIDDLE TRIM PANEL (PDC) de -	1	265.65	265.65
REAR BUMPER TRIM BOTTOM (LINES) scu -	1	216.00	216.00
EMBLEM GROMMET	2	0.80	1.60
BMW PLAQUE WITH ADHESIVE FILM	1	71.25	71.25
LETTERING X1	1	64.10	64.10
REAR LH REFLECTOR	1	37.90	37.90
REAR RH REFLECTOR	1	37.90	37.90
ULTRASONIC SENSOR BLACK	4	248.70	994.80
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20
Total Parts :			3,972.80

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 52197	Page No. : 2 of 5
Date Estimated	: 01/08/2019	
Prepared By	: Gary Poh Chai Hoon	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFK131B	EE74854	26/03/2018	X1 sDrive18i	0

Claims OD / (3rd Party / Uninsured losses / Direct Settlement)	
Regn No. _____	Claim No. _____
Date & Time <u>27/08/19 @ 1715</u>	Excess S\$ _____
Surveyor's Name <u>RASUL</u>	Sign _____
Surveyor's Tel <u>96010068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's E-mail _____	
No. of Working Days <u>3 days</u>	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	4,730.00
Parts	:	3,972.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	609.20
Grand Total	:	9,312.00

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co Reg No. 197401559W. GST Reg No. M2-0020081-X



Final Report

- ESTIMATE REPAIR FOR -
Tai Keng Hooi
723 Bedok Reservoir Road
#08-5180

- ACCOUNT - 509
Cash Sales - Service
Singapore

Singapore 470723

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFK131B	WBAJG12030EE74854	26/03/2018	X1 sDrive18i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To made good rear bumper and replace damaged parts. To remove and install body parts in order to carry out painting job.	850.00	0.00	850.00 ✓
To respray rear bumper.	934.00	0.00	934.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0.00	150.00 ✓
Sundries.	40.00	0.00	40.00 ✓
REAR TRIM UNDERRIDE PROTECTION (X L	105.40	1.00	0.00
REAR BUMPER MIDDLE TRIM PANEL (PDC)	265.65	1.00	0.00
REAR BUMPER TRIM BOTTOM (LINES)	216.00	1.00	0.00
# EXPANDING RIVET BLACK	1.35	10.00	0.00
			105.40 ✓
			265.65 ✓
			216.00 ✓
			13.50 (S) ✓

SUPPLEMENTARY ITEMS

Total Labour :	1,974.00
Total Parts :	600.55
Total Repair Costs less Excess:	2,574.55
GST @7%:	180.22
Grand Total :	2,754.77

DD	DATE	TIME
RASHI	6/10/18	3
LINK		
FAX TO		
FAX NO		
FAX TO		
FAX NO		
CONFIRMED		
DATE		
PLD OF THE LINE BY		

LOSS OF USE=\$60 X 3DAYS
GIA SEARCH FEE=\$2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

- ESTIMATE REPAIR FOR -
Tai Keng Hooi
723 Bedok Reservoir Road
#08-5180

- ACCOUNT - 509
Cash Sales - Service
Singapore

Singapore 470723

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFK131B	WBAJG12030EE74854	26/03/2018	X1 sDrive18i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
# EXPANDING RIVET BLACK <i>me</i>	1.35	10.00	0.00	13.50

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	13.50
Total Labour & Parts :	13.50