

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

01 AUG 2019

E S T I M A T E

Estimate No. : b1 52197
Date Estimated : 01/08/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Tai Keng Hooi
723 Bedok Reservoir Road
#08-5180

Singapore 470723

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFK131B	EE74854	26/03/2018	X1 sDrive18i	0

DESCRIPTION

To replace rear bumper and R/L rear bootlid & attachment
include knocking cause by the accident .

VALUE
~~850~~ 2,550.00

painting rear bumper ,bootlid

934 1,923.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries.

? 80.00

Total Labour 1: **4,730.00**

DESCRIPTION

TAILPIPE TRIM BLACK CHROME ?
REAR LH BUMPER MOUNT ?
REAR RH BUMPER MOUNT X
RR BUMPER CARRIER ?
MOUNTING SMART OPENER ?
REAR TRIM UNDERRIDE PROTECTION (X L side) -
RR BUMPER LH CORNER MOUNTING ?
RR BUMPER RH CORNER MOUNTING X
REAR BUMPER PANEL PRIMED repair
REAR BUMPER MIDDLE TRIM PANEL (PDC) de -
REAR BUMPER TRIM BOTTOM (LINES) sun -
EMBLEM GROMMET X
BMW PLAQUE WITH ADHESIVE FILM X
LETTERING X1 X
REAR LH REFLECTOR ?
REAR RH REFLECTOR X
ULTRASONIC SENSOR BLACK ?
DECOUPING RING PDC TORQUE CONVERTER ?

QTY	PRIC	VALUE
1	110.55	110.55
1	160.55	160.55
1	160.55	160.55
1	493.85	493.85
1	45.30	45.30
1	105.40	105.40
1	141.90	141.90
1	141.90	141.90
1	903.40	903.40
1	265.65	265.65
1	216.00	216.00
2	0.80	1.60
1	71.25	71.25
1	64.10	64.10
1	37.90	37.90
1	37.90	37.90
4	248.70	994.80
4	5.05	20.20

Total Parts : **3,972.80**

Performance Motors Limited

A Sime Darby Motors Company

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**

Estimate No. : **b1 52197**
Date Estimated : **01/08/2019**
Prepared By : **Gary Poh Chai Hoon**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFK131B	EE74854	26/03/2018	X1 sDrive18i	0

Claims OD / <u>3rd Party</u> / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>27/08/19 @ 1715</u>	Excess S\$ _____
Surveyor's Name <u>RASUL</u>	Sign _____
Surveyor's Tel <u>96010568</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days Turnaround <u>3 days</u>	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Labour 1	:	4,730.00
Parts	:	3,972.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	609.20
Grand Total	:	9,312.00

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY ******** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****