

ASS. REC. BY:

REF:

CS/A1919013497/Kd3

n2

Special Instruction:

Signature:

Kenneth

ASSIGNMENT (Office)

From (Person):

Hr Yinnul

of

A19

Date/Time:

31/7/19 1:35pm

Estimated Cost:

Bill to:

OD - TP - WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 6388Y

Insured:

SLR 1553C

at Workshop m/s

Yee Auto

Tel:

6457 5768 / 2625

of

160 Sin Ming Drive #02-17

Policy No:

Claim No:

4545042335 S9003

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29/7/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

up?

H.O.D. Endorsement:

Date/Time:

10:22am @ 1/8/19

Person Contacted:

Mr Chan

Vehicle IN (OUT)

Date/Time

Action/Instruction

Initials

✓

SLR 1553C -X

GBD 6388Y -X

6/9/19

8 885-cv email confirmed by email (Ref 9392.80, 9110) (NO LS)

ASS. REC. BY:

REF:

A/G/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ Yee Ato

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBD 6388Y Yr Regn: 04, 16

Type: M.Car / M.Cycle / Bus (Van) / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS NV350 c.c. 2488

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 155833 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNIMC 2E268.0002208

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 1P5R15X8

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 9 mm R/Bal. 4 mm

L/Bal. 9 mm L/Bal. 4 mm

D.O.A. 29/7/19 D.O.I. 1/8/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

NIS Fr body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

RECEIVED 09 SEP 2019

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: 3

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) 9/9 - typist

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

250

11

261

Report Format :

Merimen

Lump Sum / I.B.I. (\$) 885/2

PRE-REPAIR INSPECTION REQUEST – GBD6388Y vs SLR1553C (OI) on D.O.A.: 29/07/2019

From: "Hor, Yinnul"
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin
Sent: 7/31/2019 4:35:20 PM

Hi,

Please refer to the enclosed request from **BONNIE KWOK LLC**.

Claim no : 4545042335SG003
Case Owner : Norsiah Bte Md Noor

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yin Rui (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Yinnul.Hor@aig.com | www.aig.sg

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: Wednesday, July 31, 2019 2:44 PM
To: Hor, Yinnul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin; yeeauto pte ltd
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLR1553C AND GBD6388Y ON 29/07/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sirs,

Our client agrees to LKK Auto Consultants as the Single Joint Expert (SJE).

Please let us have their report in due course.

Kindly request for the SJE to contact the repairers, M/s Yee Auto Pte Ltd at 6457 5768 to make the necessary arrangements.

Regards,
ST

--

BONNIE KWOK LLC
Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Tue, 30 Jul 2019 at 16:31, Hor, Yinnul <Yinnul.Hor@aig.com> wrote:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่านมัน
ให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-08-06 16:31 +08 to read your message. After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinru.Hor@aig.com

To: litigation@bonniekwok.com

Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, NoorMariasa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Divyashni.Subramaniam@aig.com, Wahxin.Tong@aig.com

Subject: aigencrypl PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLR1553C AND GBD6388Y ON 29/07/2019

Date: Tue, 30 Jul 2019 08:31:04 +0000

Without Prejudice

Your Reference : GBD6388Y

Our Reference : SLR1553C

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rui (Viviane)

AIG

FNOL Adjuster I

Singapore FNOL | Claims Operations – Auto

Yinru.Hor@aig.com | www.aig.sg

From: bonnie kwok [mailto:litigation@bonniekwok.com]

Sent: Tuesday, July 30, 2019 3:03 PM

To: AIG SGP, Claims-Survey

Subject: [EXTERNAL] PRI - Acc Inv: GBD 6388 Y & SLR 1553 C ON 29 JULY 2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle GBD 6388 Y at M/s Yee Auto Pte Ltd, 160 Sin Ming Drive #02-17 Sin Ming Autocity Singapore 575722. Contact number 6457 5768.

Regards,
June

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

Virus-free. www.avg.com

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 6 September 2019 2:25 PM
To: yeeauto pte ltd; Kenneth Kong (LKKAUTO); SUR
Subject: RE: GDB6388Y (Nissan NV350) After Repair Photo

Dear Ms Phang,

Noted with thanks.

Kindly send Final invoice and all supporting documents directly to AIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: yeeauto pte ltd <yeeautopteltd@gmail.com>
Sent: Friday, 6 September 2019 2:05 PM
To: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Re: GDB6388Y (Nissan NV350) After Repair Photo

Hi Kenneth,

We accept amount \$885/- (before GST) & 03 working days.

Thanks & Regards

Ms Phang

Yee Auto Pte Ltd

160 Sin Ming Drive

#02-17 Sin Ming AutoCity

Singapore 575722

ROC & GST No.: 201719251W

email: yeeautopteltd@gmail.com

On Wed, 4 Sep 2019 at 08:25, Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com> wrote:

Attach finalised for GBD 6388Y.

From: yeeauto pte ltd [<mailto:yeeautopteltd@gmail.com>]
Sent: Tuesday, 3 September, 2019 4:13 PM
To: SUR; Kenneth Kong (LKKAUTO)
Subject: Re: GDB6388Y (Nissan NV350) After Repair Photo

Reminder

Yee Auto Pte Ltd

160 Sin Ming Drive

#02-17 Sin Ming AutoCity

Singapore 575722

ROC & GST No.: 201719251W

email: yeeautopteltd@gmail.com


On Wed, 28 Aug 2019 at 10:46, yeeauto pteltd <yeeautopteltd@gmail.com> wrote:


Good day Sir


As per attached for your reference and action.


Thanks & Regards


Ms Phang


_IMG_8889.JPGError! Filename not specified.


_IMG_8891.JPGError! Filename not specified.


_IMG_8893.JPGError! Filename not specified.

_IMG_8894.JPGError! Filename not specified.

_IMG_8895.JPGError! Filename not specified.

_IMG_8896.JPGError! Filename not specified.

_IMG_8897.JPGError! Filename not specified.

_IMG_8898.JPGError! Filename not specified.

Yee Auto Pte Ltd

160 Sin Ming Drive

#02-17 Sin Ming AutoCity

Singapore 575722

ROC & GST No.: 201719251W

email: yeeautopteltd@gmail.com



Virus-free. www.avg.com



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 29/07/2019
TP Veh Reg No: SLR1553C

Estimate No: ES1900044
Date: 01 Aug 2019
Policy No:
Veh Reg No: GBD6388Y
Make/Model: NISSAN NV350 PANEL
VAN 2.5 5MT 5DR EURO
V
Chassis No: JN1MC2E26Z0002208
Engine No: YD25350365A
Reg. Date: 26/06/2014

Estimate Repair Cost to Vehicle No :GBD6388Y

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 10,277.80
			Add GST @ 7%	719.45
			Total Amount Payable	SS 10,997.25

TOTAL: SINGAPORE DOLLAR TEN THOUSAND NINE HUNDRED NINETY SEVEN AND CENTS TWENTY FIVE ONLY

For Yee Auto Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19013497/KVD3N2

Date: 11/09/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	GBD6388Y	Insured Vehicle No :	SLR1553C
Date of Loss:	29/07/2019	Nature of Claim:	TP
		Claim No:	4545042335SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD6388Y		
Make & Model:	NISSAN NV350, 2.5 5MT 5DR EURO V (A)		
Reg. Date:	26/06/2014 (Man. Year: 2014)	Engine No:	YD25350365A
Colour:	Metallic Grey	Chassis No:	JN1MC2E26Z0002208
Engine Capacity:	2488 cc	Odometer:	155633 km
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,497.80	175.00	7,322.80	97.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	710.00	2,070.00	74.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	10,277.80	885.00	9,392.80	91.39
+ GST 7.00/7.00% (\$\$)	719.45	61.95	657.50	91.39
Nett Amount (\$\$)	10,997.25	946.95	10,050.30	91.39

INSPECTION

Date of Assignment:	31/07/2019	
Date Inspected:	01/08/2019	Inspected At:
		Yee Auto Pte Ltd (HQ) 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Serviceable	572.80 FS	*- FS
2	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
3	1		*FRONT BUMPER SIDE RETAINER-LH	Serviceable	137.20 FS	*- FS
4	1		*FRONT BUMPER FOG LAMP GARNISH-LH	Serviceable	85.00 FS	*- FS
5	1		*FRONT DOOR-LH	Repair	1,668.50 FS	*- FS
6	1		*FRONT DOOR WEATHERSTRIP-LH	Serviceable	125.60 FS	*- FS
7	1		*FRONT DOOR HINGE BOTTOM-LH	Repair	82.50 FS	*- FS
8	1		*FRONT DOOR HINGE TOP-LH	Repair	82.50 FS	*- FS
9	1		*FRONT DOOR INNER TRIM-LH	Serviceable	420.00 FS	*- FS
10	1		*FRONT DOOR LOCK-LH	Repair	320.00 FS	*- FS
11	1		*FRONT DOOR MOTOR	Serviceable	350.00 FS	*- FS
12	1		*FRONT DOOR REGULATOR-LH	Repair	280.00 FS	*- FS
13	1		*FRONT HEADLAMP-LH	Serviceable	858.40 FS	*- FS
14	1		*FRONT STEP GARNISH-LH	Serviceable	185.30 FS	*- FS
15	1		*FRONT DOOR STICKER-LH	Necessary	40.00 FS	*25.00 FS
16	1		*SLIDING DOOR-LH	Repair	1,890.00 FS	*- FS
17	1		*SLIDING DOOR STICKER-LH	Necessary	350.00 FS	*150.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					7,497.80	175.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY	New	1,200.00	300.00
2	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,200.00	400.00
3	TO APPLY RUST-PROOFING ON REPAIRED,REPLACED PANEL	New	120.00	0.00
4	TO REMOVE/TRANSFER FRONT DOOR AND SLIDING DOOR COMPONENTS	New	200.00	0.00
5	TO CHECK WIRING FUNCTIONS	New	60.00	10.00
Gross Labour Cost (\$\$)			2,780.00	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >