



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19013498/R1pa3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 23-03-2020



ATTN: KIAN CHUAN

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SKX 8729Y	<b>Veh. Inspected</b>	SLV 8977X
<b>Policy No.</b>	VA1/GA301882	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S9M01VZ1	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	KIAN CHUAN	<b>Assign Date</b>	05/08/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA JAZZ 1.3 CVT	<b>c.c</b>	1318
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
<b>Chassis No.</b>	JHMGK3850JX204808	<b>Colour</b>	BLUE
<b>Odometer</b>	023407	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	175/65 R15	YOKOHAMA	5 mm
<b>L/H Front Tyre</b>	175/65 R15	YOKOHAMA	5 mm
<b>R/H Rear Tyre</b>	175/65 R15	YOKOHAMA	5 mm
<b>L/H Rear Tyre</b>	175/65 R15	YOKOHAMA	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	02/08/2019	<b>Inspection Date</b>	09/09/2019
<b>Survey held at</b>	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**