

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 649C**AAD1907-269***Not Authorized
11 Sep @ 23501*

Vehicle No.:

Chassis No.:

Vehicle Make:

31 JUL 2019

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHF 649C

VF1ABL15AUC278383

RENAULT

LATITUDE

29.7.19

III

30/6/2014

	PART
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER INSULATOR RH
1	TOW COVER FRT
1	FRONT BRACE PANEL
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET
1	BONNET
1	BONNET INSULATOR
1	BONNET STRUT LH
1	BONNET STRUT RH
1	BONNET HINGE LH

	LIST
\$	Bu 1,259.42 ✓
\$	SL 181.75 X
\$	SL 394.68 X
\$	Dis 151.41 ✓
\$	SL 123.88
\$	SL 472.83
\$	SL 266.80
\$	SL 207.21
\$	N 914.08
\$	SL 1,184.43
\$	N 152.15
\$	N 783.83 ✓
\$	SL 278.84
\$	SL 15.79
\$	SL 130.84
\$	SL 28.61
\$	N 177.22
\$	SL 1,707.78
\$	SL 225.36
\$	SL 1,353.75
\$	N 615.90
\$	N 89.79
\$	N 1,941.63
\$	SL 405.73
\$	SL 88.61
\$	SL 88.61
\$	N 348.31

Trans-cab Auto Services Pte Ltd

AAD1907-269

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 649C

1	BONNET HINGE RH	\$	Rs	348.31	}	X	
1	BONNET LOCK	\$	Rs	305.48			
1	BONNET CABLE	\$	Rs	119.19			
1	BONNET CABLE COVER	\$	Rs	161.03			
1	BONNET SEAL OUTER	\$	Rs	92.36			
1	BONNET SEAL INNER	\$	Rs	157.28			
1	WIPER RESERVOIR MOTOR	\$	Rs	270.06			
1	WIPER RESERVOIR	\$	Rs	348.25			
1	WIPER RESERVOIR NECK	\$	Rs	136.11			
TOTAL		\$		15,527.30			
10%		\$		1,552.73			
		\$		13,974.57			

Special Nett

1	BUMPER CLIP FRT	\$	Rs 66.00	}	X
1	BUMPER BRACKET CLIP FRT RH	\$	Rs 12.00		
1	BUMPER SUPPORT CLIP FRT RH	\$	Rs 10.50		
1	BUMPER GRILLE LOWER CLIP	\$	Rs 69.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	Rs 70.00		
2	FRAME FULL SUPPORT PANEL NUT	\$	Rs 20.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	Rs 30.00		
1	WHEELARCH CLIP FRT RH	\$	Rs 30.50		
1	FRONT RIGHT TYRE	\$	Rs 300.00		
1	FRONT RIGHT TYRE RIM	\$	Rs 380.00		
1SET	Front licence plate with holder	\$	Rs 80.00		
1SET	RADIATOR GRILLE SCREW	\$	Rs 16.00		
1SET	RADIATOR GRILLE FRAME CLIP	\$	Rs 52.00		
1	WINDSCREEN SEALANT	\$	Rs 253.80		
1	FRONT WINDSCREEN MOULDING	\$	Rs 120.00		
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	Rs 100.00		
6	BONNET INSULATOR CLIP L70Y	\$	Rs 7.30		
2	BONNET STRUT L70Y	\$	Rs 88.61		
2	BONNET CABLE CLIP L70Y	\$	Rs 6.31		
2	BONNET CABLE COVER SCREW L70Y	\$	Rs 10.85		
TOTAL		\$	1,722.88		
TOTAL PARTS		\$	15,697.45		

Trans-cab Auto Services Pte Ltd

AAD1907-269

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 649C

LABOUR

Putty and spray painting of the affected portion.	\$	6,000.00	4401
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	4001
To rust-proofing of the affected areas.	\$	170.00	301
To transfer of front windscreen fittings and conduct water seepage test.	\$	na 170.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	5 380.00	X
To check steering geometry and computer wheel alignment	\$	5 220.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	5 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	5 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	5 170.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	5 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	101
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	na 380.00	X

Trans-cab Auto Services Pte Ltd

AAD1907-269

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 649C

TOTAL	\$	15,180.00
-------	----	-----------

Over All Total	\$	30,877.45
----------------	----	-----------

LUMP SUM (REPAIR DAY)

~~20 DAYS~~

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: