

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
 GST:201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD  
 64 CECIL STREET  
 #04/#05 IOB BUILDING  
 SINGAPORE 049711

TEL: 63476100 FAX: 62244174  
 ATTN: Motor Claim Department

Estimate No: EST1900235  
 Date: 31 Jul 2019

Veh Reg No: SML7308A  
 Make/Model: TOYOTA ESQUIRE  
 HYBRID 7 SEATER  
 1.8GL CVT

Chasis No: ZWR800358335  
 Reg. Date: 31/05/2019  
 Your Ref No: SHD4953H

Claim Type: Third Party  
 Accident Date: 27/07/2019  
 TP Veh Reg No: SHD4953H

*Yiao Tony*

## Estimate Repair Cost to Vehicle No :SML7308A

Quantity	Description	List Price	Amount
		SS	SS
<b>List Price</b>			
1	1 PC REAR BUMPER <del>100</del> Repair	1,675.80 <del>100</del>	
2	1 PC REAR BUMPER SIDE RETAINER <del>100</del>	132.70 <del>100</del>	
3	1 PC REAR AXLE	2,648.70 +	
4	1 PC REAR WHEEL HUB } <i>100</i>	923.30 +	
5	1 PC REAR SHOCK ABSORBER	339.30 -	
		5,719.80	
		Less 25%	4,289.87
<b>Special Net</b>			
6	1 SET REAR BUMPER CLIPS <i>100</i>	60.00 <del>100</del> 30	
7	1 PC REAR SPORT RIM <i>100</i>	900.00 <del>100</del> 750	
8	1 PC REAR TYRE <del>100</del> <i>100</i>	400.00 <del>100</del> 250	
		1,360.00	1,360.00
<b>Labour</b>			
9	1 TO CHECK WIRING	50.00 <del>100</del> 30	
10	1 TO CHECK WHEEL ALIGNMENT	120.00 <del>100</del> 80	
11	1 TO REMOVE AND REFIT UNDERCARRIAGE	500.00 +	
12	1 (REAR) TO SPRAY PAINTING	700.00 <del>100</del> 500	
13	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	700.00 <del>100</del> 300	
14	1 TO REMOVE AND REFIT INNER TRIM	150.00 <del>100</del> 60	
		2,220.00	2,220.00

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD  
64 CECIL STREET  
#04/#05 IOB BUILDING  
SINGAPORE 049711  
TEL: 63476100 FAX: 62244174  
ATTN: Motor Claim Department

Estimate No: EST1900235  
Date: 31 Jul 2019  
Veh Reg No: SML7308A  
Make/Model: TOYOTA ESQUIRE  
HYBRID 7 SEATER  
1.8GL CVT  
Chasis No: ZWR800358335  
Reg. Date: 31/05/2019  
Your Ref No: SHD4953H

Claim Type: Third Party  
Accident Date: 27/07/2019  
TP Veh Reg No: SHD4953H

## Estimate Repair Cost to Vehicle No :SML7308A

Quantity	Description	List Price	Amount
		SS	SS
		Total	SS 7,869.87
		Add GST @ 7%	550.89
		Total Amount Payable	SS 8,420.76

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND FOUR HUNDRED TWENTY AND CENTS SEVENTY SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

total. 2000  
CP/P?

210

Adrian Lj  
4/5 05/08/19.

04 Days.