

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST: 201300201N

M/S: INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL STREET
 #04/#05 IOB BUILDING
 SINGAPORE 049711

TEL: 63476100 FAX: 62244174
 ATTN: Motor Claim Department

Estimate No: EST1900235
 Date: 31 Jul 2019

Veh Reg No: SML7308A
 Make/Model: TOYOTA ESQUIRE
 HYBRID 7 SEATER
 1.8GL CVT

Chasis No: ZWR800358335
 Reg. Date: 31/05/2019
 Your Ref No: SHD4953H

Claim Type: Third Party
 Accident Date: 27/07/2019
 TP Veh Reg No: SHD4953H

Yiao Tony

Estimate Repair Cost to Vehicle No :SML7308A

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC REAR BUMPER <i>Repair</i>	1,675.80	1,675.80
2	1 PC REAR BUMPER SIDE RETAINER <i>Repair</i>	132.70	132.70
3	1 PC REAR AXLE	2,648.70	2,648.70
4	1 PC REAR WHEEL HUB	923.30	923.30
5	1 PC REAR SHOCK ABSORBER	339.30	339.30
		5,719.80	
	Less 25%	1,429.95	4,289.87
Special Net			
6	1 SET REAR BUMPER CLIPS <i>Repair</i>	60.00	60.00
7	1 PC REAR SPORT RIM <i>Lot</i>	900.00	900.00
8	1 PC REAR TYRE <i>Repair</i>	400.00	400.00
		1,360.00	1,360.00
Labour			
9	1 TO CHECK WIRING	50.00	50.00
10	1 TO CHECK WHEEL ALIGNMENT	120.00	120.00
11	1 TO REMOVE AND REFIT UNDERCARRIAGE	500.00	500.00
12	1 (REAR) TO SPRAY PAINTING	700.00	700.00
13	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	700.00	700.00
14	1 TO REMOVE AND REFIT INNER TRIM	150.00	150.00
		2,220.00	2,220.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
TEL: 63476100 FAX: 62244174
ATTN: Motor Claim Department

Estimate No: EST1900235
Date: 31 Jul 2019
Veh Reg No: SML7308A
Make/Model: TOYOTA ESQUIRE
HYBRID 7 SEATER
1.8GL CVT
Chasis No: ZWR800358335
Reg. Date: 31/05/2019
Your Ref No: SHD4953H

Claim Type: Third Party
Accident Date: 27/07/2019
TP Veh Reg No: SHD4953H

Estimate Repair Cost to Vehicle No :SML7308A

Quantity	Description	List Price	Amount
		SS	SS
		Total	S\$ 7,869.87
		Add GST @ 7%	550.89
		Total Amount Payable	S\$ 8,420.76

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND FOUR HUNDRED TWENTY AND CENTS SEVENTY SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 2000
CP/P?

2/c

Adrian Lj
4/s 05/08/19.
04 Days.