

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 7799A

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|---------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 2 | CANOE RIVET BUMPER @\$6.50 (CONSISTENT) (N) | NECESSARY | 13.00 | 13.00 |
| 4 | GROMMET BUMPER @\$2.50 (CONSISTENT) (N) | NECESSARY | 10.00 | 10.00 |
| 1 | STAY ASSY-REAR RH (CONSISTENT) (N) | NOT NECESSARY | 126.00 | - |
| 1 | STAY ASSY-REAR LH (CONSISTENT) (N) | NOT NECESSARY | 126.00 | - |
| 1 | REINF-BUMPER RR (CONSISTENT) (N) | NOT NECESSARY | 619.20 | - |
| 1 | ENERGY ABSORBER (CONSISTENT) (N) | NOT NECESSARY | 126.40 | - |
| 1 | BRACKET -BUMPER RH (CONSISTENT) (N) | NOT NECESSARY | 35.90 | - |
| 1 | BRACKET -BUMPER LH (CONSISTENT) (N) | NOT NECESSARY | 35.90 | - |
| 1 | RETAINER -BUMPER RH (CONSISTENT) (N) | NOT NECESSARY | 23.80 | - |
| 1 | RETAINER -BUMPER LH (CONSISTENT) (N) | NOT NECESSARY | 23.80 | - |
| 3 | CLIP BUMPER @\$7.40 (CONSISTENT) (N) | NECESSARY | 22.20 | 22.20 |
| 1 | FASCIA-RR BUMP (CONSISTENT) (N) | DEFORMED | 717.00 | 717.00 |
| | LESS 20% DISCOUNT | | -375.84 | -152.44 |
| | ADDITIONAL 5% DISCOUNT | | - | -30.49 |
| | | | 1,503.36 | 579.27 |
| | SPECIAL NETT ITEMS | | | |
| 1 | SUNDRIES (CONSISTENT) (SN) | NOT NECESSARY | 100.00 | - |
| 2 | GROMMET BUMPER @\$2.20 (CONSISTENT) (SN) | NECESSARY | 4.40 | 4.40 |
| 1 | REVERSE SENSOR (J11 & T32) (CONSISTENT) (SN) | NOT NECESSARY | 210.00 | - |
| | | | 314.40 | 4.40 |
| | LABOUR | | | |
| | PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL. | NOT NECESSARY | 120.00 | - |
| | SUPPLY & INSTALL REVERSE SENSOR . | | 110.00 | 110.00 |
| | APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA. | NOT NECESSARY | 100.00 | - |
| | REPAIR END PANEL AND RENEW REAR BUMPER. | | 700.00 | 250.00 |
| | S/PAINT REAR BUMPER (2 TONE) AND END PANEL. | | 800.00 | 300.00 |
| | ADDITIONAL 5% DISCOUNT | | | -33.00 |
| | | | 1,830.00 | 627.00 |

Report Ref No. CC4/ASM19013506/T1ps3q2



Page No.:2 of 2

| GRAND TOTAL | 3,647.76 | 1,210.67 |
|-----------------------------|----------|----------|
| | | |
| RECOMMENDED COST OF REPAIRS | | 1.210.67 |

Report Ref No. CC4/ASM19013506/T1ps3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

mont

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.