

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0387/2019
DATE : 31-JUL-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MISS NG LAI MING
ADDRESS : BLK 143 MEI LING STREET
#10-153
S(140143)
TELEPHONE NO : 91083199

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-FBG7519P
VEHICLE NO : SLV7799A
MODEL CODE : FRLARDWJ11USA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2017
ENGINE NO : HRA2538715A-BC
CHASSIS NO : SJNFEAJ11U2135088
MILEAGE : 1 KM
DATE IN : 31/07/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 26/07/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832

FAX : 64697472

31/07/19.

LKK

26/08/19

APM
2pm

Tanfik 97495749
6/8/19 @ 2pm

Resurvey before print

sur@lkkauto.com
tanfik@lkkauto.com
02days

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLV7799A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X
2	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	✓
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X
4	ZZ/001	REPAIR END PANEL AND RENEW REAR BUMPER	700.00	240
5	ZZ/002	S/PAINT REAR BUMPER (2 TONE) AND END PANEL	800.00	300
TOTAL LABOUR CHARGES			1830.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV7799A

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 SUNDRIES	NPN			100.00 ?
2 CANOE RIVET BUMPER \$6.50 EA X 02	76882-0M000	13.00	hel	
3 GROMMET BUMPER \$2.50 EA X 04	63846-5V000	10.00	hel	
4 GROMMET BUMPER \$2.20 EA X 02	01281-00111			4.40 hel
5 STAY ASSY-REAR RH	H5210-4EAMA	126.00	?	
6 STAY ASSY-REAR LH	H5211-4EAMA	126.00	?	
7 REINF-BUMPER RR	H5030-4EAMA	619.20	?	
8 ENERGY ABSORBER	85090-HV00A	126.40	?	
9 BRACKET-BUMPER RH	85220-4EA0A	35.90	?	
10 BRACKET-BUMPER LH	85221-4EA0A	35.90	?	
11 RETAINER-BUMPER RH	79184-4EA0A	23.80	?	
12 RETAINER-BUMPER LH	79185-4EA0A	23.80	?	
13 CLIP BUMPER \$7.40 EA X 03	85284-JD00A	22.20	hel	
14 FASCIA-RR BUMP	85022-HV00H	717.00	hel	
15 REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			210.00 ?
SUB TOTAL		1879.20	0.00	314.40
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		375.84	0.00	0.00
GRAND TOTAL		1503.36	0.00	314.40
OVERALL TOTAL		1817.76		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLV7799A

TOTAL LABOUR CHARGES	1830.00
TOTAL SPARE PARTS CHARGES	1817.76

GRAND TOTAL	3647.76 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.