

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/0926/2019/NS  
Date : 30-Jul-19

**Vehicle NOT IN workshop. Kindly arrange for survey.**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR LEMOINE PIERRE MICHEL LOUIS  
Address : 7 OCEAN WAY RESIDENCES AT W SINGAPORE SENTOSA COVE  
Singapore 098367  
Telephone : 96659935  
Type of Claim : Own Damage Claims  
Policy No. : 1800110100-01  
Vehicle No : **SME 365 S**  
Model Code : Audi A5 SB 2.0 TFS  
Model / Year : 14/9/2018  
Engine No : CVK 067189  
Chassis No : WAUZZZF54JA127802  
Mileage :  
Date In :  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 27-Jul-19  
Place of Accident : BUKIT MERAH

Adrian Ling  
01/08/19.

07899.

Not Authorised.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SME 365 S

| S/n                       | Nature of Jobs                                                                                                                                          | Estimated Charges    | Surveyor's Recommendation |
|---------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------------|
| 1                         | To remove and reinstall rear parking aid and rear lid kick sensor. Check function                                                                       | S/N \$ 360.00        | X                         |
| 2                         | To renew rhs 1/4 glass to facilitate fender renewal.                                                                                                    | S/N \$ 300.00        | X                         |
| 3                         | To remove and transfer rhs rear door's multi-lock system and power window devices. Inspect for damages                                                  | S/N \$ 360.00        | ✓                         |
| 4                         | To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.                          | S/N \$ 1,400.00      | X                         |
| 5                         | To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag. | S/N \$ 1,400.00      | X                         |
| <b>SUB LABOUR CHARGES</b> |                                                                                                                                                         | <b>: \$ 3,820.00</b> |                           |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SME 365 S

| S/n                         | Nature of Jobs                                                                                                                                                                                                             | Estimated Charges     | Surveyor's Recommendation |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|---------------------------|
| 6                           | To dismantle rear bumper, rear lid, rhs sill panel trim and rhs rear door. Cut out and weld rhs rear fender. Renew rhs door and rhs sill panel trim. Re-organise crash management components. Reinstall all parts removed. | \$ 8,000.00           | 1500                      |
| 7                           | To respray rear bumper, rhs rear fender, rhs rear door, rhs sill panel, rhs sill panel trim, door entrances, roof channel, drain panel and end panelling. To carry out joint sealer works.                                 | \$ 6,700.00           | <del>2200</del> 1650 .    |
| 8                           | To renew rhs rear rim and carry out wheel alignment.                                                                                                                                                                       | S/N \$ 280.00         | ✓                         |
| 9                           | To carry out diagnostic check.                                                                                                                                                                                             | S/N \$ 192.00         | ✓                         |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                            | <b>: \$ 18,992.00</b> |                           |

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax****Material List for Accident Vehicle Regn No. SME 365 S**

| S/N                         | Parts Description                                              | Damaged Parts & Prices |        |
|-----------------------------|----------------------------------------------------------------|------------------------|--------|
|                             |                                                                | S/Nett                 | Remark |
| 1                           | REAR DOOR - RH <i>Dented</i>                                   | \$ 2,829.00            | ✓      |
| 2                           | OUTER DOOR SEAL - RH <i>NEC</i>                                | NEC \$ 201.00          | ✓      |
| 3                           | BONDING AGENT <i>?</i>                                         | NEC \$ 45.00           | ?      |
| 4                           | CLEANING SOLUTION <i>?</i>                                     | NEC \$ 65.00           | ?      |
| 5                           | DOOR ATTACHMENT PARTS <i>?</i>                                 | \$ 117.00              | ?      |
| 6                           | DOOR CATCH <i>New</i>                                          | \$ 109.00              | ✓      |
| 7                           | SIDE MEMBER TRIM - RH <i>Del-d</i>                             | \$ 754.00              | ✓      |
| 8                           | ATTACHMENT PARTS <i>?</i>                                      | NEC \$ 118.00          | ?      |
| 9                           | ADHESIVE TAPES <i>New</i>                                      | NEC \$ 192.00          | ✓      |
| 10                          | REAR FENDER SIDE PANEL - RH <i>Repair</i>                      | \$ 2,285.00            | x      |
| 11                          | RIVETTED CAP NUT <i>?</i>                                      | NEC \$ 2.00            | +      |
| 12                          | SIDE WINDOW - RH <i>New</i>                                    | \$ 653.00              | +      |
| 13                          | CLIP NUT                                                       | NEC \$ 2.00            | +      |
| 14                          | WHEEL HOUSING LINER - RH <i>New</i>                            | \$ 256.00              | x      |
| 15                          | WHEEL HOUSING LINER ATTACHMENT PARTS - FRONT / REAR <i>New</i> | \$ 82.00               | +      |
| 16                          | REAR BUMPER GUIDE SECTION - RH <i>New</i>                      | \$ 35.00               | +      |
| 17                          | ALUMINIUM RIM <i>Lot</i>                                       | \$ 943.00              | ✓      |
| 18                          | RUBBER VALVE <i>New</i>                                        | 4 \$ 13.00             | +      |
| 19                          | 1/4 GLASS SEALANT <i>3 New</i>                                 | S/N \$ 100.00          | x      |
| 20                          | ACRYLIC SEALANT                                                | S/N \$ 180.00          | +      |
| 21                          | CAVITY WAX <i>3 New</i>                                        | S/N \$ 140.00          | x      |
| 22                          | STONE CHIP                                                     | S/N \$ 180.00          | +      |
| 23                          | METAL FILLER POWDER <i>New</i>                                 | S/N \$ 280.00          | +      |
| 24                          | SUNDRIES <i>?</i>                                              | \$ 500.00              | ?      |
| <b>TOTAL SPARE PARTS</b>    |                                                                | <b>\$ 10,081.00</b>    |        |
| <b>TOTAL LABOUR CHARGES</b> |                                                                | <b>\$ 18,992.00</b>    |        |
| <b>GRAND TOTAL</b>          |                                                                | <b>\$ 29,073.00</b>    |        |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.