



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD
1 RAFFLES QUAY #29-10 SOUTH TOWER
SINGAPORE 048583

INV No. AC2004107
INV Date 22/05/2020
Reference CC6/QBE19013516/Ads3n2
Code QBE



PROFESSIONAL SERVICE FEE

Vehicle No. SJT 1597P
Insured Veh. GBB 3137K
Claim No. VC012778
Policy No. 8-V0015675-MVA-R001
Accident Date 15/07/2019
Inspection Date 31/07/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC6/QBE19013516/Ads3n2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 22-05-2020



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 3137K	Veh. Inspected	SJT 1597P
Policy No.	8-V0015675-MVA-R001	Coverage (\$)	0.00
Claim No.	VC012778	Excess (\$)	0.00
Assign From		Assign Date	31/07/2019

2. Vehicle Particulars & Condition

Make & Model	AUDI A6	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WAUZZZ4F9AN008843	Colour	SILVER
Odometer	236630	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/35 R19	KAPSEN	6 mm
L/H Front Tyre	255/35 R19	KAPSEN	6 mm
R/H Rear Tyre	255/35 R19	KAPSEN	6 mm
L/H Rear Tyre	255/35 R19	KAPSEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/07/2019	Inspection Date	31/07/2019
Survey held at	GREEN FOREST AUTOMOBILE 8 KAKI BUKIT AVENUE 4 #05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 1597P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID EMBLE LOGO	NOT NECESSARY	82.00	-
1	REAR BOOT LID A6 LOGO	NOT NECESSARY	59.00	-
1	REAR BOOT LID 2.0 LOGO	NOT NECESSARY	59.00	-
1	REAR BUMPER	DEFORMED	1,760.00	1,760.00
4	REAR BUMPER REVERSE SENSOR @\$235.00	NOT NECESSARY	940.00	-
2	REAR BUMPER SIDE BRACKET @\$38.00	NOT NECESSARY	76.00	-
1	REAR BUMPER LOWER GARNISH	CUT	582.00	305.00
10	REAR BUMPER CLIPS @\$6.00	NECESSARY	60.00	30.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	710.00	-
2	REAR BUMPER REINFORCEMENT BRACKET @\$165.00	NOT NECESSARY	330.00	-
	LESS 10% DISCOUNT		-	-209.50
			4,658.00	1,885.50
LABOUR				
	TO REMOVE & REFIX FRONT & REAR REVERSE SENSOR .		100.00	50.00
	TO REMOVE & REFIX CUSHION .	NOT NECESSARY	100.00	-
	TO CHECK WIRING SYSTEM.		60.00	30.00
	TUFF KOTE.	NOT NECESSARY	100.00	-
	PANEL BEATING.		450.00	200.00
	SPRAY PAINTING.		450.00	200.00
			1,260.00	480.00
GRAND TOTAL			5,918.00	2,365.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,800.00

Report Ref No. CC6/QBE19013516/Ads3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJT 1597P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

