

# GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

SYLLYS AUTO PTE LTD  
8 KAKI BUKIT AVE 4  
# 05-25 PREMIER @ KB  
Singapore 415875

TP QBE  
Jia le

31<sup>st</sup> JULY 2019

Accident date: 15<sup>th</sup> JULY 2019  
Estimated repair cost for vehicle no: SJT1597P AUDI A6 2.0 '09

S/n	Qty	Items	U/price	Amount
27	1	Rear Boot Lid emble logo		\$82.00 ✓
38	1	Rear boot lid A6 logo		\$59.00 ✓
39	1	rear boot Lid 2.0 logo		\$59.00 ✓
40	1	Rear bumper <i>deland</i>		\$1,760.00 ✓
41	4	Rear bumper reverse sensor	\$235.00	\$940.00 ✓
42	2	Rear Bumper Side Bracket	\$38.00	\$76.00 ✓
43	1	Rear bumper reinforcement		\$710.00 ✓
44	2	Rear bumper reinforcement bracket	\$165.00	\$330.00 ✓
48	1	Rear bumper lower garnish <i>lit</i>		<del>\$582.00</del> 305
49	10	Rear bumper clips <i>lit</i>	\$6.00	\$60.00 30.
Subtotal :-				<u>\$4,658.00</u>

*2095*  
*1885.50*

Labour charges

To remove & re-fix front & rear reverse sensor	<del>\$100.00</del> 50
To remove & re-fix cushion	\$100.00 ✗
To Check Wiring System	<del>\$60.00</del> 30
Tuff kote	\$100.00 ✗
Panel beating	<del>\$450.00</del> 200
Spray painting	<del>\$450.00</del> 200

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Subtotal :- \$1,260.00  
Total :- \$5,918.00

*total: 2365.50*  
*L/S: 1.8K*  
*03D4p*