



bp

興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996
TEL : 762 1010, 763 9909 FAX : 760 2724 Email: hinglee@pacific.net.sg

02/8/19
4.00pm Confirm
my B.B.Tw

Pg 1

Burgman Trading P. Ltd.

GBH 7183T

Date 18/7/19 NO.

1.	front windscreen rubber / MC	\$ 328.30
2.	front wiper panel. X PB	\$ 401.10
3.	front body panel / DD	\$ 1289.30
4.	front sticker "Dyna" / MC	\$ 58.30
5.	front grille emblem / MC	\$ 70.10
6.	front grille clip (set) / MC	\$ 40.00
7.	front grille / BR	\$ 550.00
8.	front LH head lamp Assy / CH	\$ 758.00
9.	front RH head lamp Assy ?	\$ 758.00
10.	front bumper / DD	\$ 720.10
11.	2 front bumper Bracket \$ 255.30 @ / DD	\$ 510.60
12.	front LH bumper lamp ?	\$ 41.90
13.	1 front LH bumper lamp bezel ?	\$ 84.80
14.	2 front head lamp lower seat \$ 35.70 @ X	\$ 71.40
15.	1 LH step Board X	\$ 422.00
16.	air-con heater w/housing Assy ?	\$ 899.00
17.	air-con coil unit w/housing Assy ?	\$ 910.00
18.	air-con blower unit Assy ?	\$ 880.00
19.	rear exhaust X	\$ 898.00
20.	rear tail lamp RH Assy / BR	\$ 220.00
21.	rear RH reflector X	\$ 55.00





bp

興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996

TEL : 762 1010, 763 9909 FAX : 760 2724 Email: hinglee@pacific.net.sg

Pg 1-2

Burgman Trading P. Ltd

GBH 7183T


Date


18/7/19

NO.

S. NRT.

1.	Rear Tail Lamp Bracket / BT	\$ 200.00	
2	Rear bumper Cover / DD	\$ 450.00	
3.	Rear bumper Beam. / DD	\$ 580.00	
4	4 Rear bumper Beam Screw / APC	\$ 40.00	2030
5	front no plate / CUT	\$ 45.00.	35
6	Rear no plate / CUT	\$ 45.00.	35
7	Rear no plate Panel. X	\$ 280.00.	
8	front body joint Sealant / APC	\$ 50.00.	30
9	front Panel Insulation Matt ?	\$ 180.00.	
10	2 Set Rear bumper Top \$530@ / CUT	\$ 1060.00	
11	Anti Rust / APC	\$ 60.00.	30





bp

興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996
TEL : 762 1010, 763 9909 FAX : 760 2724 Email: hinglee@pacific.net.sg

Pg 1-3.

Burgheim Trading P. Ltd

GBH71837

Date 18/7/19. NO.

Labour Charge

1. To Respray painting Damage area. front & Rear	\$ 1200.00.	650
2. To Repair front & Rear Acc Damage area Cut & Weld Remove & Replace.	\$ 2000.00	1190
3. wiring fee Transfer wiring harness, checking	\$ 35.00	/
4. front windscreen Remove & Refit	\$ 120.00	/
5. Rear Exhaust Remove & Replace	\$ 80.00	X
6. Remove & Refit dash board.	\$ 280.00.	150
7. To Remove Check. Replace under-dash air-Con item	\$ 200.00.	120

Steve (LKK)

8322 8813

6 days

Steve@lkkauto.com

L/S

Ray AF Spm

OO - Not Author (Report)

EXPSS - \$600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: