

22/03/2011

ASS. REC. BY:

REF:

CS/INC19013536/As d3 n2

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person): Daniel Koh

of

INC

Date/Time: 1/8/19 @ 5.36pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YQ865K

Insured:

XE 358ER

at Workshop m/s

Hiap Hong Motor

Tel:

67459633

of

2 Kaki Bukit Ave 2 # 02-13

Policy No:

Claim No:

M7/1055996-001

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 31/07/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.55am @ 2/8/19

Person Contacted:

Chuen

Vehicle IN (OUT)

Date/Time

Action/Instruction

Tahong?

23/08/19

Confirmed p/p \$ 1,200/- @ 2 days with Adrian
(\$ 2,890.00 Red - 71%)

Nivitha (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Thursday, 1 August 2019 5:36 PM
To: 'assignments@lkkauto.com'
Cc: admin-d@lkkauto.com; Thio Tse Kiat
Subject: FW: Pre-Repair Survey by LKK on 20/6/2019

Dear LKK,

Please assist to survey the following vehicle as per Tse Kiat's instruction :-

S/n	THIRD PARTY	OUR INSURED	WORKSHOP / CONTACT NO.	DOA / CLAIM NO / OFFICER	REMARKS
1	YQ865K	XE3588R	HIAP HONG MOTOR REPAIR / 67459633	31/7/2019 / MT-1055996-001 / Rajeswary	TNG SOON CHYE & CO

Please contact workshops/lawyers.

Please revert to officer-in-charge after survey.

Daniel Koh
Senior Admin Assistant
Motor Insurance
T +65 6430 7901
www.income.com.sg



in with
you

At Income, we are 'In with You' on Performance, Growth,
Innovation and Impact. These attributes reflect what we promise
as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



Your Ref: TSC.YQ865K.Accid.2019(HH)-ak
Our Ref : MT/CA/TP/138/1055996-001/RD/AT

01 Aug 2019

TNG SOON CHYE & CO
150 SOUTH BRIDGE ROAD
#02-19 FOOK HAI BUILDING
SINGAPORE 058727

Dear Sir/Madam

CLAIM NUMBER: MT/1055996-001
ACCIDENT INVOLVING XE3588R / YQ865K on 31 Jul 2019

We refer to your email of 1 Aug 2019.

We have selected Lkk Auto Consultants Pte Ltd from your list of surveyors to be our single joint expert for this matter. May we highlight that pre-repair survey as per NIMA protocol includes survey of the vehicle when its damaged parts are being dismantled before repairs. Please provide a list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.

In addition, please note our intention to conduct a post-repair survey before the vehicle has been returned to your client. Please co-ordinate with the appointed single joint expert immediately after the repairs is completed.

If you have any queries, please contact Rajeswary Doraisamy at 6430 7934 or email us at rajeswary.doraisamy@income.com.sg.

Yours sincerely

Jenny Pe
Deputy Vice President
Motor Insurance

cc Lkk Auto Consultants Pte Ltd

HN / bthw01

Register New Vehicle (Acknowledgement)

Vehicle Particulars

Vehicle No.: YQ865K
Vehicle Type: B30 - Goods (Open) Lorry (Wooden Body) Vehicle Scheme: Normal
Vehicle Attachment 1: With Hood
Vehicle Attachment 2: - Vehicle Attachment 3: -
Vehicle Make: HINO Vehicle Model: XZU710R 14FT WIDE CAB 5T
Chassis No.: JHHUCV3H00K030740 Engine No.: N04CVV10700
Motor No.: - Trailer Chassis No.: -
Propellant: Diesel Passenger Capacity: 2
Engine Capacity: 4009 cc Power Rating: -
Maximum Power Output: -
Unladen Weight: 2500 kg Maximum Laden Weight: 5000 kg
Primary Colour: White Secondary Colour: -
First Registration Date: 29 May 2019 Original Registration Date: 29 May 2019
Manufacturing Year: 2019 Open Market Value: \$34,302.00
☒ RF Eligibility: No Minimum PARF Benefit: \$0.00
No. of Transfers: 0 Additional Registration Fee Rate: 5.00%
Actual ARF Paid: \$1,716.00

Owner Particulars

Owner Name: KM CONSTRUCTION CO. (S) PTE. LTD.
Owner ID Type: Company
Owner ID: 199908291C
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 40
Registered Street Name: KAKI BUKIT PLACE
Registered Unit No.: -
Registered Building Name: EUNOS TECHPARK
Registered Postal Code: 416218
COE No. / Expiry Date: 2019052905001134M / 28 May 2029
☒ E Bid Category: C - Goods Vehicle & Bus
PQP Paid: \$24,834.00

Transaction Details

Business Transaction Ref. No.: 20190529161419805313
Business Transaction Date: 29 May 2019
Business Transaction Time: 16:14:19

Message

The above vehicle has been successfully registered.
Please note that \$21,229.00 will be deducted from your GIRO account.

YQ865K

TP INC

Shirley

Hino XZU710R

JHHUCV3H00K030740

Tailgate (Wooden) Repir	1500(SN) +
Tailgate Outer Bracket RH	350(SN) 250(SN)
Tailgate Inner Bracket RH	300(SN) 150(SN)
Tailgate RH Hinge	180(SN) X
Tailgate Adbolishment	200(SN) X
60km/h Sticker	15(SN) X
23 Pax Sticker	15(SN) X
Side Gate Outer Bracket	350(SN) 250(SN)
Side Gate Inner Bracket	300(SN) 150(SN)
Side Gate Lock Safety Pin	80(SN) 50(SN)

Panel Beating . 350 ~~400~~ 200

To varnish tailgate and side gate 400 150

Total - 4090/-

total 1200 (P/P)

02 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19013536/Asd3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 04-09-2019



ATTN: RAJESWARY

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 3588R	Veh. Inspected	YQ 865K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1055996-001	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	01/08/2019

2. Vehicle Particulars & Condition

Make & Model	HINO XZU710R	c.c	4009
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JHHUCV3H00K030740	Colour	WHITE
Odometer	11687 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	7.00 R16	YOKOHAMA	9 mm
L/H Front Tyre	7.00 R16	YOKOHAMA	9 mm
R/H Rear Tyre	7.00 R16	YOKOHAMA	9 mm
L/H Rear Tyre	7.00 R16	YOKOHAMA	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/07/2019	Inspect Date / Time	02/08/2019 (01:50 PM)
Survey held at	HIAP HONG MOTOR REPAIR 2 KAKI BUKIT AVE 2 #02-13 SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 865K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE (WOODEN)(SN)	TO REPAIR SEE LABOUR	1,500.00	-
1	TAILGATE OUTER BRACKET RH (SN)	BENT	350.00	250.00
1	TAILGATE INNER BRACKET RH (SN)	BENT	300.00	150.00
1	TAILGATE RH HINGE (SN)	NOT NECESSARY	180.00	-
1	TAILGATE ADVERTISEMENT (SN)	NOT NECESSARY	200.00	-
1	60KM/H STICKER (SN)	NOT NECESSARY	15.00	-
1	23 PAX STICKER (SN)	NOT NECESSARY	15.00	-
1	SIDE GATE OUTER BRACKET (SN)	BENT	350.00	250.00
1	SIDE GATE INNER BRACKET (SN)	BENT	300.00	150.00
1	SIDE GATE LOCK SAFETY PIN (SN)	BENT	80.00	50.00
			3,290.00	850.00
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF TAILGATE (WOODEN).		400.00	200.00
	TO VARNISH TAILGATE AND SIDE GATE.		400.00	150.00
			800.00	350.00
	GRAND TOTAL		4,090.00	1,200.00
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,200.00

Report Ref No. CS/INC19013536/Asd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.