

QUOTATION FOR REPAIR : FBL409T

Chassis MEIRGI

Cecil

Qty	Description
2 pc	MIRROR L&R
1 pc	HANDLE BAR
1 pc	Brake Lever
2 pc	Balancer
1 pc	Fuel Tank Left Hand Cowling
1 pc	Front Mudguard
1 pc	Rear Mudguard
1 set	Box Rack
1 pc	Swingarm
1 set	Fork
1 Set	Exhaust Cover
1 pc	Front Fuel Tank Cover Left Side
1 pc	Left side Middle Cover
2 pc	Front Footrest
2 pc	Rear Footrest
1 pc	Splash Guard

Repairer's Estimate

NNX	88.00
BT	180.00 \$95
Br	95.00 \$20
Cra	95.00 \$20
Cra	151.00 \$80
Cut	80.00
NNX	80.00
Scr	350.00 \$150
NNX	338.00
BT	450.00
Scr	158.00 \$60
Cra	98.00 \$79
Cut	108.00 \$88
NNX	158.00
Scr	158.00 \$68
Br	98.00 \$69

Net Item: \$1257

2,685.00

add 10% = \$1131.30

2,685.00

Qty	Description
1 pc	Fork Oil Shield
1 pc	Fork Dust Cover
2 pc	number plate
1 pc	Box
2 Bottle	Fork Oil
	Total parts

rec	48.00 \$40
rec	48.00 \$40
BT	28.00
Scr	350.00 \$180
rec	40.00 \$30

3,199.00

Net Item: \$318

Steering Cone
towing to alignment body frame (2 way)
Alignment Body Frame
Towing fees
Front rim realign
Workmanship
Total parts and labour charges

55.00

90.00

380.00

45.00

80.00

600.00

4,449.00

8 days

Provide receipt

\$150

Provide receipt

\$300

Labour: \$585

Total: \$2034.30

L/S 20% = \$1600.00

23/8/19
R/Days: 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: