

Spark Car Care

ComfortDelgro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 FAX : 67436072

Finalization Form

Bill To : CHINA TAIPING **Vehicle Number** : SKU 8144A
Attn to : MR ADRIAN LING **Type Of Claim** : TP

A. Spare parts	\$	<u>2,173.00</u>		F. Total Parts	\$	<u>1,738.40</u>
B. Supplementary	\$	<u>-</u>		G. Total Labour	\$	<u>1,080.00</u>
C. Nett Price	\$	<u>-</u>		H. Total Repair	\$	<u>2,818.40</u>
D. Supp Nett Price	\$	<u>-</u>		I. Excess		<u> </u>
E. S/Nett		<u> </u>		Part by Parts Total		<u>2,818.40</u>

Total Spare Parts Price	\$	2,173.00
Cost plus / List Down 20%		434.60
Total		1,738.40

Total Nett Price	\$	-
Nett Price Less 0%		-
Total		-

Lump Sum Less	\$	<u>-</u>
Less Excess		<u> </u>
Total		<u> </u>
Lump Sum Rounding		<u> </u>
<i>Total Finalized Amount</i>		<u> </u>

N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.

Remarks : Please confirm and revert by Fax or Email

Date In : _____
 Date Survey : _____
 Date Out : _____
 Sat/Sun/Ph. : _____
 Authorized Repair Day : _____

Total Repair Day : 4
 LOU/ Day : _____
 Total LOU : _____
 Rental/Day : _____
 Total Rental : _____

Submitted By / Date :

Confirmed By / Date :



320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP

Vehicle No. : SKU 8144A

Make & Model : MAZDA 3

Year of Manufacture : 2015

Chassis No. : JM6BM42A8G0316497

Ins Company : CHINA TAIPING

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 28.07.2018

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimates

Case Owner : _____

Signature : _____

Contact No : _____

Parts (a) Cost / List Price Items \$ 4,408.00

Plus/Less 20% \$ 881.60

Total of Cost / List \$ 3,526.40

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ 3,526.40

Labour (Appendix B) \$ 2,020.00

Total Repair Cost \$ 5,546.40

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Adrian King

Company : LIC

Survey conducted on : 07/08/19 at 3:40pm

Remarks By Surveyor

(a) The repair of this vehicle is authorized is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : [Signature] Date: 07/08/19

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : SKU8144A Case Owner : JOHARI

Make & Model : MAZDA 3 Year Manufacture : 2015

Chassis No : JM6BM42A8G0316497 Engine No : P520308267

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : _____

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	RHR TAIL LAMP <i>original</i>	1		\$ 1,045.00	✓		
2	RHR FENDER <i>?</i>	1		\$ 1,481.00	✓		
3	RHF FENDER AIR VENT <i>?</i>	1		\$ 98.00	✓		
4	REAR BUMPER <i>Distorted</i>	1		\$ 1,355.00	<i>✓ 1028</i>		
5	REAR BUMPER CLIP'S <i>new</i>	15		\$ 54.00	✓		
6	REAR BUMPER SIDE RETAINER RH <i>new</i>	1		\$ 46.00	✓		
7	REAR BUMPER REFLECTOR LAMP RH <i>new new</i>	1		\$ 64.00	X.		
8	REVERSE SENSOR OUTER RH <i>new</i>	1		\$ 245.00	X.		
9	REVERSE SENSOR holder <i>new</i>	1		\$ 20.00	X.		
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

