

ASS. REC. BY:

REF: CS/CTI19013556/AVD3/n2

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI Date/Time: 28/1/19 @ 11:20am

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKU 8144A Insured: SLC 4596M

at Workshop m/s Comfort Delgro Tel: 6848 5725

of 320 Ubi Road 3

Policy No: Claim No: SNMI9D203539

Sum Insured: Excess:

Make of Vch: (Client's Record) D.O.A. 28/1/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:41pm @ 28/1/19 Person Contacted: Johni Vehicle IN (OUT)

| Date/Time | Action/Instruction  | Remarks      |
|-----------|---|--------------|
|           | if car in. Assign to Adrian.                                    |              |
|           | SKU 8144A - NA/CTI19013306/h4                                   | JWA: 28/1/19 |
|           | SLC 4596M - NA/CTI19013306/h4                                   | JWA: 28/1/19 |
| 12/1/19   | Final fig \$ 2818.40 confirmed by email (Red 278, H910) (NO LS) |              |

ISS. REC. BY:

Adrian

REF: CTI

ASSIGNMENT

From: \_\_\_\_\_ Date: 7/8/19

Veh No: SKU8144A. Yr Regn: 2015 August.

Estimated Cost: \_\_\_\_\_

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SKU 8144A

Make: Mazda 3 c.c. 1496

at Workshop m/s Comfort Delgro

Colour: Blue. A/C: Insured / Std / NI / NA

of 320 Ubi Road 3

Sp. Reading 23284 T/Radio: Insured / Std / NI / NA

Insured: \_\_\_\_\_

Eng/No: \_\_\_\_\_

Policy No. \_\_\_\_\_

C/No: JM6BM42A860316497

Claims No. \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: 3.00pm - 5pm

Modi: Nil / SRim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 215/50R17.

R: 215/50R17.

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| /   |     |
| N/S | O/S |
|     |     |

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Bal. or Market Value: \_\_\_\_\_

Front

Rear

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

R/Bal. 06 mm

R/Bal. 06 mm

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

L/Bal. 06 mm

L/Bal. 06 mm

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

D.O.A. \_\_\_\_\_ D.O.I. 07/08/19.

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Survey held at Comfort (Ubi).

CA / REV / REP. / 24 HRS Cup


Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear b/s.

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time          | Action / Instruction  |
|----------------------|---|
|                      | TP China.   |
| RECEIVED 13 SEP 2019 |   |
|                      | <br>12/9/2019. |

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 4

1)

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2) 13/9 - typist

Add Fee:  Site Insp (\$)

Survey Fee:

Transportation: \_\_\_\_\_

3 + RS. \$

Photos:

Others:

Report Format: merimen

Lump Sum / T.B.H: 2818.40

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

220

TOTAL

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Friday, 2 August 2019 11:20 AM  
**To:** CDGE Ubi Private Cars Crash Repair Counter  
**Cc:** assignments  
**Subject:** RE: OUR REF; SNM19D203539-SLC4596M-CBS - FW: TO ARRANGE TP SURVEY SKU8144A ( SLC4596M CHINA TAIPING )

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client' s vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](http://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** CDGE Ubi Private Cars Crash Repair Counter [mailto:ubi\_cr@sparkcarcare.com]

**Sent:** Friday, 2 August, 2019 8:56 AM

**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

**Subject:** Re: OUR REF; SNM19D203539-SLC4596M-CBS - FW: TO ARRANGE TP SURVEY SKU8144A ( SLC4596M CHINA TAIPING )

Hi Boon Sen,

Kindly appoint Adrian Ling.

Thks & Regards,  
Tinie  
Crash Repair

COMFORT DELGRO  
ENGINEERING

ComfortDelGro Engineering Pte Ltd  
320 Ubi Road 3 S (408649)  
Tel: +65 6848 5725/26  
Email: [Ubi\\_CR@sparkcarcare.com](mailto:Ubi_CR@sparkcarcare.com)



---

**From:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>  
**Sent:** Friday, 2 August 2019 8:31 AM  
**To:** CDGE Ubi Private Cars Crash Repair Counter <[ubi\\_cr@sparkcarcare.com](mailto:ubi_cr@sparkcarcare.com)>  
**Subject:** RE: OUR REF; SNM19D203539-SLC4596M-CBS - FW: TO ARRANGE TP SURVEY SKU8144A ( SLC4596M CHINA TAIPING )

WARNING: This email originated from an external party outside ComfortDelGro. Sender of this email could not be validated and name in the "From" field may be forged.

---

**WITHOUT PREJUDICE**

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

|                         |
|-------------------------|
| ADRIAN LING             |
| Kelvin Ang              |
| SEE CHEW SENG           |
| MOHD FADHILAH BIN OSMAN |
| XING QUO QIANG          |
| KENNETH KONG            |
| SIMON HO                |
| CHUA WEIJIE             |
| MARCUS CHUA             |
| HENRY NG                |

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** CDGE Ubi Private Cars Crash Repair Counter [[mailto:ubi\\_cr@sparkcarcare.com](mailto:ubi_cr@sparkcarcare.com)]  
**Sent:** Friday, 2 August, 2019 7:44 AM  
**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>; Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>

**Subject:** Re: OUR REF; SNM19D203539-SLC4596M-CBS - FW: TO ARRANGE TP SURVEY SKU8144A ( SLC4596M CHINA TAIPING )

Hi Boon Sen,

Kindly let me know when is the next available slot for survey.

Thks & Regards,

Tinie

Crash Repair

ComfortDelGro Engineering Pte Ltd

320 Ubi Road 3 S (408649)

Tel: +65 6848 5725/26

Email: [Ubi\\_CR@sparkcarcare.com](mailto:Ubi_CR@sparkcarcare.com)



---

**From:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Sent:** Thursday, 1 August 2019 5:28 PM

**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; CDGE Ubi Private Cars Crash Repair Counter <[ubi\\_cr@sparkcarcare.com](mailto:ubi_cr@sparkcarcare.com)>

**Subject:** OUR REF; SNM19D203539-SLC4596M-CBS - FW: TO ARRANGE TP SURVEY SKU8144A ( SLC4596M CHINA TAIPING )

WARNING: This email originated from an external party outside ComfortDelGro. Sender of this email could not be validated and name in the "From" field may be forged.

---

Dear Boon Sen

Please conduct PRS SKU8144A.

File with officer in charge –Chong Boon Sen -63896171.

Thank you

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** CDGE Ubi Private Cars Crash Repair Counter [[mailto:ubi\\_cr@sparkcarcare.com](mailto:ubi_cr@sparkcarcare.com)]

**Sent:** Thursday, August 01, 2019 3:22 PM

**To:** Claims Dept of CTI  
**Subject:** TO ARRANGE TP SURVEY SKU8144A ( SLC4596M CHINA TAIPING )

Dear Survey Team,

Kindly arrange survey.

Thks & Regards,

Tinie

Crash Repair

ComfortDelGro Engineering Pte Ltd

320 Ubi Road 3 S (408649)

Tel: +65 6848 5725/26

Email: [Ubi\\_CR@sparkcarcare.com](mailto:Ubi_CR@sparkcarcare.com)



---

From: ApeosPort-III C4400 <[xerox@comfortdelgro.com.sg](mailto:xerox@comfortdelgro.com.sg)>  
Sent: Thursday, 1 August 2019 3:07 PM  
To: CDGE Ubi Private Cars Crash Repair Counter  
Subject: Scan Data from CDG\_UBI\_SK\_A4400

Number of Images: 3  
Attachment File Type: PDF

Device Name: ApeosPort-III C4400  
Device Location:

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 12 September 2019 2:16 PM  
**To:** CDGE Ubi Private Cars Crash Repair Counter; SUR  
**Subject:** RE: TO FINALIZE SKU 8144A-DOA: 28/7/2019

Dear Tinie,

WITHOUT PREJUDICE

Confirmed amount \$2818.40 before GST @ 4 working days.

**Kindly send Final invoice and all supporting documents directly to CHINA TAIPING**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** CDGE Ubi Private Cars Crash Repair Counter <ubi\_cr@sparkcarcare.com>  
**Sent:** Wednesday, 4 September 2019 6:03 PM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Adrian Ling (LKKAuto) <adrianling@lkkauto.com>  
**Subject:** TO FINALIZE SKU 8144A-DOA: 28/7/2019

Dear Adrian & Veron,

Attached for your action.

Thks & Regards,  
Tinie  
Crash Repair  
ComfortDelGro Engineering Pte Ltd  
320 Ubi Road 3 S (408649)  
Tel: +65 6848 5725/26  
Email: [Ubi\\_CR@sparkcarcare.com](mailto:Ubi_CR@sparkcarcare.com)



---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Sent:** Wednesday, 4 September 2019 4:43 PM  
**To:** CDGE Ubi Private Cars Crash Repair Counter <ubi\_cr@sparkcarcare.com>; SUR <sur@lkkauto.com>  
**Subject:** SKU 8144A-DOA: 28/7/2019

Dear Tinie,

Kindly advise vehicle status.

**If vehicle has been repaired, please finalize with us.**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                      |
|----------------------------|----------------------|
| Date Of Report             | 29/07/2019 14:04     |
| Date Of Accident           | 28/07/2019 16:10     |
| Exact Location Of Accident | UPPER SERANGOON ROAD |
| Country/State of Loss      | SINGAPORE            |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SKU8144A             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | CINDY CHAN XINYI     |
| NRIC No                     | S9032902B            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             | (LOCAL) +65-82866588 |
| Alternative Phone No        | OFFICE-82866588      |

### Vehicle Particulars

|  |               |
|--|---------------|
| Manufacturer   | MAZDA         |
| Model  | -             |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USAGE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO            |
| If No, Please state action to be taken                                       | THIRD PARTY   |
| Vehicle Category   | PRIVATE CAR   |

### Insurance Company

|                           |                           |
|---------------------------|---------------------------|
| Name of Insurance Company | LIBERTY INSURANCE PTE LTD |
| Type Of Coverage          | COMPREHENSIVE             |
| Fleet Policy              | NO                        |
| Policy Number             | DMPPHQ18-005596           |
| Cover Note Number         |                           |

### Driver

|                      |                      |
|----------------------|----------------------|
| Name of Driver       | LEE JING HENG        |
| Passport No/FIN      | G1183363U            |
| Date Of Birth        | 01/11/1992           |
| Occupation           | INDOOR               |
| Date Of Driving Pass | 19/08/2017           |
| Driving Experience   | 1 YEAR AND 11 MONTHS |
| Gender               | MALE                 |
| Mobile Number        | (LOCAL) +65-82866588 |
| Fax Number           |                      |
| Contact Number       | OFFICE-82866588      |
| EMail Address        | NOEMAIL              |

|   |                        |
|---|------------------------|
| Address   | BLK 336 CLEMENTI AVE 2 |
| Postcode  | 120336                 |
| Was driver an employee of the Insured's Company     | NO                     |
| If No, Relationship of the Driver with the Insured  | FRIEND                 |
| Vehicle Registration Number of Driver's Own Vehicle | -                      |
|   | -                      |
|   | -                      |
| Insurance Company of Driver's Own Vehicle           | -                      |
|   | -                      |
|   | -                      |

### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

### Other Information

|   |  |
|---|--|
| Was any foreign vehicle involved in this accident?  | NO   |
| Number of vehicles (including own vehicle) involved in the accident                         | 2  |
| Was any body injured in the Accident?   | NO   |
| Was any injured conveyed to hospital by ambulance?  |  |
| Was any other material or property damaged?   | YES  |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO   |
| Number of Passengers (Including Driver)   | 2  |
| Passenger 1   | NAME: : CHAN JIAYI CAROL<br>GENDER: : FEMALE |

### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

### Circumstances of Accident

REFER TO ATTACHMENT


### Attachment(s)

|   |                  |
|---|------------------|
| Are accident photos available for attachment? | YES              |
| Was there any video captured by Car Camera?   | YES              |
| Remarks/ Reasons:                             | VIDEO WITH OWNER |
| Was there any audio recorded?                 | NO               |

### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |             |
|-----------------------------|-------------|
| Vehicle Registration Number | SLC4596M    |
| Vehicle Make/Model/Colour   |             |
| Details Of Properties       |             |
| Vehicle Category            | PRIVATE CAR |
| Name of Driver              |             |
| NRIC/Passport Number        |             |
| Contact Number              |             |
| Address                     |             |
| Postcode                    |             |
| Insurance Company Name      |             |
| Nature Of Damage            |             |

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle was on the right lane changing into the left lane. The taxi in front of me made an emergency break for the bus coming out of the bus stop. I had to make an emergency stop before fully entering the left lane while waiting for the bus to move, after 2-3 seconds of making the emergency break, another car knock into the right rear of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 29/01/2019  
 11.43am.

CONFORTDELGPO ENGINEERING PTE LTD  
 CENTRAL BUSINESS DISTRICT  
 SIGNATURE

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TP

Vehicle No. : SKU 8144A

Make & Model : MAZDA 3

Year of Manufacture : 2015

Chassis No. : JM6BM42A8G0316497

Ins Company : CHINA TAIPING

Engine No. : \_\_\_\_\_

Excess : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Date of Accident : 28.07.2019

Time of Accident : \_\_\_\_\_

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor

**Repair Estimates**

Case Owner : \_\_\_\_\_

Signature : \_\_\_\_\_

Contact No : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ 4,408.00

Plus/Less 20% \$ 881.60

Total of Cost / List \$ 3,526.40

(b) Nett Price Items \$ -

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ 3,526.40

Labour (Appendix B) \$ 2,020.00

Total Repair Cost \$ 5,546.40

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Adrian King

Company : L/C/C

Survey conducted on : 07/08/19 at 3:40pm

Remarks By Surveyor

(a) The repair of this vehicle is authorized is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : [Signature] Date: 07/08/19

# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
320 UBI ROAD 3 SINGAPORE 408649  
TEL :68438723/68438736 Fax:67436072

## Spare Parts

Vehicle No : SKU8144A Case Owner : JOHARI  
 Make & Model : MAZDA 3 Year Manufacture : 2015  
 Chassis No : JM6BM42A8G0316497 Engine No : P520308267  
 Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_  
 Order By : \_\_\_\_\_ Type of Claim : \_\_\_\_\_

| S/No | Part Description                             | QTY | Cost Price | List Price  | Nett Price | S/N | Disposition By Surveyor |
|------|--|-----|------------|-------------|------------|-----|-------------------------|
| 1    | RHR TAIL LAMP <i>cracked</i>                 | 1   |            | \$ 1,045.00 | ✓          |     |                         |
| 2    | RHR FENDER <i>Reqs</i>                       | 1   |            | \$ 1,481.00 | +          |     |                         |
| 3    | RHF FENDER AIR VENT <i>Not new</i>           | 1   |            | \$ 98.00    | +          |     |                         |
| 4    | REAR BUMPER <i>Distorted</i>                 | 1   |            | \$ 1,355.00 | ✓ 1028     |     |                         |
| 5    | REAR BUMPER CLIP'S <i>New</i>                | 15  |            | \$ 54.00    | ✓          |     |                         |
| 6    | REAR BUMPER SIDE RETAINER RH <i>Not new</i>  | 1   |            | \$ 46.00    | ✓          |     |                         |
| 7    | REAR BUMPER REFLECTOR LAMP RH <i>Not new</i> | 1   |            | \$ 64.00    | +          |     |                         |
| 8    | REVERSE SENSOR OUTER RH <i>2M</i>            | 1   |            | \$ 245.00   | +          |     |                         |
| 9    | REVERSE SENSOR holder <i>SM</i>              | 1   |            | \$ 20.00    | +          |     |                         |
| 10   |  |     |            |             |            |     |                         |
| 11   |  |     |            |             |            |     |                         |
| 12   |  |     |            | 2173        |            |     |                         |
| 13   |  |     |            | 1738-40     |            |     |                         |
| 14   |  |     |            |             |            |     |                         |
| 15   |  |     |            |             |            |     |                         |
| 16   |  |     |            |             |            |     |                         |
| 17   |  |     |            |             |            |     |                         |
| 18   |  |     |            |             |            |     |                         |
| 19   |  |     |            |             |            |     |                         |
| 20   |  |     |            |             |            |     |                         |
| 21   |  |     |            |             |            |     |                         |
| 22   |  |     |            |             |            |     |                         |
| 23   |  |     |            |             |            |     |                         |
| 24   |  |     |            |             |            |     |                         |
| 25   |  |     |            |             |            |     |                         |
| 26   |  |     |            |             |            |     |                         |
| 27   |  |     |            |             |            |     |                         |
| 28   |  |     |            |             |            |     |                         |
| 29   |  |     |            |             |            |     |                         |
| 30   |  |     |            |             |            |     |                         |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



# Spark Car Care

ComfortDelgro Engineering Pte Ltd  
320 UBI ROAD 3 SINGAPORE 408649  
Tel: 68438723/68438736 FAX : 67436072

Finalization Form

**Bill To** : CHINA TAIPING                      **Vehicle Number** : SKU 8144A  
**Attn to** : MR ADRIAN LING                      **Type Of Claim** : TP

**A. Spare parts**                      \$ 2,173.00  
**B. Supplementary**                      \$ -  
**C. Nett Price**                      \$ -  
**D. Supp Nett Price**                      \$ -  
**E. S/Nett**                      \_\_\_\_\_

**F. Total Parts**                      \$ 1,738.40  
**G. Total Labour**                      \$ 1,080.00  
**H. Total Repair**                      \$ 2,818.40  
**I. Excess**                      \_\_\_\_\_  
**Part by Parts Total**                      2,818.40

|                         |     |             |
|-------------------------|-----|-------------|
| Total Spare Parts Price |     | \$ 2,173.00 |
| Cost plus / List Down   | 20% | 434.60      |
| Total                   |     | 1,738.40    |

|                  |    |      |
|------------------|----|------|
| Total Nett Price |    | \$ - |
| Nett Price Less  | 0% | \$ - |
| Total            |    | -    |

Lump Sum Less                      \$ -  
 \_\_\_\_\_  
 Less Excess                      \_\_\_\_\_  
 Total                      \_\_\_\_\_  
 Lump Sum Rounding                      \_\_\_\_\_  
**Total Finalized Amount**                      \_\_\_\_\_

**N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.**

Remarks : Please confirm and revert by Fax or Email

Date In : \_\_\_\_\_  
 Date Survey : \_\_\_\_\_  
 Date Out : \_\_\_\_\_  
 Sat/Sun/Ph. : \_\_\_\_\_  
 Authorized Repair Day : \_\_\_\_\_  
 Submitted By / Date : \_\_\_\_\_

Total Repair Day : 4 \_\_\_\_\_  
 LOU/ Day : \_\_\_\_\_  
 Total LOU : \_\_\_\_\_  
 Rental/Day : \_\_\_\_\_  
 Total Rental : \_\_\_\_\_  
 Confirmed By / Date : \_\_\_\_\_



320 UBI ROAD 3 SINGAPORE 408649

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TPVehicle No. : SKU 8144AMake & Model : MAZDA 3Year of Manufacture : 2015Chassis No. : JM6BM42A8G0316497Ins Company : CHINA TAIPING

Engine No. : \_\_\_\_\_

Excess : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Date of Accident : 28.07.2018

Time of Accident : \_\_\_\_\_

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor**Repair Estimates**

Case Owner : \_\_\_\_\_

Signature : \_\_\_\_\_

Contact No : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ 4,408.00Plus/Less 20% \$ 881.60Total of Cost / List \$ 3,526.40(b) Nett Price Items \$ -

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 3,526.40Labour (Appendix B) \$ 2,020.00Total Repair Cost \$ 5,546.40

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Adrian KingCompany : L/C/CSurvey conducted on : 07/08/19 at 3:40pm**Remarks By Surveyor**(a) The repair of this vehicle is authorized ~~is not authorized~~ until further notice.(b) Recommended Days of Repair : 04 day(s)(c) Resurvey : Required Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : [Signature]Date: 07/08/19

## Spark Car Care

ComfortDelGro Engineering Pte Ltd  
320 UBI ROAD 3 SINGAPORE 408649  
TEL :68438723/68438736 Fax:67436072

### Spare Parts

Vehicle No : SKU8144A Case Owner : JOHARI

Make & Model : MAZDA 3 Year Manufacture : 2015

Chassis No : JM6BM42A8G0316497 Engine No : P520308267

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : \_\_\_\_\_

| S/No | Part Description                         | QTY | Cost Price | List Price             | Nett Price | S/N | Disposition By Surveyor |
|------|--|-----|------------|------------------------|------------|-----|-------------------------|
| 1    | RHR TAIL LAMP <i>cracked</i>             | 1   |            | \$ 1,045.00            | ✓          |     |                         |
| 2    | RHR FENDER                               | 1   |            | \$ 1,481.00            | ✓          |     |                         |
| 3    | RHF FENDER AIR VENT ?                    | 1   |            | \$ 98.00               | ✓          |     |                         |
| 4    | REAR BUMPER <i>Distorted</i>             | 1   |            | <del>\$ 1,355.00</del> | ✓ / 1028   |     |                         |
| 5    | REAR BUMPER CLIP'S <i>new</i>            | 15  |            | \$ 54.00               | ✓          |     |                         |
| 6    | REAR BUMPER SIDE RETAINER RH <i>new</i>  | 1   |            | \$ 46.00               | ✓          |     |                         |
| 7    | REAR BUMPER REFLECTOR LAMP RH <i>new</i> | 1   |            | \$ 64.00               | ✓          |     |                         |
| 8    | REVERSE SENSOR OUTER RH <i>new</i>       | 1   |            | \$ 245.00              | ✓          |     |                         |
| 9    | REVERSE SENSOR holder <i>new</i>         | 1   |            | \$ 20.00               | ✓          |     |                         |
| 10   |  |     |            |                        |            |     |                         |
| 11   |  |     |            |                        |            |     |                         |
| 12   |  |     |            |                        |            |     |                         |
| 13   |  |     |            |                        |            |     |                         |
| 14   |  |     |            |                        |            |     |                         |
| 15   |  |     |            |                        |            |     |                         |
| 16   |  |     |            |                        |            |     |                         |
| 17   |  |     |            |                        |            |     |                         |
| 18   |  |     |            |                        |            |     |                         |
| 19   |  |     |            |                        |            |     |                         |
| 20   |  |     |            |                        |            |     |                         |
| 21   |  |     |            |                        |            |     |                         |
| 22   |  |     |            |                        |            |     |                         |
| 23   |  |     |            |                        |            |     |                         |
| 24   |  |     |            |                        |            |     |                         |
| 25   |  |     |            |                        |            |     |                         |
| 26   |  |     |            |                        |            |     |                         |
| 27   |  |     |            |                        |            |     |                         |
| 28   |  |     |            |                        |            |     |                         |
| 29   |  |     |            |                        |            |     |                         |
| 30   |  |     |            |                        |            |     |                         |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119013556/AVD3N2

Date: 16/09/2019

**REFERENCE**

|                              |   |                             |                   |                  |                 |
|------------------------------|---|-----------------------------|-------------------|------------------|-----------------|
| <b>Handling Insurer:</b>     | China Taiping Insurance (Singapore) Pte. Ltd. | <b>Policy No:</b>           | DMPCSN30536419000 |                  |                 |
| <b>Claimant Vehicle No :</b> | SKU8144A                                      | <b>Insured Vehicle No :</b> | SLC4596M          |                  |                 |
| <b>Date of Loss:</b>         | 28/07/2019                                    | <b>Nature of Claim:</b>     | TP                | <b>Claim No:</b> | SNM19D203539C02 |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                                    |                                  |                    |                   |
|------------------------------------|----------------------------------|--------------------|-------------------|
| <b>Reg No:</b>                     | SKU8144A                         | <b>Engine No:</b>  | P520308267        |
| <b>Make &amp; Model:</b>           | MAZDA 3, 1.5 4 DOOR SEDAN SP (A) | <b>Chassis No:</b> | JM6BM42A8G0316497 |
| <b>Reg. Date:</b>                  | 18/08/2015 (Man. Year: 2015)     | <b>Odometer:</b>   | 23284 km          |
| <b>Colour:</b>                     | Blue                             |                    |                   |
| <b>Engine Capacity:</b>            | 1496 cc                          |                    |                   |
| <b>Market Value/New Car Price:</b> | N/A                              |                    |                   |
| <b>Sum Insured (S\$):</b>          | Market Value/New Car Price       |                    |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                                 |     |                                |     |                                 |     |
|---------------------------------|-----|--------------------------------|-----|---------------------------------|-----|
| <b>General Condition:</b>       |     | <b>Steering (Serviceable):</b> | Yes | <b>Footbrake (Serviceable):</b> | Yes |
| <b>Handbrake (Serviceable):</b> | Yes | <b>Engine Modification:</b>    | No  | <b>Pre-accident Condition:</b>  |     |

**CONDITION OF TYRES**

|                          |                  |                         |                  |
|--------------------------|------------------|-------------------------|------------------|
| <b>Front Tyre Size:</b>  | 215/50R17        | <b>Rear Tyre Size:</b>  | 215/50R17        |
| <b>Front Left Side:</b>  | Continental 6 mm | <b>Rear Left Side:</b>  | Continental 6 mm |
| <b>Front Right Side:</b> | Continental 6 mm | <b>Rear Right Side:</b> | Continental 6 mm |

The above values represent the remaining tyre treads depth

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 3,526.40          | 1,738.40          | 1,788.00          | 50.70         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 2,020.00          | 1,080.00          | 940.00            | 46.53         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>5,546.40</b>   | <b>2,818.40</b>   | <b>2,728.00</b>   | <b>49.19</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>388.25</b>     | <b>197.29</b>     | <b>190.96</b>     | <b>49.18</b>  |
| <b>Nett Amount (S\$)</b>      | <b>5,934.65</b>   | <b>3,015.69</b>   | <b>2,918.96</b>   | <b>49.19</b>  |

**INSPECTION**

|                            |            |                      |  |
|----------------------------|------------|----------------------|--|
| <b>Date of Assignment:</b> | 06/08/2019 |                      |  |
| <b>Date Inspected:</b>     | 07/08/2019 | <b>Inspected At:</b> | ComfortDelGro Engineering Pte Ltd<br>(Ubi)<br>320 UBI ROAD 3<br>Singapore 408649 |

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

**REPAIR DETAILS****Reference**

|                            |  |
|----------------------------|--|
| <b>Part Source:</b> MRM-SG | Version: 1.0 (Last Synchronised: 16 Sep 2019)  |
| <b>Parts:</b> 143          | MAZDA 3 1.5 4 DOOR SEDAN SP (A) (Catalogue:Merimen Singapore 1.0)  |
| <b>Labour:</b> Repairer's  | (Price-denominated Standard List)  |
| <b>Print Code:</b>         | (Unsubmitted, no print-code for SKU8144A)  |
| <b>Validity:</b>           | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>       | Items/values not in reference catalogue are prefixed with an asterisk *.   |

**Recommended Parts**

| No. | Qty | Part No. | Particulars                    | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *RHR TAIL LAMP                 | Cracked       | 1,045.00 FL | *1,045.00 FL |
| 2   | 1   |          | *RHR FENDER                    | Repair        | 1,481.00 FL | *- FL        |
| 3   | 1   |          | *RHR FENDER AIR VENT           | Not Necessary | 98.00 FL    | *- FL        |
| 4   | 1   |          | *REAR BUMPER                   | Distorted     | 1,355.00 FL | *1,028.00 FL |
| 5   | 15  |          | *REAR BUMPER CLIPS             | Necessary     | 54.00 FL    | *54.00 FL    |
| 6   | 1   |          | *REAR BUMPER SIDE RETAINER RH  | Necessary     | 46.00 FL    | *46.00 FL    |
| 7   | 1   |          | *REAR BUMPER REFLECTOR LAMP RH | Not Necessary | 64.00 FL    | *- FL        |
| 8   | 1   |          | *REVESE SENSOR OUTER RH        | Not Necessary | 245.00 FL   | *- FL        |
| 9   | 1   |          | *REVESE SENSOR HOLDER          | Not Necessary | 20.00 FL    | *- FL        |

F=Franchise part. L=ListItemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>4,408.00</b> | <b>2,173.00</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | 881.60          | 434.60          |
| <b>Total Parts (\$\$)</b>                                  | <b>3,526.40</b> | <b>1,738.40</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars  | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--|----------|-----------------|-----------------|
| <b>Labour Items</b>            |  |          |                 |                 |
| 1                              | TO DISCONNECT & CHECK ELECTRICAL WIRING,WIRE SOCKET REMOVE & REINSTALL DAMAGED PARTS,TEST & RECTIFY FOR PROPER FUNCTIONING | New      | 100.00          | 30.00           |
| 2                              | TO KNOCK & REPAIR END PANEL,RHR FENDER,REAR BUMPER AND AFFECTED AREA   | New      | 700.00          | 400.00          |
| 3                              | TO REMOVE & REPLACE REVERSE SENSOR   | New      | 120.00          | 50.00           |
| 4                              | TO PUTTY & SPRAY PAINT REAR BOOT,REAR BUMPER,RHR FENDER,END PANEL,AFFECTED AREA  | New      | 1,100.00        | 600.00          |
| <b>Gross Labour Cost (S\$)</b> |  |          | <b>2,020.00</b> | <b>1,080.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >