

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

731J.

TO	: AIG	DATE	: 31-Jul-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
Kherchan			
VEHICLE DETAILS			
VEHICLE NO	: SJT6975Z		
MODEL	: MERCEDES BENZ CLA180	WDB2037462E071531	
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 27-Jul-19
		TIME	: 1630HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Repair</i>	1	\$ 2,350.00	\$ 2,350.00
2	BOOTLID OUTER PROTECTOR <i>cracked</i>	1	\$ 1,350.00	\$ 1,350.00
3	BOOTLID LOGO <i>new</i>	1	\$ 70.00	\$ 70.00
4	BOOTLID LOCK <i>2nd</i>	1	\$ 280.00	\$ 280.00
5	BOOTLID WEATHERSTRIP <i>new</i>	1	\$ 211.50	\$ 211.50
6	REAR BUMPER <i>Delaid</i>	1	\$ 1,580.50	\$ 1,580.50
7	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 92.50	\$ 185.00
8	REAR BUMPER LOWER LIP <i>at</i>	1	\$ 530.00	\$ 530.00
9	REAR REINFORCEMENT BAR <i>Best</i>	1	\$ 811.50	\$ 811.50
10	REAR REINFORCEMENT BAR SPONGE <i>cracked</i>	1	\$ 230.00	\$ 230.00
11	REAR BUMPER TOWING COVER <i>Delaid</i>	1	\$ 70.50	\$ 70.50
12	REAR BUMPER CENTER BRACKET <i>cracked</i>	1	\$ 211.40	\$ 211.40
13	REAR BUMPER CENTRE CHROME <i>3pc</i>	1	\$ 180.00	\$ 180.00
14	REAR BUMPER SIDE CHROME	2	\$ 133.50	\$ 267.00
15	REVERSE SENSOR <i>2 pieces damaged</i>	4	\$ 320.00	\$ 1,280.00
16	REVERSE SENSOR RUBBER <i>3pc</i>	4	\$ 25.50	\$ 102.00
17	REVERSE SENSOR HOLDER <i>1pc</i>	4	\$ 60.50	\$ 242.00

895
1350
687
560

18	TAIL LAMP <i>not could</i>	2	\$ 822.50	\$ 1,645.00	✓
19	TAIL LAMP LOWER BRACKET <i>new</i>	1	\$ 88.40	\$ 88.40	+
20	REAR END PANEL <i>Dented.</i>	1	\$ 1,055.90	\$ 1,055.90	✓
21	REAR END PANEL TOP GARNISH <i>Delud</i>	1	\$ 240.00	\$ 240.00	✓
22	REAR FLOOR PANEL <i>could.</i>	1	\$ 1,988.50	\$ 1,988.50	698
23	REAR FLOOR PANEL TOP OARD <i>new</i>	1	\$ 530.00	\$ 530.00	+
24	SPARE TYRE TRAY <i>not could</i>	1	\$ 422.80	\$ 422.80	306.
25	TOOLS COMPARTMENT <i>new</i>	1	\$ 320.00	\$ 320.00	+
26	EXHAUST CHROME TIP <i>new But</i>	1	\$ 420.00	\$ 420.00	180

9862.30

8867.07

TOTAL PRICE \$ 16,662.00

LESS 10% \$ 1,666.20

SUB TOTAL PRICE \$ 14,995.80

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	BOOT LID SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
3	BOOT LID STICKER <i>new</i>	1	\$ 500.00	\$ 500.00	300.
4	REAR BUMPER CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	-
5	REAR BUMPER STICKER <i>new</i>	1	\$ 500.00	\$ 500.00	350
6	TAIL LAMP CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	-
7	REAR END PANEL TOP GARNISH CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	-
8	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60. 770

TOTAL \$ 1,340.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	TO PANEL BEAT, WELD, CUT, KNOCK STRAIGHTEN, ADJUST GRAZE, JOIN	\$ 1,600.00	1800	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX AFFECTED PARTS AND PANELS	\$ 1,400.00	900	
3	TUFF COAT	\$ 250.00	60.	
4	WIRING CHECK	\$ 120.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 150.00	80	
6	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X	
7	TRANFER BOOTLID MECHANISM	\$ 80.00	X	

8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	60.	
9	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 180.00	X	
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 480.00	X 100	

2230

TOTAL

\$4,420.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 16,335.80

TOTAL LABOUR COST : \$ 4,420.00

TOTAL REPAIR COST : \$ 20,755.80

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian L
w/s 01/08/19.
07 Days.

total: 11867.07

w/s 9.5K

9.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	731J
Vehicle Details	
Vehicle No.:	SJT6975Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Nov 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CLC 180 K
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	27194631228049
Chassis No.:	WDB2037462E071531
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$34,036.00
Original Registration Date:	27 Oct 2009
First Registration Date:	27 Oct 2009
Transfer Count:	2
Actual ARF Paid:	\$34,036.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Oct 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$37,502.00
COE Rebate Amount:	\$37,320.00
Total Rebate Amount:	\$37,320.00

The information contained herein is correct as at 13 Nov 2019

OK