

LKW AUTO SERVICES

23 Hume Avenue #05-02
Hume Park 2, Singapore 598728
e-mail: lkw.claims@gmail.com

ESTIMATE

SENTOSA LIMOUSINE SERVICES PTE LTD

Not with work
11 days 87
Resony After Paint
11 days

Date: 2/8/2019

QTY	PARTICULARS	AMT (\$)
RE: KIA CERATO FORTE / SJS 6149 Y		
1 pc	rear boot lid <i>Br</i>	
1 pc	rear boot lock <i>Br</i>	
1 pc	rear boot lock catch ?	
1 pc	rear boot weatherstrip ?	
1 pc	rear boot emblem 'CERATO' <i>Br</i>	
1 pc	rear boot emblem 'FORTE' <i>Br</i>	
1 pc	rear boot emblem 'logo' <i>Br</i>	
2 pcs	rear boot lamp assy ?	@
2 pcs	rear boot hinge <i>R X</i>	@
2 pcs	rear tail lamp assy ?	@
2 pcs	rear fender <i>Br</i>	@
1 pc	rear end panel ?	
1 pc	rear end panel garnish ?	
1 pc	rear windscreen glass moulding <i>Br</i>	
1 pc	rear exhaust silencer ?	
1 pc	rear bumper <i>Br</i>	
1 pc	rear bumper lower disfuser <i>DIT</i>	
12 pcs	rear bumper clip <i>Br</i>	@
3 4 pcs	rear bumper reverse sensor <i>Short</i>	@
4 pcs	rear bumper reverse sensor holder <i>Br</i>	@
2 pcs	rear bumper reinforcement bracket ?	@
2 pcs	rear bumper side retainer <i>DIT</i>	@
2 pcs	rear bumper corner retainer ?	@
1 pc	rear number plate	s.nett <i>nd</i>
1 pc	rear number plate casing	s.nett <i>4552</i>
1 pc	rear boot emblem 'c&c'	s.nett <i>Br</i>
1 pc	windscreen glass sealant	s.nett <i>Br</i>
Sub-total		8,600.83

	Balance carried forward		8,600.83
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	1201	1,300.00
	To check wiring system.	201	50.00
	To apply waterproof sealant on affected areas.	1201	150.00
	To apply putty & spray painting on affected areas.	1201	1,350.00
	To remove carpet, trimming and seats to enable repair.	✓	100.00
	To remove & reinstall rear windscreen glass.	1201	140.00
	To install reverse sensors.	601	80.00
	To carry out exhaust works.	601	80.00
	Towing charges.	100	50.00 X
	Total:		11,900.83