

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SMA9169D

Chassis No : JHMGK3850JX222851

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : CHEN WEE KEONG

Ins Policy No :
Date of Accident : 1/8/2019

Document No. : SQT19003373 Page 1

Date : 1. Aug 2019

Customer No. : WZ1007

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L13B11030797

Date | Time : 1. Aug 2019 8:48:33 AM

Surveyor Name : DID : +65 6846 5673

Survey Date : HP : +65 8100 6306

Authorisation Date : Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 73170)						
	OWNER: CHEN WEE KEONG						
	OWNER INSURER: MSIG INSURANCE PTE LTD						
	ACC DATE: 01/08/2019@01.55AM						
	A:T/J JURONG T/HALL RD(L/P22)>JURONG E AVE1 (L/P42)						
	SURVEYED BY:						
	REF NO:						
	TP INSURER: INDIA INTERNATIONAL INS PTE LTD						
	TP VEH: SHC1305D - HYUNDAI/I40/BLUE/TAXI						
BO-TOW-SW	TOWING SERVICE	1	50.00		50.00	3.50	53.50 ✓
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60 ✓
	Sum Ext. Service				<u>230.00</u>	<u>16.10</u>	<u>246.10</u>
42700-T5S-M72	WHEEL,DISK AL 15X7	1	418.40	25	313.80	21.97	335.77
42700-TAR-E91	DISK ALUMINIUM WHEEL,16X6	1	772.30	25	579.22	40.55	619.77
60400-T5B-J00ZZ	BULKHEAD COMP,FR.	1	381.70	25	286.27	20.04	306.31
60261-T5R-A00ZZ	PANELL.FR.FENDER	1	398.60	25	298.95	20.93	319.88
60690-T5A-300ZZ	BRACKET COMP,L.FR.FENDER	1	41.70	25	31.27	2.19	33.46
04684-T5A-300ZZ	EXTENSION SETL.FR.	1	94.40	25	70.80	4.96	75.76
60630-T5B-000ZZ	BASE COMP, BATTERY	1	68.70	25	51.52	3.61	55.13
60710-T5A-B00ZZ	MEMBER COMP,L.FR.WHEELHOUSE SET	1	59.00	25	44.25	3.10	47.35
60912-T5A-300ZZ	PLATEL.FR.BACK	1	107.50	25	80.62	5.64	86.26
60943-T5A-300ZZ	BRACKETL.FR.BUMPER BEAM	1	45.00	25	33.75	2.36	36.11
60944-T5A-300ZZ	PLATEL.SIDE FRAME	1	30.80	25	23.10	1.62	24.72
60945-T5A-300ZZ	GUSSETL.FR.SIDE	1	46.10	25	34.57	2.42	36.99
60100-T5A-000ZZ	HOOD COMP	1	537.50	25	403.12	28.22	431.34
60120-TAR-000ZZ	HINGE COMP,R.HOOD	1	25.70	25	19.27	1.35	20.62
60170-TAR-000ZZ	HINGE COMPL.HOOD	1	25.70	25	19.27	1.35	20.62

Printed on 1/8/2019 3:26:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SMA9169D
Chassis No : JHMGK3850JX222851
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : CHEN WEE KEONG
Ins Policy No. :
Date of Accident : 1/8/2019

Document No. : SQT19003373
Date : 1. Aug 2019
Customer No. : WZI007
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L13B11030797
Date | Time : 1. Aug 2019 8:48:33 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
74120-T5A-J01	LOCK ASSYHOOD	1	42.60 ?	25	31.95	2.24	34.19
74141-T5B-000	INSULATORHOOD	1	87.70 X	25	65.77	4.60	70.37
74147-T5A-000	GARNISH ASSYHOOD	1	41.40 ?	25	31.05	2.17	33.22
74198-T5A-000	GARNISH ASSYL.HOOD	1	14.50 ?	25	10.87	0.76	11.63
80100-T5B-003	CONDENSER ASSY	1	704.40 ✓	25	528.30	36.98	565.28
80311-T5A-003	HOSE COMPSUCTION	1	124.00 X	25	93.00	6.51	99.51
80315-T5B-003	HOSE COMPDISCHARGE	1	144.80 X	25	108.60	7.60	116.20
80341-T5A-003	PIPE COMPRECEIVER	1	111.90 X	25	83.92	5.87	89.79
19010-5R1-901	RADIATOR COMP	1	1211.20 ?	25	908.40	63.59	971.99
19015-5R1-003	SHROUD COMP	1	89.30 ?	25	66.97	4.69	71.66
19020-5R1-003	FANCOOLING	1	26.30 ?	25	19.72	1.38	21.10
38611-5R1-003	FANCOOLING	1	49.20 ?	25	36.90	2.58	39.48
38615-5R1-003	SHROUD COMP	1	46.30 ?	25	34.72	2.43	37.15
33100-T5A-J81	HEADLIGHT ASSY,R.	1	479.70 ?	25	359.77	25.18	384.95
33150-T5A-J81	HEADLIGHT ASSY,L.	1	479.70 ✓	25	359.77	25.18	384.95
17249-5R0-J00	SEPARATOR,SPLASH INTAKE	1	31.00 ?	25	23.25	1.63	24.88
17252-5V5-M00	DUCT ASSY,AIR INTAKE	1	21.60 ?	25	16.20	1.13	17.33
17230-5R0-J01	CHAMBER ASSYRESONATOR	1	89.50 ?	25	67.12	4.70	71.82
17234-5R0-000	TUBERESONATOR CHAMBER	1	28.50 ?	25	21.37	1.50	22.87
50850-T9A-003	RUBBER ASSYTRANSMISSION MTG	1	111.40 ?	25	83.55	5.85	89.40
74111-T5A-900	COVER,ENG UNDER	1	86.00 ?	25	64.50	4.52	69.02
74150-T5L-T10	FENDER ASSY,L.FR.	1	69.20 ?	25	51.90	3.63	55.53
74165-T5A-010	GUARDL.FR.SPLASH	1	23.40 ?	25	17.55	1.23	18.78
91505-TM8-003	CLIP,BUMPER	14	2.30 ✓	25	24.15	1.69	25.84
77930-T5A-J01	SENSOR ASSYFR.CRASH	2	63.40 ?	25	95.10	6.66	101.76
77960-T5A-W41	UNIT ASSYSRS	1	822.80 ✓	25	617.10	43.20	660.30
77100-T5A-J10ZA	PANEL COMPINSTRUMENT	1	732.80 ✓	25	549.60	38.47	588.07
77820-T5A-J80	MODULE ASSYPASSENGER	1	2236.80 ✓	25	1677.60	117.43	1795.03
77810-T5A-N81ZA	MODULE ASSYDRIVER	1	1640.30 ✓	25	1230.22	86.12	1316.34

Printed on 1/8/2019 3:26:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SMA9169D

Chassis No : JHMGK3850JX222851

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : CHEN WEE KEONG

Ins Policy No. :

Date of Accident : 1/8/2019

Document No. : SQT19003373 **Page** 3

Date : 1. Aug 2019

Customer No. : WZ1007

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L13B11030797

Date | Time : 1. Aug 2019 8:48:33 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
81450-TAR-U01ZA	TONGUE ASSYR.FR.SEATBELT	1	454.80	25	341.10	23.88	364.98
81850-TAR-U01ZA	TONGUE ASSYL.FR.SEATBELT	1	454.80	25	341.10	23.88	364.98
71105-T5A-J50	COVER,FR.GRILLE	1	12.60	25	9.45	0.66	10.11
71121-T5A-J50	BASE,FR.GRILLE HOOK	1	227.40	25	170.55	11.94	182.49
71122-T5A-J50	MOLDING LOWER,FR.GRILLE	1	148.90	25	111.67	7.82	119.49
71123-T5A-J50	MOLDING UPPER,FR.GRILLE	1	124.10	25	93.07	6.51	99.58
71124-T5A-J50	STAY,FR.GRILLE	1	12.70	25	9.52	0.67	10.19
71125-T5C-J50	SCREEN,R.FR.GRILLE	1	8.10	25	6.07	0.42	6.49
71126-T5A-J50	EMBLEM BASE,FR.GRILLE	1	20.30	25	15.22	1.07	16.29
75700-T5A-000	EMBLEM H	1	15.00	25	11.25	0.79	12.04
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
04711-T5A-J50ZZ	FACE,FR.BUMPER	1	504.60	25	378.45	26.49	404.94
71102-T5L-T50	LOWER GRILLE ASSY,FR.	1	137.90	25	103.42	7.24	110.66
71108-T5A-J50	GARNISH,L.FR.BUMPER	1	29.00	25	21.75	1.52	23.27
71119-T5A-J50	GARNISH,L.FR.LOWER GRILLE	1	8.70	25	6.52	0.46	6.98
71130-T5A-J50ZZ	BEAM COMP,FR.BUMPER	1	213.00	25	159.75	11.18	170.93
71140-T5A-J50	BEAM UPPER,R.FR.BUMPER	1	27.70	25	20.77	1.45	22.22
71145-TAR-T50	BASE,FR.LICENCE PLATE	1	49.00	25	36.75	2.57	39.32
71190-T5A-J50	BEAM UPPER,L.FR.BUMPER	1	27.70	25	20.77	1.45	22.22
71193-T5A-000	SPACERR.FR.BUMPER	1	10.40	25	7.80	0.55	8.35
71198-T5A-000	SPACERL.FR.BUMPER	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER	10	2.30	25	17.25	1.21	18.46
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	3	23.20	25	52.20	3.65	55.85
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00	X	45.00	3.15	48.15
YH-175/65R15-S71A	YOKOHAMA TYRE	1	108.00	?	108.00	7.56	115.56
Sum Item					11667.08	816.72	12,483.80
BOSUN	SUNDRIES	1	60.00	20	60.00	4.20	64.20
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00

Printed on 1/8/2019 3:26:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SMA9169D

Chassis No : JHMGK3850JX222851

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : CHEN WEE KEONG

Ins Policy No. :

Date of Accident : 1/8/2019

Document No. : SQT19003373 Page 4

Date : 1. Aug 2019

Customer No. : WZ1007

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L13B11030797

Date | Time : 1. Aug 2019 8:48:33 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOJSE	BODY JOINT SEALANT.	1	150.00	100	150.00	10.50	160.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	160.00	120	160.00	11.20	171.20
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	✓	250.00	17.50	267.50
BMC01D	REMOVE & INSTALL RADIATOR WITH FAN MOTOR.	1	300.00	230	300.00	21.00	321.00
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH AN MOTOR.	1	350.00	250	350.00	24.50	374.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	350.00	300	350.00	24.50	374.50
BKOT00A	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT	1	1400.00	1000? phd.	1400.00	98.00	1498.00
BMS00R	RENEW BOTH DRIVER & PASSENGER AIRBAG ASSY ECU &	1	1800.00	560	1800.00	126.00	1926.00
BME00D	REMOVE & INSTALL ENGINE ASSY GEARBOX & OTHERS	1	1800.00	1120? phd.	1800.00	126.00	1926.00
BKBH11M	RENEW BULKHEAD, WHEELHOUSE ASSY & ALIGN CHASSIS	1	2800.00	2240	2800.00	196.00	2996.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2800.00	2250	2800.00	196.00	2996.00
Sum Labor					12320.00	862.40	13,182.40

Survey By

mercus hll

Date & Time

2/8/19 @ 12pm.

Excess

Status

not allowed

Signature

*the phd. survey
12-14dy.*

Total Amount 24,217.08 1,695.22 25,912.30

Total (Inclusive of GST) 25,912.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 1/8/2019 3:26:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.