

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

20-08-19

OUR REF NO. PA 9587U

SINGAPORE DUCKTOURS PTE. LTD.
82, AMOY STREET
#03-00
SINGAPORE 069901

ESTIMATE BILL FOR VEHICLE NO. PA 9587U

MODEL : SCANIA KUB4X2

SPECIAL NETT ITEM

- | | | |
|----------------------------|-------------|-------------|
| 1) REAR CORNER PANEL (RH) | \$ 800.00 | Rx |
| 2) REAR END FLIP DOOR (RH) | \$ 1,500.00 | Rx |
| | | \$ 2,300.00 |

LABOUR CHARGE

- | | | |
|---|-------------|--------------------|
| 1) TO SUPPLY LASER GRAPHIC ADVERTISEMENT LOGO MATERIAL | \$ 1,000.00 | 600 |
| 2) TO REMOVE AND CLEAN ADVERTISEMENT STICKER, CHEMICAL, CLEAN SURFACE AND REPASTE STICKER | \$ 1,500.00 | 300 |
| 3) TO RESPRAY ON AFFECTED AREAS | \$ 1,000.00 | 400 |
| 4) TO REPLACE NEW PARTS ETC | \$ 800.00 | 450 |
| | | \$ 4,300.00 |
| GRAND TOTAL | | <u>\$ 6,600.00</u> |

Tanpin 97495749
WP
20/8/19
sur@Mant.com
4 days.
Lumpsum
Resurvey after repair.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: