

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7695T**AAD1907-274***Not Authored**Recovery B4 painting*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

01 AUG 2019

SHB 7695T

JTDKB3FU403080156

TOYOTA

PRIUS

30.7.19

AXA

24/5/2019

		PART	LIST	
1	1	REAR BUMPER	\$ <i>Buc</i> 458.60	✓
2	1	REAR BUMPER RE-INFORCEMENT	\$ DE 318.80	✓
3	1	REAR BUMPER TOWING COVER	\$ <i>Sn</i> 14.70	X
4	1	REAR BUMPER UNDER COVER (BLACK)	\$ <i>Ad/ln</i> 552.60	✓
5	1	ANTENNA, ELECTRICAL KEY	\$ <i>Sn</i> 61.40	X
6	1	REAR BUMPER SIDE RETAINER LH	\$ <i>Sn</i> 112.70	} X
7	1	REAR BUMPER SIDE RETAINER RH	\$ <i>Sn</i> 112.70	
8	1	REAR TAILGATE	\$ <i>Sn</i> 1,547.27	
9	1	REAR TAILGATE OUTER GARNISH	\$ <i>Sn</i> 910.40	
10	1	COVER, REAR COMBINATION LAMP, RH	\$ <i>Sn</i> 54.70	
11	1	COVER, REAR COMBINATION LAMP, LH	\$ <i>Sn</i> 54.70	
12	1	GARNISH, BACK DOOR SIDE, LH	\$ <i>Sn</i> 93.60	
13	1	GARNISH, BACK DOOR SIDE, RH	\$ <i>Sn</i> 93.60	
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$ <i>Sn</i> 55.40	
15	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$ <i>Sn</i> 55.40	
16	1	BOARD ASSY, BACK DOOR TRIM	\$ <i>Sn</i> 254.40	
17	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$ <i>Sn</i> 51.20	
18	1	REAR TAILGATE WEATHERSTRIP	\$ <i>Sn</i> 365.20	
19	1	PANEL SUB-ASSY, BODY LOWER BACK (REAR END PANEL)	\$ <i>Sn</i> 641.50	
20	1	TAILLAMP LOWER RH	\$ <i>Sn</i> 548.40	} X
21	1	TAILLAMP UPPER RH	\$ <i>Sn</i> 557.90	
22	1	REAR BUMPER SIDE RH	\$ <i>Sn</i> 232.00	
23	1	REAR BUMPER SIDE LH	\$ <i>Sn</i> 232.00	
24	1	TAILLAMP LOWER LH	\$ <i>Sn</i> 548.40	
25	1	TAILLAMP UPPER LH	\$ <i>Sn</i> 557.90	
26	1	REAR RH FENDER PANEL	\$ <i>Sn</i> 836.70	
27	1	REAR LH FENDER PANEL	\$ <i>Sn</i> 836.70	X

Trans-cab Auto Services Pte Ltd**AAD1907-274**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7695T

28	1	LINER, REAR WHEEL HOUSE, LH	\$	<i>n</i>	138.10	}	<i>X</i>	
29	1	LINER, REAR WHEEL HOUSE, RH	\$	<i>n</i>	138.10			
30	1	BOARD, BACK DOOR TRIM	\$	<i>sn</i>	220.70			
31	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	<i>sn</i>	351.10			
32	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	<i>sn</i>	351.10			
33	1	COVER, FLOOR UNDER, NO.1	\$	<i>sn</i>	172.60			
34	1	COVER, FLOOR UNDER, NO.2	\$	<i>sn</i>	238.70	}		
35	1	COVER, REAR FLOOR	\$	<i>n</i>	226.80			
TOTAL			\$		11,996.07			
25%			\$		2,999.02			
			\$		8,997.05			

Special Nett

1	1SET	PARKING AID	\$	sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	na	22.00	✓
3	2	REAR WINDSCREEN SEALANT	\$	na	80.00	} X
4	1	WINDSCREEN MOULDING	\$	na	100.00	
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
6	1	REAR TAILGATE TOYOTA LOGO	\$	na	47.00	
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	na	52.90	
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	na	53.50	
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	na	80.00	}
10	1	REAR TAILGATE STICKER '6555-3333'	\$	na	80.00	
11	1	REAR BUMPER PROTECTOR	\$	na	100.00	400.00
12	1	REAR WHEEL RIM	\$	sn	1,570.55	} X
13	1	REAR WHEEL RIM COVER	\$	sn	175.80	
14	1	SPARE WHEEL RIM	\$	sn	1,570.55	
15	1	SPARE WHEEL RIM COVER	\$	sn	175.80	
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	}
17	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
TOTAL			\$		4,978.10	
TOTAL PARTS			\$		13,975.15	

LABOUR

Trans-cab Auto Services Pte Ltd**AAD1907-274**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7695T

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	2001
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00	X
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	2801
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	nn 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	501
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	101
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X

Trans-cab Auto Services Pte Ltd**AAD1907-274**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7695T

Labour charge to mount and dismount vehicle on jig
bench, to facilitate repair.

\$ *nn* 380.00 X**TOTAL \$ 12,100.00****Over All Total \$ 26,075.15****(PART-BY-PART) Repair Days**~~15 Days~~*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: