

**BIKE PRODUCTION PTE LTD**  
610, Serangoon Road S(218216)  
Tel: 63922555, 62995177 Fax: 62975400  
**ROC/ GST Reg No.: 200007407G**

Date: 29 Jul 2019

**ASSESSMENT FOR REPAIR: SUZUKI GSX1300RAZL4 - FBK6439Y**

Chassis No.: JS1CK131BE0100113  
Engine No.: X704152562

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front mudguard	\$440.00 <i>int</i>
1 pc	Front left fork assembly	\$1,680.00 <i>7 hr</i>
1 pc	Brake Fluid Dot 4	\$20.00 <i>x</i>
1 pc	Brake right caliper assy	\$520.00 <i>x</i>
1 pc	Left handle bar	\$450.00 <i>x</i>
1 pc	Clutch lever	\$95.00 <i>at</i>
1 pc	Left balancer	\$90.00 <i>at</i>
1 pc	Left view mirror	\$250.00 <i>at</i>
1 pc	Headlight front cover assy	\$680.00 <i>at</i>
1 pc	Left fairing lower	\$395.00 <i>at</i>
1 pc	Left fairing	\$795.00 <i>at</i>
1 pc	Left fairing black cover	\$295.00 <i>at</i>
1 pc	Left fairing emblem	\$195.00 <i>at</i>
1 pc	Gear pedal assy	\$255.00 <i>x</i>
1 pc	Left front footrest holder	\$235.00 <i>x</i>
1 pc	Left rear footrest holder	\$185.00 <i>x</i>
1 pc	Left front footrest	\$145.00 <i>x</i>
1 pc	Left rear footrest	\$125.00 <i>x</i>
1 pc	Side stand	\$195.00 <i>at</i>
1 pc	Left engine cover	\$695.00 <i>at</i>
1 pc	Left engine cover gasket	\$135.00 <i>at</i>
1 pc	Left exhaust assy	\$1,490.00 <i>at</i>
		<u>\$9,345.00</u>
	Less discount 10%	\$934.50
		<u>\$8,410.50</u>
<b><u>Special nett items</u></b>		
1 pc	ERP IU	\$157.00 <i>at</i>
4 pcs	Engine oil fully synthetic @ \$30.00	\$120.00 <i>at</i>
2 pcs	Front number plate	\$30.00 <i>at</i>
1)	Towing charges	\$100.00 <i>80 towing receipt</i>
2)	Replace, realign and adjust above damaged parts	\$800.00 <i>400</i>
3)	Balancing front and rear wheel rim	\$180.00 <i>30</i>
	To remove/refit, replace (if damage) check and	<i>120</i>
4)	straighten front fork tubes	\$180.00
5)	Check wiring and lighting system	\$60.00 <i>30</i>
	To knock, straighten chassis & body	
6)	balancing	\$450.00 <i>200 x photo</i>
7)	Spray painting	\$400.00 <i>300</i>
	<b>Total Estimate</b>	<u><u>\$10,487.50</u></u>

Note: The above estimate is subjected to the prevailing GST of 7%

For Bike Production Pte Ltd

Tanjil 97495749

Not Authorise

To Revert Ex: to be advise.

2/8/19 @ 5 pm.

lump sum To check part price

Resurvey after repair

sur@lkkauto.com

5 days.

**LKK Auto Consultants hence notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: