

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0929/2019/NS
Date : 31-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR. ZHOU SONG
Address : 63 CHESTNUT AVENUE
#17-12
Singapore 679523
Telephone : (HP) +65 97388624
Type of Claim : Own Damage Claim
Policy No. : 2100288690-07
Vehicle No : **SKE 3116 Z**
Model Code : Audi A4 1.8 TFSI MU (A)
Model / Year : Feb-12
Engine No : CDH 160215
Chassic No. : WAUZZZ8K6CA108173
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Jul-19
Place of Accident : GREATWORLD CITY OFFICE B1 CARPARK

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKE 3116 Z

S/n	Nature of Jobs	Estimated Charges	SURVEYOR'S RECOMMENDATION
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. To repair bonnet. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00 1250	
3	To respray front bumper, rhs front fender and bonnet. ✓ ✓	\$ 3,000.00 1650.	
4	To carry out diagnostic check	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>6,352.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SKE 3116 Z

S/N	Parts Description	Damaged Parts & Prices		REMARKS
		S/Nett		
1	FRONT BUMPER <i>Deland</i>	\$	2,041.00	✓
2	BUMPER FIXING PARTS <i>new</i>	\$	234.00	+
3	FRONT BUMPER IMPACT BAR <i>new</i>	\$	802.00	+
4	FRONT BUMPER SUPPORT - LH / RH <i>new</i>	2 \$	52.00	+
5	FRONT BUMPER GUIDE SECTION - RH <i>Damaged</i>	\$	40.00	✓
6	FRONT BUMPER COVER <i>stop covered</i>	\$	116.00	✓
7	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	160.00	+
8	FRONT BUMPER FOAM FILLER PIECE ?	\$	113.00	?
9	FRONT BUMPER VENT GRILLE - RH ?	\$	156.00	?
10	COVER <i>new</i>	\$	89.00	+
11	FENDER - RH <i>Dented</i>	\$	904.00	✓
12	FENDER ATTACHMENT PARTS - FRONT ?	\$	52.00	?
13	FENDER BRACKET - RH FRONT ?	\$	48.00	?
14	DEFORMATION ELEMENT BRACKET - RH REAR ?	\$	45.00	?
15	POP RIVET <i>new</i>	4 \$	12.00	✓
16	FENDER BRACE - RH LOWER <i>Best</i>	\$	107.00	✓
17	WHEEL HOUSING LINER <i>new</i>	\$	223.00	+
18	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$	41.00	+
19	MAIN BEAM HEADLIGHT MOUNTING - RH <i>new</i> ?	\$	107.00	?
20	BRACKET - RH <i>new</i>	\$	71.00	+
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 5,413.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SKE 3116 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	REMARKS
1	HALOGEN HEADLIGHTS - RH <i>cancel</i>	\$ 994.00	✓
2	HALOGEN FOG L AMP - RH <i>men</i>	\$ 238.00	+
3	SIGNAL HORN - RH LOW TONE <i>3 men</i>	\$ 184.00	+
4	SPRING SHACKLE - RH LOW TONE	\$ 23.00	+
5	AIR DUCT - RH <i>men</i>	\$ 25.00	+
6	SEALING STRIP <i>not n</i>	\$ 21.00	+
7	CAUTION' SIGN STICKER <i>3 men</i>	S/N \$ 13.00	+
8	AIRCON STICKER	S/N \$ 18.00	+
9	SUNDRIES <i>?</i>	\$ 400.00	?
TOTAL SPARE PARTS CHARGES		: \$ 7,329.00	
TOTAL LABOUR CHARGES		: \$ 6,352.00	
GRAND TOTAL		: <u>\$ 13,681.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ly
Surveyed Date : 02/08/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, OS ap

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant