

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0928/2019/NS
Date : 31-Jul-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR SOHN SEOG HUN
Address : 37 JURONG EAST AVENUE 1
#02-03
Singapore 609775
Telephone : HP +65 98623004
Type of Claim : Own Damage Claims
Policy No. : 1700033001-02
Vehicle No : **SLR 1213 J**
Model Code : Audi A6 1.8 TFSI S TRONIC
Model / Year : Jul-17
Engine No : CYG 017930
Chassis No : WAUZZZ4GXHN068164
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Jul-19
Place of Accident : ALONG FARRER ROAD

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 1213 J

S/N	Nature of Jobs	Estimated Charges	SURVEYOR'S RECOMMENDATION
1	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for devices.	s/n \$ 280.00	✓
2	To dismantle lhs rear door and lhs sill panel trim. To repair lhs front door and lhs rear fender. To renew lhs rear door. Re-organise crash management components. Reinstall all parts removed.	\$ 3,200.00	650 750. 2200
3	To respray lhs rear fender, lhs front door, lhs rear door, door handles and lhs sill panel trim.	\$ 4,500.00	2200 4 x 550 = 2200 sill panel trim
4	To carry out diagnostic check.	s/n \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,172.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 1213 J

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	STONE GUARD FILM - LH FRONT <i>new</i>	\$ 110.00	✓
2	REAR DOOR - LH <i>Dented</i>	S/N \$ 3,374.00	✓
3	DOOR ATTACHMENT PARTS ?	\$ 76.00	?
4	OUTER DOOR SEAL <i>new</i>	NEC \$ 212.00	+
5	BONDING AGENT ?	NEC \$ 45.00	?
6	CLEANING SOLUTION ?	NEC \$ 65.00	?
7	DOOR CATCH <i>new</i>	\$ 109.00	+
8	SILL PANEL TRIM ATTACHMENT PARTS <i>new ?</i>	\$ 81.00	?
9	ADHESIVE TAPE ?	\$ 15.00	?
10	WINDOW SLOT SEAL - LH FRONT ? <i>new</i>	\$ 310.00	+
11	WINDOW SLOT SEAL - LH REAR	\$ 256.00	+
12	STONE CHIP <i>new</i>	S/N \$ 180.00	✓
13	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		: \$ 5,133.00	
TOTAL LABOUR CHARGES		: \$ 8,172.00	
GRAND TOTAL		: <u>\$ 13,305.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lim*
Surveyed Date : *02/08/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 05 Days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant