

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 4Z

AAD1907-278

*Not Authorized
11/2/2015*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model: **01 AUG 2019**
Date of Accident :
Third Party Insurer :
Date of Registration :

SHD 4Z
VF1ABL15AUC281522
RENAULT
LATITUDE
31.7.19
AIG
23/3/2015

PART		LIST	
1	1 BUMPER COVER REAR	\$ CMA 1,108.46	✓
2	1 BUMPER LOWER REAR	\$ ncl/w 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$ S 113.47	X
4	1 BUMPER BRACKET SIDE RH REAR	\$ S 135.97	X
5	1 BUMPER RETAINER RH REAR	\$ S 44.99	X
6	1 BUMPER REFLECTOR RH	\$ S 43.61	X
7	1 BUMPER BRACKET SIDE LH REAR	\$ S 135.97	X
8	1 BUMPER RETAINER LH REAR	\$ S 44.99	X
9	1 BUMPER REFLECTOR LH	\$ CMA 43.61	✓
10	1 BUMPER BEAM REAR	\$ B 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ D 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$ R 225.95	X
13	1 OUTER PANEL REAR (End Panel)	\$ R 1,471.77	} X
14	1 OUTER PANEL REAR (End Panel)TRIM	\$ S 404.56	
15	1 TAILLAMP RH	\$ S 552.55	
16	1 TAILLAMP PANEL RH	\$ R 986.70	
17	1 TAILLAMP LH	\$ S 552.55	
18	1 TAILLAMP PANEL LH	\$ R 986.70	
19	1 BOOT REAR	\$ R 2,872.68	
20	1 BOOT FINISHER	\$ S 470.06	
21	1 BOOT WHEATERSTRIP	\$ S 323.05	
22	1 BOOT REFLECTOR LAMP LH	\$ S 493.35	
23	1 BOOT REFLECTOR LAMP RH	\$ S 493.35	
24	1 BOOT BADGE 'RENAULT'	\$ na 225.36	
25	1 BOOT BADGE	\$ na 225.36	
26	1 BOOT STRUT LH	\$ S 276.08	
27	1 BOOT STRUT RH	\$ S 276.08	

Trans-cab Auto Services Pte Ltd

AAD1907-278

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 4Z

28	1	BOOT HINGE LH	\$	<i>R</i>	367.84	} X
29	1	BOOT HINGE RH	\$	<i>R</i>	367.84	
30	1	BOOT INNER TRIM	\$	<i>S</i>	586.45	
31	1	BOOT SWITCH	\$	<i>S</i>	168.13	
32	1	BOOT LOCK	\$	<i>R</i>	202.67	
33	1	BOOT LOCK CATCH	\$	<i>R</i>	74.40	
TOTAL			\$		16,046.87	
10%			\$		1,604.69	
			\$		14,442.19	

Special Nett

1	1SET	PARKING AID	\$	<i>S</i>	700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>R</i>	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>R</i>	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>R</i>	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	<i>R</i>	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>R</i>	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	<i>R</i>	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>R</i>	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>R</i>	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	<i>R</i>	30.00	X
11	1	BOOT STICKER "6555-3333"	\$	<i>R</i>	30.00	X
12	1	EXHAUST MOUNTING REAR	\$	<i>S</i>	17.82	} X
13	2	REAR WINDSCREEN SEALANT	\$	<i>R</i>	80.00	
14	1	WINDSCREEN MOULDING	\$	<i>R</i>	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>R</i>	100.00	
16	1	BOOT INNER TRIM CLIP	\$	<i>R</i>	45.00	
17	1SET	BOOT FINISHER CLIP	\$	<i>R</i>	24.20	
18	1	TAILLAMP CLIP LH	\$	<i>R</i>	5.00	
19	1	TAILLAMP CLIP RH	\$	<i>R</i>	5.00	
TOTAL			\$		1,384.02	

TOTAL PARTS \$ 15,826.21

LABOUR

To Check Electrical Lighting Concerned. \$ 170.00 *15h*

Trans-cab Auto Services Pte Ltd

AAD1907-278

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 4Z

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00 X
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <i>600</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00 <i>2000</i>
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 <i>2200</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i> 380.00 X

TOTAL \$ 11,550.00

Over All Total \$ 27,376.21

LUMP SUM (REPAIR DAY) 15 DAYS
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: