

22/03/2012

ASS. REC. BY:

REF: CS/SMD 19013585 / Dsf³

Special Instruction:

market value

Surveyor

Bryan

ASSIGNMENT (Office)

From (Person): Agres chan shu Hui

of SMO

Date/Time: 2.8.19 16:58 p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 8845K

Insured: YP 9624K

at Workshop m/s Channi motor

Tel: 65427162

of BIK 10 701-05/06

Policy No: D19MTHCVE000189

Claim No: CMD 1903712

Sum Insured:

Excess:

Make of Veh:

D.O.A. 1.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 5.8.19 5:12 p.m

Person Contacted: Lynn

H.O.D. Endorsement:

Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate | |
|-----------|--------------------------------------|--------------------|
| | SHD 8845K - NS/INC 13003659 / k10b12 | D.O.A - 15/6/2018 |
| | YP 9624K - CS/SMD/8021291 / T1462 | D.O.A - 04/12/2018 |
| 5/8/19 | Send preli revised via merimen | |

REF:

ASSIGNMENT

10/12 Sept 2020

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No. 8HD 8845K Yr Regn: 2012 SeptType: M.Car / M.Cycle / Bus / Van / Lorry (C) / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E220.c 2143Colour: white A/C: Insured / Std / NI / NASp. Reading: N/A T/Radio: Insured / Std / NI / NAEng/No: 65192431508067C/No: WDD2120022A681512Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 01/08/2019 D.O.I. 05/08/2019Survey held at Chunni AMC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Sompo 5P9624K

10/08/19 vehicle total loss. N/A safe to repair as LH front wheel house* badly crumpled affecting the firewall panel. To submit unsage to repair.

BV 36.5K

L/A 33K

HL 3.5K

vehicle balance 1 yr.

RECEIVED 15 AUG 2019

Date/Time, File Pass to?

15/08/19
Tipist☐ : Preli. Report☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 14Resurvey No. of Trip: 1Survey Fee: 450

Transportation

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format: Total Loss

Lump Sum / I.B.I. (\$) _____

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---------|---------------|------------|--|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 02 Aug 2019 | | 02 Aug 2019 16:58 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|--|------------------------|------------------------------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | ETHOZ GROUP LTD, Co. Reg. No.: 198104531H | | | | | | | | |
| Main Claimant: | LOW KIM HENG (LIU JINXING), ID: S7719164Z | | | | | | | | |
| Vehicle Reg. No.: | SHD8845K | Date of Loss: | 01/08/2019 05:00 - :59 | | | | | | |
| Claim Type: | TP / CMTD1903712 | Policy/Cover Note No.: | D19MTHCVE000189 (Third Party Only) | | | | | | |
| Vehicle Reg. No. (Insured): | YP9624K | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016 | | | | | | | | |
| Handling Insurer: | Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/08/2019] | | | | | | | | |
| Adj Asg. Remarks: | Please assign to Mr Rasul and to conduct the survey on a without prejudice and without admission or liability basis. | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

View Sent Message

This mail is associated with :

***SHD8845K (CMTD1903712)
[YP9624K]**

TP

LOW KIM HENG (LIU JINXING)

Aug 1 2019 5:00AM

[ETHOZ GROUP LTD]

Chunni Motor Work Pte Ltd - Amk

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **15/08/2019 15:37 PM.**
To agnes.chan@sompo.com.sg
CC sur@lkkauto.com
Subject SHD8845K (CMTD1903712) [YP9624K] TP

Hi Agnes,

Kindly inform vehicle recommended total loss due to unsafe for repair.

We will submit our report accordingly.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 05 Aug 2019

Preliminary Advice

| | | | |
|--------------------|-----------------------------|-------------------------|--------------|
| Insured Vehicle No | : YP9624K | Accident Date | : 01/08/2019 |
| TP Vehicle No | : SHD8845K | Assignment Date | : 02/08/2019 |
| Make | : MERCEDES-BENZ E220 | Est. Duration of Repair | : 14 |
| Date of Inspection | : 5/8/2019 | | |
| Inspection At | : CHUNNI MOTOR WORK PTE LTD | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 54,109.60 |
| Revised Amount | :S\$ | 24,710.53 |
| Check Items (Estimated) | :S\$ | 13,902.19 |
| Total | :S\$ | 38,612.72 |

| | | |
|-----------------|------|--|
| Lump Sum Repair | :S\$ | |
|-----------------|------|--|

Total Loss Consideration

| | | |
|--------------------|------|--|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | |
| COE / PARF Rebate | :S\$ | |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | |

Remarks

☐ The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

☐ The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

☒ Other comments :The above survey was conducted on a 'Without Prejudice' basis.

MCD619100543 / ComfortDelGro Engineering Pte Ltd - Loyal
 ENTRY DATE & TIME: 01/08/2019 09:43
 SUBMITTED BY: Huang XiaoYan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GlA Records Management Centre established by the General Insurance Association of Singapore (GlA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 01/08/2019 09:43
 Date Of Accident 01/08/2019 05:15
 Exact Location Of Accident EU TONG SEN ST TOWARDS HILL ST
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD8845K
 Insured/Policyholder
 Name Of Registered Owner CITYCAB PTE LTD
 Co Reg No 199502839G
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
 Vehicle Particulars
 Manufacturer MERCEDES-BENZ
 Model E220
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
 Insurance Company
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number D-18088937MFSH
 Cover Note Number
 Driver
 Name of Driver LOW KIM HENG (LIU JINXING)
 NRIC No S7719184Z
 Date Of Birth 16/07/1977
 Occupation OUTDOOR
 Date Of Driving Pass 18/04/2000
 Driving Experience 19 YEARS AND 3 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-81010912
 Fax Number
 Contact Number
 EMail Address VIN9945@YAHOO.COM.SG

Address BLK 18 JALAN SULTAN #15-156
 Postcode 190018
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY
 Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3

Passenger 1
 NAME: : -
 GENDER: : FEMALE
 Passenger 2
 NAME: : -
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 POLICE STATION NAME [OTHER] PASIR RIS N.P.C
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED / POLICE REPORT : T/20190801/2025 / Type Of Accident : HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP9624K
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CITYCAB PTE LTD
CO. REG. NO. 199502839G


Policyholder's Signature
Date & Time: 1/8/2019

Driver's Signature
(If driver is not the policyholder)
Date & Time: 1/8/2019
@09:10hrs

Lisa

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As attached Police Report no:T/20190801/2025

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CITYCAB PTE LTD
CO. REG. NO. 199502839G

Policyholder's Signature
Date & Time: 1/8/2019

Driver's Signature
(If driver is not the policyholder)
Date & Time: 1/8/2019
@09:10hrs

Lisa
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


**SINGAPORE
POLICE FORCE**


T/20190801/2025

1 of 3

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

Report No. T/20190801/2025

REPORT OF A TRAFFIC ACCIDENT

| | | |
|--|-------------------------------------|--------------------------|
| Date/Time Report Made: 01/08/2019 07:32 | Vide Report No.: A/20190801/0051 | Station Diary No.: 32 |
|--|-------------------------------------|--------------------------|

Informant's Particulars

| | | | | |
|--|------------|------------------------------|--|----------------------------|
| Name of Informant: LOW KIM HENG | | | Address: APT BLK 18 JALAN SULTAN #15-156 SINGAPORE 190018 | |
| ID Type / ID No.: NRIC NO / S7719164Z | | | Contact No.: Home/Office: | Mobile: 81010912 |
| Nationality: SINGAPORE CITIZEN | | | Email: | |
| Sex: Male | Age: 42 | Date of Birth: 16/07/1977 | Type of Informant: Driver | |
| Race: Chinese | | | Language: English | Institution / School Name: |
| Occupation: Taxi driver | | | Driving Licence Information: Class: 3 | Date of Expiry: |

General Information of the Accident

| | | | | |
|--|------------------------------|------------------------------------|---|---|
| Type of Accident: | Injury Attended by Police | Drink Drive: No | Date/Time of Accident: 01/08/2019 05:15 | Type of Location: Straight Road |
| Location: Along Road 1 EU TONG SEN STREET HILL STREET Eu Tong Sen St towards to Hill St (Lamp post 21) Lamp Post Number: 21 | | | | |
| Weather: Clear | | Road Surface: Dry | | Road Speed Limit: |
| Traffic Flow: Two Way | | Traffic Control: Not Controlled | | Traffic Volume: No Traffic |
| Type of Collision: Between Moving Vehicles - Head To Rear | | | | Anyone conveyed by ambulance: Yes |

Details of Vehicle Involved

| Vehicle No. | Type | Make | Model | Color | Condition | No of Passenger |
|-------------|------|------|-------|-------|------------------|-----------------|
| SHD8845K | Car | | | | Slightly Damaged | 2 |

Details of Person Involved

| | |
|---------------------------------|--------------------------------|
| Any Pedestrian Involved: No | |
| No. of Pedestrians Injured: NIL | Use of Pedestrian Crossing: NA |



**SINGAPORE
POLICE FORCE**



T/20190801/2025

2 of 3

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

Report No. T/20190801/2025

CONTINUATION OF REPORT

| | | | |
|-----------------------------------|----------------|------------------|---|
| Driver | | | |
| Name | LOW KIM HENG | | ID No. S7719164Z |
| Related Vehicle | SHD8845K (Car) | | Contact No. 81010912 |
| Hospital/Clinic | NIL | | Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |
| Passenger | | | |
| Name | SOH YUEN YOKE | | ID No. S0321506G |
| Related Vehicle | SHD8845K (Car) | | Contact No. NIL |
| Hospital/Clinic | NIL | | Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | Serious |

Brief Details.

On 01/08/2019 at about 0519hrs, while I was driving a limousine taxi (SHD8845K) along Eu Tong Sen St extreme right lane heading towards Hill St. My passenger is my aunty age of 70 years old and with her domestic helper. While driving straight I could see a lorry front of me coming from opposite road (Eu tong sen st towards cantonment rd) making a U-turn into (Eu Tong Sen St towards Hill St).

I kept close to the center divider on my right trying to avoid the lorry, however, the lorry turned quite fast in front of me and went into lane 2 instead of lane 1 which is my lane. I ended up collided on the lorry right rear portion. As resulted my aunty left elbow skin was badly peeled off and her domestic helper sustained some minor injuries.

I wish to state that my front portion of my car is badly damaged and my taxi has a in car camera.

I am lodging this traffic accident report for insurance claims purpose.

**SINGAPORE
POLICE FORCE**

T/20190801/2025

3 of 3

Report No. T/20190801/2025

Police Station Of Origin:

Pasir Ris N.P.C

1 Pasir Ris Drive 4 #01-01 SINGAPORE

519457

Tel No: 1800-5852999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 LOW JAMES GABRIEL

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt SUFIYAN BIN KHAIRI

Contact No: 65476390 SINGAPORE

POLICE FORCE

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

01/08/2019 07:32

Classification Of Case:

SIGNATURE

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|---|--------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 839G |
| Vehicle Details | |
| Vehicle No.: | SHD8845K |
| Vehicle to be Exported: | Yes |
| Intended Deregistration Date: | 05 Aug 2019 |
| Vehicle Make: | MERCEDES BENZ |
| Vehicle Model: | E 220 CDI BLUEEFFICIENCY |
| Primary Colour: | White |
| Manufacturing Year: | 2012 |
| Engine No.: | 65192431508067 |
| Chassis No.: | WDD2120022A681512 |
| Maximum Power Output: | 125.0 kW (167 bhp) |
| Open Market Value: | \$40,934.00 |
| Original Registration Date: | 12 Sep 2012 |
| First Registration Date: | 12 Sep 2012 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$40,934.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 11 Sep 2020 |
| PARF Rebate Amount: | \$26,607.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 11 Sep 2020 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 8 |
| QP Paid: | \$46,801.00 |
| COE Rebate Amount: | \$6,435.00 |
| Total Rebate Amount: | \$33,042.00 |
| Message | |
| Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. | |

The information contained herein is correct as at 05 Aug 2019

OK

REPAIR ESTIMATE*

DATE : 1.08.2019

TEL : 6542 5119

FAX : 6542 6039

Comp

| MODEL | : MERCEDES | | FAX | 0542 0057 |
|-------|--|------|-------------|-------------|
| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
| | Bumper Assy, Frt <i>broken</i> | | | \$ 1,890.50 |
| | Bumper Reinforcement, Frt <i>bt</i> | | | \$ 1,158.00 |
| | Bumper Bracket, Frt/LH/RH <i>broken</i> | | \$ 95.00 | \$ 190.00 |
| | Bumper Absorber, Frt/LH/RH <i>o/s NH N/S bt</i> | | \$ 295.00 | \$ 590.00 |
| | Bumper Frame, Frt/Centre <i>NH</i> | | | \$ 389.00 |
| | Bumper Frame, Frt/LH <i>broken</i> | | | \$ 168.00 |
| | Bumper Sponge, Frt/Centre <i>NH</i> | | | \$ 285.00 |
| | Bumper Sponge, Frt/LH <i>dislodged</i> | | | \$ 250.00 |
| | Bumper Sponge Extension, Frt/LH <i>NH</i> | | | \$ 105.00 |
| | Bumper Inner Clip, Frt <i>NH</i> | | | \$ 22.00 |
| | License Plate Trim Cover, Frt <i>NH</i> | | | \$ 155.00 |
| | Head Lamp Assy (LH/RH) <i>N/S broken o/s ?</i> | | \$ 2,380.00 | \$ 4,760.00 |
| | Head Lamp Bracket (LH/RH) <i>N/S broken o/s NH</i> | | \$ 300.00 | \$ 600.00 |
| | Radiator Top Panel, Frt <i>bt</i> | | | \$ 330.50 |
| | Head Lamp Panel (LH/RH) <i>o/s NH N/S broken</i> | | \$ 480.00 | \$ 960.00 |
| | Radiator Grille <i>broken</i> | | | \$ 1,220.00 |
| | Radiator Grille Star Logo <i>broken</i> | | | \$ 170.00 |
| | Radiator Grille Adjuster Bracket <i>broken</i> | | | \$ 685.70 |
| | Bonnet Assy <i>fine</i> | | | \$ 2,850.60 |
| | Bonnet Mercedes Star Logo <i>Down</i> | | | \$ 112.00 |
| | Bonnet Hinge (LH/RH) <i>bt</i> | | \$ 285.50 | \$ 571.00 |
| | Bonnet Shock Absorber <i>Down</i> | | | \$ 295.40 |
| | Bonnet Insulator <i>bt</i> | | | \$ 235.40 |
| | Bonnet Centre Lock <i>bt</i> | | | \$ 95.00 |
| | Bonnet Lock, Top <i>bt</i> | | | \$ 94.00 |
| | Bonnet Lock Lower (2 pcs) <i>N/S Down o/s NH</i> | | \$ 92.00 | \$ 184.00 |
| | Bonnet Lock Brace Panel <i>bt</i> | | | \$ 64.80 |
| | Bonnet Air Inlet Grille <i>broken</i> | | | \$ 269.25 |
| | Fender, Frt/LH <i>fine</i> | | | \$ 996.08 |
| | Fender Splashshield, Frt/LH (Front) <i>dislodged</i> | | | \$ 257.00 |
| | Fender Splashshield, Frt/LH (Rear) <i>dislodged</i> | | | \$ 263.00 |
| | W/House Assy, Frt/LH <i>fine</i> | | | \$ 5,346.00 |
| | Horn (Woofer) (LH) <i>?</i> | | | \$ 228.00 |
| | Horn (Tweeter) (LH) <i>?</i> | | | \$ 228.00 |
| | Radiator Assy <i>?</i> | | | \$ 1,345.00 |
| | Radiator Fan Blower Assy <i>?</i> | | | \$ 1,385.40 |
| | Radiator Shroud <i>?</i> | | | \$ 1,225.60 |
| | Radiator Air Baffle, Top <i>broken</i> | | | \$ 80.00 |
| | Radiator Air Baffle, Lower <i>broken</i> | | | \$ 125.90 |
| | Radiator Dowel Pin -2 pcs <i>NH</i> | | \$ 14.00 | \$ 28.00 |
| | Radiator Mounting Lower <i>NH</i> | | | \$ 8.00 |
| | Radiator Mounting Top-2 pcs <i>NH</i> | | \$ 19.00 | \$ 38.00 |
| | Radiator Hose, Top <i>dislodged</i> | | | \$ 75.00 |
| | Radiator Hose Lower <i>NH</i> | | | \$ 95.00 |
| | Aircon Condenser <i>?</i> | | | \$ 1,235.80 |
| | Aircon Discharge Hose/Pipe <i>bt</i> | | | \$ 372.55 |

SHD 8845K

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|--|---|------|------------|--------------------|
| | Turbo Charger Air Cooler ? | | | \$ 1,053.80 ? |
| | Turbo Charger Cooler Hose, RH ? | | | \$ 313.60 X |
| | Turbo Charger Cooler Hose, LH ? | | | \$ 75.45 X |
| | Turbo Charger Cooler Hose, Top ? | | | \$ 92.50 X |
| | Wheel Rim, LH ? | | | \$ 1,250.00 X |
| | Tyre 205/60R16 Yokohama, LH ? | | | \$ 480.00 X |
| | Wheel Hub Bearing, Frt, LH ? | | | \$ 1,250.00 ? |
| | Windscreen Glass, Frt ? | | | \$ 1,850.00 ✓ |
| | Windscreen Side Moulding, Frt/LH ? | | | \$ 330.00 ✓ |
| | S/Absorber, Front LH ? | | | \$ 944.00 ? |
| | Strut, Frt/LH ? | | | \$ 604.00 ? |
| | Steering Knuckle Arm, Frt/LH ? | | | \$ 1,119.00 ? |
| | Lower Arm Assy, Frt/LH ? | | | \$ 661.05 ? |
| | Top Arm Assy, Frt/LH ? | | | \$ 720.00 ? |
| | Torsion Bar Rod, Frt/LH ? | | | \$ 375.00 ? |
| | Torsion Bar Frt/LH ? | | | \$ 470.00 ? |
| | Engine Crossmember ? | | | \$ 2,985.50 X |
| | Engine Mounting (LH/RH) ? | | \$ 450.80 | \$ 901.60 X |
| | P/Steering Cooling Pipe ? | | | \$ 556.80 ✓ photo |
| | P/Steering Gear Assy ? | | | \$ 7,167.00 X |
| | SUB TOTAL | | | \$ 55,231.78 |
| | LESS 10% | | | \$ 5,523.18 |
| | DISCOUNTED TOTAL | | | \$ 49,708.60 |
| | Number Plate, Frt (Merc Taxi) ✓ | | | \$ 50.00 |
| | Head Lamp Bulb, LH ? | | | \$ 25.00 |
| | Sikaflex 255 FCC 310ml ? | | | \$ 46.00 |
| | | | | Nett 45/- |
| | | | | Nett X |
| | | | | Nett ✓ |
| | | | | \$ 121.00 |
| | Labour Charge | | | |
| | Panel Beating | | | \$ 1,600.00 1200/- |
| | Spray Painting Charge | | | \$ 1,300.00 800/- |
| | Wiring Charge | | | \$ 50.00 30/- |
| | Towing Charges | | | \$ 50.00 20/- |
| | Tuff Kote | | | \$ 100.00 40/- |
| | Remove/Refix Undercarriage (FRT) | | | \$ 200.00 ? |
| | FRT Wheel Alignment | | | \$ 120.00 60/- |
| | Remove/Refix Aircon & Refill Gas | | | \$ 100.00 80/- |
| | Remove/Refix Dashboard | | | \$ 250.00 200/- |
| | Remove/Refix Front Windscreen Glass | | | \$ 120.00 80/- |
| | Remove/Refix Cushion & Upholstery Front | | | \$ 90.00 70/- |
| | Re-set and Diagnosis | | | \$ 300.00 280/- |
| | TOTAL LABOUR | | | \$ 4,280.00 |
| | ESTIMATE TOTAL | | | \$ 54,109.60 |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. | | | | |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Elementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL LABOUR

ESTIMATE TOTAL

Vehicle
TAN HSS.
Not age
to repair

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

ryan

LKK Auto

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--|--|--|------------|---|
| Main | 02 Aug 2019 | | 02 Aug 2019 16:58 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

| | | | |
|-----------------------------|--|------------------------|--|
| Insured: | ETHOZ GROUP LTD, Co. Reg. No.: 198104531H | | |
| Main Claimant: | LOW KIM HENG (LIU JINXING), ID: S7719164Z | | |
| Vehicle Reg. No.: | SHD8845K | Date of Loss: | 01/08/2019 05:00 - :59 [82 Months and 20 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / CMTD1903712 | Policy/Cover Note No.: | D19MTHCVE000189 (Third Party Only) |
| Vehicle Reg. No. (Insured): | YP9624K | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016 | | |
| Handling Insurer: | Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 15/08/2019] | | |
| Adj Asg. Remarks: | Please assign to Mr Rasul and to conduct the survey on a without prejudice and without admission or liability basis. | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

***SHD8845K (CMTD1903712)**
[YP9624K]
TP
LOW KIM HENG (LIU JINXING)
Aug 1 2019 5:00AM
[ETHOZ GROUP LTD]
Chunni Motor Work Pte Ltd - Amk

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

































Assessment Reports
















































1 per page ☒














































| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
|----|----------------|-----------------------------------|--|-------------------------------------|
| 1 | 05/08/19 14:30 | Adjuster Immediate Advice |  Load HTM | <input checked="" type="checkbox"/> |





















Photos/Images

3 per page ☒

| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
|----|-----------------|-----------------------------------|--|-------------------------------------|
| 1 | 10/08/19 15:15 | Front View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 10/08/19 15:15 | Front View Left |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 10/08/19 15:15 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 10/08/19 15:15 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 10/08/19 15:15 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 10/08/19 15:15 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 10/08/19 15:15 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports | | | 1 per page ▾ | <input checked="" type="checkbox"/> |
|--------------------|----------------|-----------------------------------|--|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 33 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 10/08/19 15:16 | General View | Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports | | | 1 per page ▼ | <input checked="" type="checkbox"/> |
|--------------------|----------------|-----------------------------------|--|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 81 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 82 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 83 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 84 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 85 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 86 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 87 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 88 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 89 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 90 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 91 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 92 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 93 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 94 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 95 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 96 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 97 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 98 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 99 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 100 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 101 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 102 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 103 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 104 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 105 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 106 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 107 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 108 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 109 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 110 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 111 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 112 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 113 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 114 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 115 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 116 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 117 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 118 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 119 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 120 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 121 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 122 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 123 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 124 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 125 | 10/08/19 15:16 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 126 | 10/08/19 15:16 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 127 | 10/08/19 15:16 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 128 | 10/08/19 15:16 | General View | Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports | | | 1 per page ▼ | ✓ |
|--------------------|-----------------|--|--|-------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 129 | 10/08/19 15:16 | General View |  Load JPG | ✓ |
| 130 | 10/08/19 15:16 | General View |  Load JPG | ✓ |
| 131 | 10/08/19 15:16 | General View |  Load JPG | ✓ |
| 132 | 10/08/19 15:16 | General View |  Load JPG | ✓ |
| 133 | 10/08/19 15:16 | General View |  Load JPG | ✓ |
| 134 | 10/08/19 15:16 | General View |  Load JPG | ✓ |
| 135 | 10/08/19 15:16 | General View |  Load JPG | ✓ |
| 136 | 10/08/19 15:16 | General View |  Load JPG | ✓ |
| 137 | 10/08/19 15:16 | General View |  Load JPG | ✓ |
| 138 | 10/08/19 15:16 | General View |  Load JPG | ✓ |
| 139 | 10/08/19 15:16 | General View |  Load JPG | ✓ |
| 140 | 10/08/19 15:16 | General View |  Load JPG | ✓ |
| 141 | 10/08/19 15:16 | General View |  Load JPG | ✓ |
| 142 | 10/08/19 15:16 | General View |  Load JPG | ✓ |
| 143 | 10/08/19 15:16 | General View |  Load JPG | ✓ |
| 144 | 10/08/19 15:16 | Chassis Number |  Load JPG | ✓ |
| Documentation | | | 1 per page ▼ | ✓ |
| No | Finalized On | Sompo Insurance Singapore Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 02/08/19 16:36 | Repair Estimates |  Load PDF | |
| 2 | 02/08/19 16:57 | PRI - LKK |  Load HTM | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 16/08/19 16:43 | LTA REBATE |  Load PDF | |
| 2 | 22/08/19 14:43 | TOTAL LOSS LETTER |  Load PDF | |

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19013585/DSF3S2
Date: 22/08/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D19MTHCVE000189
Claimant Vehicle No: SHD8845K Insured Vehicle No: YP9624K
Date of Loss: 01/08/2019 Nature of Claim: TP Claim No: CMTD1903712

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD8845K Engine No: 65192431508067
Make & Model: MERCEDES-BENZ E220, 2.0 (A) Chassis No: WDD2120022A681512
Reg. Date: 12/09/2012 (Man. Year: 2012) Odometer: 0 km
Colour: White
Engine Capacity: 2143 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 02/08/2019
Date Inspected: 05/08/2019 Inspected At: Chunni Motor Work Pte Ltd - Amk (HQ)
Estimated Period of Repair: 0.0 days Blk 10 #01-05/06, AMK Autopoint
Singapore 568047

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 16 Aug 2019) |
| Parts: | 143 | MERCEDES-BENZ E220 2.0 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SHD8845K) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >