1 4 4 /	r · · · · · · · · · · · · · · · · · · ·
ASS. REC. BY:	/ CC3/TMI 19013619/KVf3 172
Kenneth	ASSIGNMENT
From: Date:	
Estimated Cost:	- Yr Regn: // /
OD (TP) WS I TP RES I OD RES I EVA I INV I MV	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / Truck / Traller or
To Inspect Vehicle No:	Make: Reneult Controle co 1893
at Workshop m/s Trans Coh	Colour M Whit ID 1 Controle c.c 1773
of	Sp. Reading 48481 TRANSING Insured / Std / NI / NA
Insured: SUC 2068S	Sp.Reading 49484/ T/Radio: Insured / Std / NI / NA Eng/No:
Policy No. MK000573	
Claims No. m1905851	Gen. Cond: Good/Fair/Poor/Burnt
Sum Insured: Excess:	Sleering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: MI STD A/Rim or
(Policy Condition)	Tyre Size: F: 215/60216
Remark: The veh had commenced its N/S O/S	5 1
repair at the time of inspection.	TOYO I YOKO or GITI
Bal. or Market Value: 643; 5000	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bai. A mm R/Bai 7
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 7 mm L/Bal 7
Est. Repairs: O Zdays Res.: Yes or No	D.O.A. 31/7/19 D.O.L. 2/8/19
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date:Person Contacted: Vehicle: IN / OUT	013 179
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
/ Fix poss to	
5 8 19 61 Em 6 25501. (Red 42.	666.43 9490
	KPL362 P.UA-22/04/2016
COLC E I CO	
sold Emen and to Imi	RECEIVED D & AUG 2019
Oote/Time, File Pass to?	
: Prell. Report	Days Of Repair: 2
Outa/Time, File Return 10?	Resurvey No. of Trip: Survey Fee:
2 (10 1 1	Transportation: 250
Add Fee:	: Site Insp (\$)s-Rssi 11
Report Format: Merimen	: Interview (\$), Fix 735
	Tech Invs (\$). Others
Lump Sum / I.B.I: (S >550 2	Weekend (\$
	10144 201

...CLAIM SUBFOLDER...(Pending for Survey Report)

	FOLDER TRA	Est Submitted	Adt Assigned	Adi Rpt	Adj Subr	nitted 1	ns Authled	Status	
Main	01 Aug 2019	Est Submitted	05 Aug 2019 14:05 Edit Adj Rpt					Pending for Surv Report Cancel Case	rey
	Main	Re	ference		Claim Details		Documents	5	how All
CLAIM SI	JBFOLDER DE	TAILS				[Created	by insurer]		
Insured:	LION CIT	Y RENTALS PTE	LTD, Co. Reg.	No.: 201504	621K				
Main Claimant:		AB SERVICES PT							
Vehicle Re	g. SHC539	9G			Date of Loss:	31/07/2019	9 17:00 - :59		
No.: Claim Type	: TP / M1	905851			Policy/Cover Note No.:	MK000573 (Third Party Only) Coverage: 25/06/2019 - 24/02/2020			
Vehicle Re No.	SLK2068	s			Policy No. (Claimant):	VFX/P1680520			
(Insured):					Excess:	S\$1,600.00			
Repairer:	Trans Ca	b Auto Services	Pte Ltd - Amk ((HQ) No 2 A	ng Mo Kio St 63,	569111 Ang	Mo Kio - Tel:	2000	
Handling Insurer:	Tokio Ma	rine Insurance S	Singapore Ltd (HQ) - Tel: 6	221 6111 [Ha	ndled by Nu	rulhaida Binte M	Nohd Seain]	
Claimant's Insurer:	AXAINS	rance Pte Ltd (F	HQ) - Tel: 6338	7288	Policial and have been	VENNETH V	one: [Final	Rpt due 16/08	/20191
Adjuster:	LKK Auto	Consultants Pt	e Ltd (HQ) - Tel	: 6256-3561	[Handled by I	KENNEINK		Rpt due 16/08	
ASSOCIA	TED MAIL R	ECEIVED					V	/iew All Compose	Case Mail
There are	no mail for thi	s case.							
ALL ASS	OCIATED TA	sks ⁼				View All	Search Tasks	Create New Task	Complete
Due Da	ite Priority		Group Sub	oject Ha	ndler Assign	ned By	Completed On	Created On	Done

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Monday, 5 August 2019 10:46 AM

To:

'motorclaims'; SUR

Subject:

DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE

LTD, DOA: 31/7/2019, SHC 5399G (TP VEHICLE), SLK 2068S (OI VEHICLE)

Attachments:

EST.pdf; GIA.pdf; POLICE REPORT.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHC 5399G at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 2/8/2019

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From:

Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent:

Monday, 5 August 2019 4:06 PM

To:

Veron Chen (LKKAuto)

Cc:

'Jasmine Tan'; 'calvin.er'; SUR

Subject:

FW: SHC 5399G-DOA: 31/7/2019 -- AAD1908-009

Attachments:

EST.pdf

WITHOUT PREJUDICE

Dear Veron

Amount confirmed \$ 2,550 (before GST).

Thank You Best Regards, Ng Wai Yin Finance Department TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764 Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Monday, 5 August, 2019 10:50 AM

To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; calvin.er@transcab.com.sg

Cc: jasminetan@transcab.com.sg; SUR <sur@lkkauto.com>

Subject: SHC 5399G-DOA: 31/7/2019

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Lump Sum \$2550 @ 2 working days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Monday, 5 August 2019 10:50 AM

To:

Ng Wai Yin; 'calvin.er@transcab.com.sg'

Cc:

jasminetan@transcab.com.sg; SUR

Subject:

SHC 5399G-DOA: 31/7/2019

Attachments:

EST.pdf

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Lump Sum \$2550 @ 2 working days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle Vehicle Owner Particulars Company Owner ID Type: 878K Owner ID: Vehicle Details SHC5399G Vehicle No.: Yes Vehicle to be Exported: 01 Aug 2019 Intended Deregistration Date: RENAULT Vehicle Make: LATITUDE 2.0L DCI AUTO D/AB 4DR Vehicle Model: Primary Colour: 2014 Manufacturing Year: M9R8839C001828 Engine No.: VF1ABL15AUC279417 Chassis No.: 127.0 kW (170 bhp) Maximum Power Output: \$19,998.00 Open Market Value: 04 Nov 2014 Original Registration Date: 04 Nov 2014 First Registration Date: Transfer Count: 0 \$12,498.00 Actual ARF Paid: Intended PARF Rebate Details Yes PARF Eligibility: PARF Eligibility Expiry Date: 03 Nov 2022 \$9,373.00 PARF Rebate Amount: Intended COE Rebate Details 03 Nov 2022 COE Expiry Date: A - Car up to 1600cc & 97kW (130bhp) COE Category: 8 COE Period(Years): \$51,337.00 POP Paid: \$20.891.00 COE Rebate Amount: Total Rebate Amount: \$30,264.00 Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 01 Aug 2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 By the lodgement of this report to the insurers, you hereby consaforesaid. 	ent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	01/08/2019 13:16
Date Of Accident	31/07/2019 17:30
Exact Location Of Accident	AYE .
Country/State of Loss	SINGAPORE
D	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHC5399G
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY

Vehicle Category

TAXI

Insurance Company

Name of Insurance Company

AXA INSURANCE PTE LTD

Type Of Coverage

THIRD PARTY

Fleet Policy

YES

Policy Number

VFX/P1680520

Cover Note Number

Driver

CHEN VOON SIN Name of Driver

NRIC No S7021970J 04/07/1970 Date Of Birth Occupation OUTDOOR Date Of Driving Pass 17/04/1998

21 YEARS AND 3 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-93624718 Mobile Number

Fax Number

Contact Number

EMail Address NOEMAIL

BLK 662B JURONG WEST STREET 64 Address

#02-316

642662 Postcode

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OTHER - HIRER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

4

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

YES NO

Number of Passengers (Including Driver)

4

Passenger 1

NAME:

: UNKNOWN

GENDER:

: MALE

Passenger 2

NAME:

: UNKNOWN

GENDER:

: MALE

Passenger 3

NAME:

: UNKNOWN

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

Police Station Name

If Yes Please state which Police Station

BISHAN NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-5529999 - FAX NO: 65561905

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT: T/20190801/2073

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FILE TOO BIG

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLK2068S

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

PRIVATE CAR NAH BOON SIANG

S8031828F

DETAILS OF INJURED PERSON 1

Name

CHEN VOON SIN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHC5399G

Were seat belts worn?

YES

Was this injured conveyed to hospital by

ambulance?

NO

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2 Pg. 1

ETCH PLAN		**************************************
+		
N.A.		53996
HAYE	1 7.8	B= SLX 20685
	────────────────────────────────────	1 20685
111111111111111111111111111111111111111		G- 3L-
		4 4
	49	f 7
	pis See ottach	adia Report
	25060	
	1	
		1
21		50 C C C C C C C C C C C C C C C C C C C
		All Market State Control of the Cont
CLADATION		
ECLARATION		
We declare the foregoing pa	rticulars are true in every respect.	
	4	Graly
	/\	Charle
licyholder's Signature	Driver's Signature	Reporting Centre Personnel's Signature
ste & Time:	(If driver is not the policyholder)	Name:
	Date P Times.	NIDIC/EIN NIA

GIARMC SketchPlanForm_V3

POLICE REPORT Pg. 1





Police Station Of Origin: Bishan N.P.C 20 Bishan Street 23 SINGAPORE 579757 Tel No: 1800-5529999 . 1 of 3 Report No. T/20190801/2073

REPORT	F A TRAFFIC	CACCIDENT				
Date/Time Report Made: 01/08/2019 12:21			Vide Report No.:	Station Diary No.		
Informa	nt's Partici	ulars	CHICAN ENGLISHED			
Name of Informant: CHEN VOON SIN			Address: APT BLK 662B JURONG WEST STREET 64 #02-316 SINGAPORE 642662			
ID Type / ID No.: NRIC NO / S7021970J			Contact No.: Home/Office: Mobile: 93624718			
National SINGAF	ity: ORE CITIZ	EN	Email:			
Sex: Male	Age:	Date of Birth: 04/07/1970	Type of Informant: Driver			
Race: Chinese			Language:	Institution / School Name:		
Occupation: Taxi driver			Driving Licence Information: Class: 2B,2A,3 Date of Expiry:			

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 31/07/2019 17:30	Type of Location:	
		Road 2		B	
		Road Surface: Dry	F	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	100	Traffic Volume: Heavy	
Type of Collis Between Mov	sion: ring Vehicles - Head	i To Rear	8	Anyone conveyed by ambulance:	

Vehicle No	Type	Make	Model	Color Till	Condition	No of Passenge
SHC5399G	TAXI	RENAULT	LATITUDE 2.0L DCI AUTO D/AB 4DR	Red		3
SLK2068S	Car	HONDA	VEZEL 1.5X HYBRID A	Silver		2

POLICE REPORT Pg. 1



T/20190801/2073

Police Station Of Origin: Bishan N.P.C 20 Bishan Street 23 SINGAPORE 579757 Tel No: 1800-5529999

2 of 3 Report No. T/20190801/2073

CONTINUATION OF REPORT

Any Pedestrian In		1	Use of Ped	estrian	Cross	ing: NA
No. of Pedestrian		CLOS SACRE	Jacob City Co	SHE STORY	STATE OF	
Driver 2000	CHEN VOON SIN	DISTRIBUTE STREET	2500 sym (FF) - (5-12)	ID No.		S7021970J
Related Vehicle	SHC5399G (TAXI)			Contact No.		93624718
Hospital/Clinic	SIN MIN CLINIC			Class Driving Licence Expiry	g æ&	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	01/08/2019		Date Disch			3/2019
No. of Days gran	ted Medical Leave 07		Degree of	Injury	NIL	
Driver 1	I demot a succession	All ages	THE ROLL	10 00000000000000000000000000000000000	3500	200010005
Name	NAH BOON SIANG			ID No		S8031828F
Related Vehicle	SLK2068S (Car)			Conta	ct No.	NIL
Hospital/Clinic	NIL			Class Drivin Licent Expiry	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	-	Date Disc	harge	NIL	
No of Days gran	ted Medical Leave NI	IL	Degree of	Injury	NIL	

On 31/7/2019 at about 1732hrs, I was travelling on my taxi bearing registration number: SHC 5399G together with three (3) passenger along AYE towards Clemenceau Avenue exit. I saw a vehicle Honda Vezel my right lane. I was in the exit lane when suddenly the said vehicle made an abrupt lane change and cut into my lane.

I wish to state that the driver did not signal. I did pressed on my brake however I could not stop in time and as such, hit on the rear of the vehicle. Due to the impact, the vehicle then hit onto the water barrier on chevron marking. My vehicle sustained scratches on the front right bonnet. I suffered whiplash to the neck. I have an in car camera in my vehicle which records down the incident.

I seek medical treatment and was given seven (7) days of medical leave.

POLICE REPORT Pg. 1





Police Station Of Origin: Bishan N.P.C 20 Bishan Street 23 SINGAPORE 579757 Tel No: 1800-5529999 3 of 3 Report No. T/20190801/2073

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

3ISHAN NPC

3 BISHAN STREET 23

3 APORE 579757

61. 1960-5529999

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: E / Sr Staff Sgt NORHIDAHYAH BINTE AHMAD	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 01/08/2019 12:21
Officer In Charge Of Case:	Classification Of Case:
Sgt 3 KOH CHEE SENG SEVIN MGAPORE Contact No.: 65472073	SN 061
Authentication Stamp NP158 STATU	RE .

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5399G

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer:

Date of Registration:

SHC 5399G

VF1ABL15AUC279417

Not Askansel 11 By 82550L

RENAULT

LATITUDE

31.7.19

TOKIO MARINE

4/11/2014

	PART	LIST
1	BUMPER COVER FRT	\$ Buc / Mg cm 1,259.42
1	BUMPER SPOILER FRT	\$ رم 181.75 x
1	BUMPER ABSORBER FRT	\$ √L 394.68 X
1	BUMPER RETAINER FRT RH	\$ n:1151.41 -
1	BUMPER SUPPORT FRT	\$ 123.88 X
1	BUMPER UNDERTRAY FRT	\$ 5 472.83 X
1	BUMPER GRILLE LOWER FRT	\$ 266.80 ⊀
1	BUMPER FOG LAMP GRILLE RH	\$ √ 207.21 X
1	BUMPER BEAM FRT	\$ 914.08 🗸
1	HEADLAMP RH	\$ auf 1,184.43 -
1	HEADLAMP PANEL FRT RH	\$ N 152.15
1	FENDER PANEL FRT RH	\$ 783.83
1	WHEELARCH FRT RH	\$ ⁵ 4 278.84
1	FENDER BRACKET LOWER RH	\$ 15.79
1	FENDER INSULATOR RH	\$ ∫- 130.84
1	TOW COVER FRT	\$ ر 28.61
1	FRONT BRACE PANEL	\$ N 177.22
1	RADIATOR GRILLE	\$ $f = 1,707.78 $ χ
1	RADIATOR GRILLE BADGE 'RENAULT'	\$ 225.36
1	RADIATOR GRILLE FRAME	\$ آم 1,353.75
1	FRAME FULL SUPPORT PANEL	\$ Su 615.90
1	FRAME FULL SUPPORT BRACKET	\$ N 89.79
1	BONNET	\$ √ 1,941.63
1	BONNET INSULATOR	\$ /s 405.73
1	BONNET STRUT LH	\$ Sa 88.61
1	BONNET STRUT RH	\$ FL 88.61
1	BONNET HINGE LH	\$ n 348.31
1	BONNET HINGE RH	\$ N 348.31
1	BONNET LOCK	\$ n 305.48)

0.2 AUG 2019

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5399G

1	BONNET CABLE		\$ PL 119.19
1	BONNET CABLE COVER		\$ رِي 161.03
1	BONNET SEAL OUTER		\$ الم 92.36
1	BONNET SEAL INNER		\$ امر 157.28
1	DOOR PANEL FRT RH		\$ M 2,844.66
1	DOOR MIRROR ASSY RH		\$ ام 1,483.40
1	ROCKER PANEL INNER GARNISH RH		\$ fu 466.51
1	ROCKER PANEL INNER RH		\$ N & 1,024.79
1	ROCKER PANEL OUTER RH		\$ * 1,184.99 \ \
1	ROCKER PANEL CENTER RH		\$ n 990.25
1	LOWER ARM RH L70Y		\$ 685.76
1	KNUCKLE ARM RH L70Y		\$ Sh 846.98
1	ABSORBER FRT RH L70Y		\$ رم 360.54
1	DRIVESHAFT RH		\$ 1,747.45
1	STABILIZER BAR FRT		\$ رم 604.65
1	WIPER RESERVOIR MOTOR		\$ SL 270.06
1	WIPER RESERVOIR		\$ Sh 348.25
1	WIPER RESERVOIR NECK		\$ المر 136.11
1	DOOR HARNESS WIRE RH		\$ Ju 2,670.00
1880		TOTAL	\$ 30,437.28
		10%	\$ 3,043.73
		-	\$ 27,393.55
	Special Nett		
1	FRONT DOOR STICKER 'Trans-cab'		\$ nn 80.00 x
1	FRONT DOOR STICKER 'Classic'		\$ 2~ 80.00 X
1	BUMPER CLIP FRT		\$ na 66.00
1	BUMPER BRACKET CLIP FRT RH		\$ nn 12.00)
1	BUMPER SUPPORT CLIP FRT RH		\$ 10.50
1	BUMPER GRILLE LOWER CLIP		\$ ~~ 69.00 \
1SET	FRAME FULL SUPPORT PANEL CLIP		\$ 70.00
2	FRAME FULL SUPPORT PANEL NUT		\$ 20.00
2	FRAME FULL SUPPORT PANEL STUD		\$ ~~ 30.00 /^
1	WHEELARCH CLIP FRT RH		\$ 30.50
1	FRONT RIGHT TYRE		\$ Sh 300.00
1	FRONT RIGHT TYRE RIM		\$ S≤ 380.00
1SET	Front licence plate with holder		\$ Sh 80.00
1SET	RADIATOR GRILLE SCREW		\$ S- 16.00)

Halls	cab Auto Scivices i te Eta		
No. 2 Ar	ng Mo Kio Street 63 Singapore 569111		
Tel No. :	: 6287 6666 Fax No. : 6257 1330		
CO./GST	Reg. No. 201019626G		
SHC 539	99G		
1SET	RADIATOR GRILLE FRAME CLIP	\$	~~ 52.00 \
1	WINDSCREEN SEALANT	\$	NA 253.80
1	FRONT WINDSCREEN MOULDING	\$	na 120.00
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	ا 100.00
6	BONNET INSULATOR CLIP L70Y	\$	~~ 7.30 }X
2	BONNET STRUT L70Y	\$	AL 88.61
2	BONNET CABLE CLIP L70Y	\$	n 6.31
2	BONNET CABLE COVER SCREW L70Y	\$	10.85
_	TOTAL	\$	1,882.88
	TOTAL PARTS	\$	29,276.43
	LABOUR		
		ď	6,000.00 440
	Putty and spray painting of the affected portion.	\$	0,000.00 7 46/
	Panel beating, knocking and straightening the		
	necessary portion, remove and renewal of parts, adjust		
	and realign the same	\$	6,000.00 304
	To rust-proofing of the affected areas.	\$	An 170.00 X
	To transfer of front windscreen fittings and conduct		
	water seepage test.	\$	^~ 170.00 X
	To transfer of front fender fittings, attachment and		
	perform water seepage test.	\$	n ≈ 380.00 ×
	To check steering geometry and computer wheel		A/2 222.22 /
	alignment	\$	220.00 X
	To dismantle and refit front end suspension,		
	undercarriage parts, final checking and testing.	\$	~
	To transfer of front bumper fittings, attachment and		231
	perform water seepage test.	\$	~~ 380.00 X
	To remove and refit interior fittings, trimings, garnish,		
	fittings and other, to enable repair.	\$	ma 380.00 X

AAD1908-009

Trans-cab Auto Services Pte Ltd

Trans-cab Auto Services Pte Ltd

AAD1908-009

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330 CO./GST Reg. No. 201019626G

SHC 5399G

LUMP SUM (REPAIR DAY)	20 DAYS		
Over All Total	\$ 45,	216.43	
TOTAL	\$ 15,	940.00	-0
To apply paint protection system (PPS) maintain and enhancement	\$ nn	380.00	y
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$ n	380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of bonnet fittings, attachment and perform water seepage test.	\$ n	380.00	у
To transfer of tire, rim and on wheel balancing.	\$ n	170.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$ M	380.00	X

- . Supplementary item(s) must be resurveyed and

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/TMI19013619/KVF3N2

Date:

07/08/2019

REFERENCE

Handling Insurer:

Tokio Marine Insurance Singapore Ltd

Policy No:

MK000573

Claimant

Vehicle No:

SHC5399G

Insured Vehicle No:

SLK2068S

Date of Loss:

31/07/2019

Nature of Claim:

TP

Claim No: M1905851

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHC5399G

Make & Model:

RENAULT LATITUDE, 2.0 L (A) 04/11/2014 (Man. Year: 2014)

Engine No: Chassis No: M9R8839C001828 VF1ABL15AUC279417

Reg. Date: Colour:

Metallic White/Red

Odometer:

494971 km

Engine Capacity:

Market Value/New Car

N/A

1995 cc

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

215/60R16 Giti 7 mm

Rear Tyre Size: Rear Left Side: Rear Right Side: 215/60R16 Giti 7 mm Giti 7 mm

Front Right Side: Giti 7 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,276.43	2,401.73	26,874.70	91.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,940.00	760.00	15,180.00	95.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,216.43	3,161.73	42,054.70	93.01
Approved Total (Overridden) (S\$)		2,550.00		5-04,965-6
(S\$)	45,216.43	2,550.00	42,666.43	94.36
+ GST 7.00/7.00% (S\$)	3,165.15	178.50	2,986.65	94.36
Nett Amount (S\$)	48,381.58	2,728.50	45,653.08	94.36

INSPECTION

Date of Assignment:

05/08/2019

Date Inspected:

02/08/2019 Inspected At:

Trans Cab Auto Services Pte Ltd - Amk

(HQ)

No 2 Ang Mo Kio St 63 Singapore 569111

Estimated Period of Repair:

2.0 days

Manager: VERON CHEN Adjuster: KENNETH KONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

Adjuster Report Page 2 of 5

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference Version: 1.0 (Last Synchronised: 06 Aug 2019) Part Source: MRM-SG

RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0) 143 Parts:

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SHC5399G)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

507		nended Parts Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER FRT	Buckled/Mtg Cracked	1,259.42 FL	*1,259.42 FL
2	1	*BUMPER SPOILER FRT	Serviceable	181.75 FL	*-FL
3	1	*BUMPER ABSORBER FRT	Serviceable	394.68 FL	
4	1	*BUMPER RETAINER FRT RH	Distorted	151.41 FL	*151.41 FL
5	1	*BUMPER SUPPORT FRT	Serviceable	123.88 FL	
6	1	*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	
7	1	*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	
8	1	*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	
9	1	*BUMPER BEAM FRT	Repair	914.08 FL	
10	1	*HEADLAMP RH	Cut		*1,184.43 FL
11	1	*HEADLAMP PANEL FRT RH	Repair	152.15 FL	
12	1	*FENDER PANEL FRT RH	Repair	783.83 FL	
13	1	*WHEELARCH FRT RH	Serviceable	278.84 FL	
14	1	*FENDER BRACKET LOWER RH	Serviceable	15.79 FL	
15	1	*FENDER INSULATOR RH	Serviceable	130.84 FL	
16	1	*TOW COVER FRT	Serviceable	28.61 FL	
17	1	*FRONT BRACE PANEL	Repair	177.22 FL	
18	1	*RADIATOR GRILLE	Serviceable	1,707.78 FL	
19	1	*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	
20	1	*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	
21	1	*FRAME FULL SUPPORT PANEL	Serviceable	615.90 FL	
22	1	*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	
23	1	*BONNET	Repair	1,941.63 FL	
24	1	*BONNET INSULATOR	Serviceable	405.73 FL	
25	1	*BONNET STRUT LH	Serviceable	88.61 FL	
26	1	*BONNET STRUT RH	Serviceable	88.61 FL	
27	1	*BONNET HINGE LH	Repair	348.31 FL 348.31 FL	
28	1	*BONNET HINGE RH	Repair	305.48 FL	
29	1	*BONNET LOCK	Repair Serviceable	119.19 FL	
30	1	*BONNET CABLE	Serviceable	161.03 FL	
31	1	*BONNET CABLE COVER	Serviceable	92.36 FL	
32	1	*BONNET SEAL OUTER	Serviceable	157.28 FL	
33	1	*BONNET SEAL INNER	Repair	2,844.66 FL	
34	1	*DOOR PANEL FRT RH *DOOR MIRROR ASSY RH	Serviceable	1,483.40 FL	
35	1	*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	
36	1	*ROCKER PANEL INNER RH	Repair	1,024.79 FL	
37	1	*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	
38	1	William Control to the Control of th	Repair	990.25 FL	
39	1	*ROCKER PANEL CENTER RH *LOWER ARM RH L70Y	Serviceable	685.76 FL	
40	1		Serviceable	846.98 FL	
41 42	1	*KNUCKLE ARM RH L70Y *ABSORBER FRT RH L70Y	Serviceable	360.54 FL	
	4	*DRIVESHAFT RH	Repair	1,747.45 FL	0.77900
43 44	1	*STABILIZER BAR FRT	Serviceable	604.65 FL	1000000
77	-1	OTABILIEEN DAN FRI	00.11000010	00110011	

	Qty	Part No. Particulars	Condition	Repairer's	Amount
15	1	*WIPER RESERVOIR MOTOR	Serviceable	270.06 FL	*-FL
	1		Serviceable	348.25 FL	*-FL
-	1		Serviceable	136.11 FL	*-FL
	1		Serviceable	2,670.00 FL	*-FL
	1	*FRONT DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*-FS
0.00	1		Not Necessary	80.00 FS	*-FS
	1	*BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
	1	*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*-FS
	1	*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*-FS
54	1	*BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*-FS
55	1	*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*-FS
	2	*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*-FS
	2	*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*-FS
58	1	*WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	*-FS
59	1	*FRONT RIGHT TYRE	Serviceable	300.00 FS	*-FS
60	1	*FRONT RIGHT TYRE RIM	Serviceable	380.00 FS	*-FS
	1	*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*-FS
62	1	*SET RADIATOR GRILLE SCREW	Serviceable	16.00 FS	*- FS
	1	*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	*-FS
	1	*WINDSCREEN SEALANT	Not Necessary	253.80 FS	*-FS
65	1	*FRONT WINDSCREEN MOULDING	Not Necessary	120.00 FS	*-FS
66	1	*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
67	6	*BONNET INSULATOR CLIP L70Y	Not Necessary	7.30 FS	*- FS
68	2	*BONNET STRUT L70Y	Not Necessary	88.61 FS	*-FS
69	2	*BONNET CABLE CLIP L70Y	Not Necessary	6.31 FS	*-FS
70	2	*BONNET CABLE COVER SCREW L70Y	Not Necessary	10.85 FS	*- FS
F=Fran	nchise	part. S=SpcNett. L=ListItemDisc.			
			Sub Total (S\$)	32,320.16	2,661.26
		- List Item Discount on L Ite		3,043.73	259.53
			Total Parts (S\$)	29,276.43	2,401.73

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Docomi	mended	l abour
Recomi	nenueu	Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	440.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	6,000.00	300.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
5	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING	New	380.00	0.00
8	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
9	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
10	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
11	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
12	TO TRANSFER OF BONNET FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
13	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
14	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
15	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
	Gross Labou	Cost (S\$)	15,940.00	760.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.